

145

NASA CR-54101



FACILITY FORM 602

N64-31715

(ACCESSION NUMBER)

270

(PAGES)

CR-54101

(NASA CR OR TMX OR AD NUMBER)

(THRU)

(CODE)

(CATEGORY)

## VOLUME 3

# BRUSHLESS ROTATING ELECTRICAL GENERATORS FOR SPACE AUXILIARY POWER SYSTEMS

by

J. N. Ellis and F. A. Collins

prepared for

NATIONAL AERONAUTICS AND SPACE ADMINISTRATION

CONTRACT NO. NAS 3-2783

OTS PRICE

XEROX

\$

6.00 KS

MICROFILM

\$

1.25 mf.



LEAR SIEGLER, INC.

POWER EQUIPMENT DIVISION

CLEVELAND 1, OHIO

CASE FILE COPY

#### NOTICE

This report was prepared as an account of Government sponsored work. Neither the United States, nor the National Aeronautics and Space Administration (NASA), nor any person acting on behalf of NASA:

- A.) Makes any warranty or representation, expressed or implied, with respect to the accuracy, completeness, or usefulness of the information contained in this report, or that the use of any information, apparatus, method, or process disclosed in this report may not infringe privately owned rights; or
- B.) Assumes any liabilities with respect to the use of, or for damages resulting from the use of any information, apparatus, method or process disclosed in this report.

As used above, "person acting on behalf of NASA" includes any employee or contractor of NASA, or employee of such contractor, to the extent that such employee or contractor of NASA, or employee of such contractor prepares, disseminates, or provides access to, any information pursuant to his employment or contract with NASA, or his employment with such contractor.

Requests for copies of this report  
should be referred to:

National Aeronautics and Space Administration  
Office of Scientific and Technical Information  
Washington 25, D.C.  
Attention: AFSS-A

THIRD QUARTERLY  
REPORT

July 15, 1964

BRUSHLESS ROTATING ELECTRICAL GENERATORS  
FOR SPACE AUXILIARY POWER SYSTEMS

Contract No. NAS 3-2783

prepared for

NATIONAL AERONAUTICS AND SPACE ADMINISTRATION

by

J. N. Ellis and F. A. Collins

Technical Management  
Howard A. Shumaker  
NASA Lewis Research Center  
Space Power System Division  
Solar and Chemical Power Branch

LEAR SIEGLER, INC.  
Power Equipment Division  
Cleveland, Ohio

## TABLE OF CONTENTS

Summary . . . . .	1
Introduction . . . . .	2
Work Being Accomplished . . . . .	3
Contents of Next Report . . . . .	5
Design Manual for Two-Coil, Inside-Coil Lundell or Bekey-Robinson Generator . . . . .	Section A
Design Manual for Two-Coil, Outside-Coil Lundell Generator . . . . .	Section B
Design Manual for Single-Coil, Outside-Coil Lundell Generator . . . . .	Section C
Design Manual for Rotating-Coil Lundell (Automotive Type) . . . . .	Section D
Design Manual for Inside-Coil, Stationary-Coil Lundell . . . . .	Section E
Design Manual for Permanent- Magnet AC Generators . . . . .	Section F
Design Manual for Homopolar Inductor AC Generators . . . . .	Section G
Design Manual for Disk-Type or Axial Air-Gap Lundell Generator . . . . .	Section H
Synchronous AC Generator Equivalent Circuits . . . . .	Section I



1

## SUMMARY

8/17/5

In this quarterly report, design manuals and Fortran computer programs are presented for the following AC generators:

1. Two-Coil, Inside-Coil Lundell or Becky-Robinson Generator
2. Two-Coil, Outside-Coil Lundell
3. Single-Coil, Outside Coil Lundell
4. Rotating-Coil Lundell (Automotive Type)
5. Inside-Coil, Stationary-Coil Lundell.

Design manuals without computer programs are presented for:

6. Permanent-Magnet AC Generators
7. Homopolar Inductor AC Generators
8. Disk-Type or Axial Air-Gap Lundell Generator

An equivalent circuit representation of synchronous AC generators is published with a discussion of its development.

*Auth*

### THE NEXT REPORT

The next report is the final report, to be issued in October, and it will consist of two parts. The first part is generator selection criteria and the second part is the electrical design section.

In the first section, the selection criteria, comparison data will be published. Such data will be weight and physical size comparison, evaluations of rotor dynamics, suitability of the various types of generator rotors for use with gas or liquid bearings. Thermal equivalent circuits are to be published in the selection section also.

The second section of the final report will contain the generator design manuals with the Fortran computer programs and the synchronous generator equivalent circuits.

An appendix will be published containing the small studies, discussions and derivations that support the rest of the study.

For each generator design manual, a general approach to the start of a generator design will be provided. It will be similar to that provided for permanent magnet generators in this third quarterly report. Beyond this general approach, the user must select the various design parameters himself. The user of these programs should have some familiarity with AC machine design.

In this, the third quarterly report, Fortran computer programs and design manuals are published for the following AC generators:

1. Two-Coil, Inside-Coil Lundell or Becky-Robinson Generator
2. Two-Coil, Outside-Coil Lundell Generator
3. Single-Coil, Outside-Coil Lundell Generator
4. Rotating-Coil Lundell (Automotive-Type) Generator
5. Inside-Coil, Stationary-Coil, Lundell Generator

Design manuals without computer programs are published for:

6. Permanent-Magnet AC Generators
7. Homopolar Inductor AC Generators
8. Axial Air-Gap Lundell Generators

The last three design manuals are to be programmed in Fortran for the final report. And, in addition, a program for Induction generators will be included if time on this contract permits.

Because of the general and widely understood use of the term Lundell, all of the generators discussed in this study that have claw-type or interlocking, finger-type poles are called Lundell generators. To most engineers, the name Lundell describes the rotor pole arrangement. In this report, there is no other basis for the use of the name.

### NOTE ON WINDAGE CALCULATIONS

In each design manual there is a statement to the effect that there is no known satisfactory method of calculating windage. That, of course, is open to challenge and probably should read "we know of no . . . . .". The formula given is crude and is only intended for use in standard air.

For gases or fluids other than standard air, the fluid density and viscosity must be considered. The formula given in the manual can be modified by the factors

$$\left(\frac{\rho}{.0765}\right)^{.8} \left(\frac{\mu}{.0435}\right)^{.2}$$

where

$\rho$  = density - Lbs FT<sup>-3</sup>

$\mu$  = viscosity LBS FT<sup>-1</sup> HR<sup>-1</sup>

.0765 = density std. air


.0435 = viscosity Std air

The above relationship can be arrived at by referring to Shepherd "Principles of Turbomachinery", Macmillan Pub. Company. See page 152. The friction factor for turbulent flow is a function of  $\frac{1}{(R_e)^{.2}}$  and the loss is a function of  $\frac{\rho}{(R_e)^{.2}}$  times a constant for a fixed velocity and fixed dimensions. The correction for a gas other than standard air, since  $R_e = \frac{DV\rho}{\mu}$ , would be

$$\frac{\rho}{\rho_{air}} \cdot \left(\frac{\rho_{air}}{\rho}\right)^{.2} \cdot \left(\frac{\mu}{\mu_{air}}\right)^{.2} \quad \text{or} \quad \left(\frac{\rho}{.0765}\right)^{.8} \left(\frac{\mu}{.0435}\right)^{.2}$$

A person unfamiliar with electrical machine design would benefit from a synthesis program that selected the design parameters for the design program inputs, but the time available on this contract does not allow its development.

## HOMOPOLAR-INDUCTOR AC GENERATORS




# G

## HOMOPOLAR INDUCTOR, AC GENERATOR

Before 1900 in the young age of electrical power engineering, many different generator designs were proposed and patented. One of those old designs, widely used since its conception, is described in U.S. Patent No. 499446 issued to William Stanley, Jr. and John F. Kelly in 1893.


The same configuration is now made by every company building homopolar inductor AC generators.

The AC generator known as the homopolar inductor is confused in the literature with a DC generator that is also called a homopolar inductor. The DC generator is called both a unipolar generator and an acyclic generator to distinguish it from the AC machine. A paper given by B. G. Lamme, AIEE Transactions 1912, PP 1811-1835, describes the development problems of a 2000 KW acyclic (DC) generator. The acyclic generators are of interest for generating the high direct currents needed for pumping liquid metals but are not discussed in this study.



HOMOPOLAR INDUCTOR GENERATOR





### SMALL HOMOPOLAR INDUCTOR GENERATOR

The homopolar inductor, AC generator uses two identical wound stators and two identical rotor sections to produce AC electrical power.

The magnetic flux from the rotor poles passing through each stator section and linking the output windings, is unidirectional and pulsating. Since the magnetic flux never changes direction in a stator and the poles of a rotor section are of one polarity, the generator has been called a homopolar generator (or alike-pole generator).

(No Model.)

W. STANLY, Jr. & J. F. KELLY.  
ALTERNATING CURRENT GENERATOR.

No. 499,446.

Patented June 13, 1893.

Fig. 2





Fig. 1



Witnesses:  
Raphael Vetter  
John C. Galloway

Inventors  
William Stanley, Jr.  
by John F. Kelly  
Bureau & Page  
Attorneys

The usual homopolar inductor consists of two identical stators wound with a common winding, a double rotor having all north poles on one end and all south poles on the other end, and a field coil enclosed in the magnetic path formed by the outer shell or yoke, the stators, and the rotor.


When the field coil is excited and the rotor is rotating, unidirectional fields of flux cut the windings of each stator in such a manner that approximately the same voltage is generated in the two stator combined as would be generated in one stator by a single rotor having both the north and south poles of the two ends of the homopolar inductor rotor. In other words, two stators and two rotor ends are electrically and magnetically accomplishing what one stator and its corresponding rotor would do in a conventional salient-pole, synchronous, wound-field generator.


The homopolar inductor alternator has been known and used for approximately seventy (70) years. During this time it has been used mainly in industrial applications where size and weight were of little consequence. One of its uses has been to supply high frequency electrical power for induction heating of steel products.

Homopolar inductor designs used in industrial applications have poles, or rotor teeth as they are often called, protruding far out of the shaft so that only a very small amount of unwanted flux passes from the shaft to the stator between the poles of a single polarity (on one end of the stator.)


Recently, the homopolar inductor is being used in airborne and space applications where size and weight are of primary importance. In these applications the area of the shaft between the two groups of poles of opposite polarities directly limits the maximum output of the machine. In these minimum weight designs, the shaft is the largest diameter practicable and the poles or rotor teeth do not protrude far from the shaft. The unwanted flux passing from the shaft to the stator in the region between poles of like polarity is significant. It is of the order of several percent in a practical, useable design. This unwanted flux generates a voltage opposite to the output voltage in the output windings and reduces the output of the machine.

VIEW OF A 4-POLE HOMOPOLAR INDUCTOR





View showing a conventional four-pole, homopolar inductor rotor with approximately the proportions that might be used for maximum output



View of the rotor shown at the top of the page after removal of excess metal to improve the output of the generator

Advantages of the homopolar inductor generator for use in space power systems are:

1. It is simple in design and inherently reliable.
2. The homopolar rotor has high strength and can be used for high rotational speeds if bearing problems permit.
3. At lower speeds the rotors can be laminated to remove the output limits imposed by pole-face losses.

Disadvantages of the machine for the same applications are:

1. It is a heavy machine -- the heaviest of all of the AC generators if compared at the same rpm.
2. Stator protection problems are compounded by the two stators when used in a hostile environment.
3. The solid pole faces limit the output unless the poles are treated to reduce the pole-face losses.
4. The long, double rotor is sometimes not as stiff as desirable for high-speed applications where fluid or gas bearings are used.

### NOTICE

The design procedure given here has not been checked yet. For the final report a design calculation will be compared against test data and the errors in procedure, etc., will be corrected.

The numbers and general arrangement for a computer program are used and the program will be in the final report.





## HOMOPOLAR INDUCTOR A-C GENERATOR

\_\_\_\_\_ KVA \_\_\_\_\_ % PF \_\_\_\_\_ Volts \_\_\_\_\_ Amps. \_\_\_\_\_ Ph. \_\_\_\_\_ Cycles \_\_\_\_\_ RPM


\_\_\_\_\_ Date \_\_\_\_\_

STATOR	
PUNCHING I. D.	_____
PUNCHING O. D.	_____
CORE LENGTH	_____
DBS x 2	_____
SLOTS	_____
SIZE SLOTS	_____
CARTER COEFF.	_____
TYPE WDG.	_____
THROW	_____
SKEW & DIST. FACT.	_____
CHORD FACT	_____
COND. PER SLOT	_____
TOTAL EFF. COND.	_____
COND. SIZE	_____
COND. AREA	_____
CURRENT DENSIT Y	_____
WDG. CONST.	_____ C1 _____
TOTAL FLUX	_____
GAP AREA	_____
GAP DENSITY	_____
POLE CONST.	_____
FLUX PER POLE	_____
TOOTH PITCH	_____
TOOTH DENSITY	_____
CORE DENSITY	_____
GRADE OF IRON	_____
½ MEAN TURN	_____
RES. PER PH. •	_____ 0 _____
EDDY FACT. TOP	_____
EDDY FACT. BOT.	_____
DEMAG. FACT. Cm	_____ Cq _____
AMP. COND. PER IN.	_____
REACT. FACTOR	_____
COND. PERM.	_____
END PERM.	_____
LEAKAGE REACT.	_____
AIR GAP PERM.	_____
REACT. OF ARM Xad	_____ Xaq _____
WT. OF COPPER	_____
WT. OF IRON	_____



Field turns _____			
COND. SIZE	_____	_____	_____
COND. AREA	_____	_____	_____
MEAN TURN	_____	_____	_____
RES. •	0	_____	_____
% LOAD	_____	_____	_____
AMPS.	_____	_____	_____
VOLTS	_____	_____	_____
AMPS /IN 2	_____	_____	_____
FIELD LEAK. REACT.	_____	_____	_____
FIELD SELF INDUCT.	_____	_____	_____
DAMP. LEAK. Xd	_____	_____	Xdq _____

ROTOR	
SINGLE GAP _____	Ge _____
ROTOR DIAMETER _____	
PERIPHERAL SPEED _____	
POLE PITCH _____	$\alpha$ _____
POLE AREA _____	
POLE DENSITY _____	
GRADE OF IRON _____	




REACT-TIME CONST.	
SYNCH. $X_d$ _____	$X_q$ _____
UNSAT TRANS. _____	
SAT. TRANS. _____	
SUBTRANS. $X_d'$ _____	$X_q'$ _____
NEG. SEQUENCE _____	
ZERO SEQUENCE _____	
OPEN CIRC. TIME CON. _____	
ARM TIME CON. _____	
TRANS. TIME CON. _____	
SUBTRANS. TIME CON. _____	


#### LOSSES-EFFICIENCY

% LOAD			
F & W			
STA. TEETH			
STA. CORE			
POLE FACE			
DAMPER			
STA. $I^2R$			
EDDY			
ROT. $I^2R$			
$\Sigma$ LOSSES			
RATING			
RTG+LOSS			
% LOSS			
% EFF			


(a) Open Slots



(b) Constant Slot Width



(c) Constant Tooth Width



(d) Round Slots




FIG 1



VALUES OF  $K_{dn}$  FOR INTEGRAL-SLOT, 30 WINDINGS - TABLE 2

$n$	$K_{dn}$ - HARMONIC DISTRIBUTION FACTORS									
$q =$	2	3	4	5	6	7	8	9	10	$\infty$
1	.966	.960	.958	.957	.957	.957	.956	.955	.955	.955
3	.707	.667	.654	.646	.644	.642	.641	.640	.639	.636
5	.259	.217	.205	.200	.197	.195	.194	.194	.193	.191
7	-.259	-.177	-.158	-.149	-.145	-.143	-.141	-.140	-.140	-.136
9	-.707	-.333	-.270	-.247	-.236	-.229	-.225	-.222	-.220	-.212
11	-.966	-.177	-.126	-.110	-.102	-.097	-.095	-.093	-.092	-.087
13	-.966	.217	.126	.102	.092	.086	.083	.081	.079	.073
15	-.707	.667	.270	.200	.172	.158	.150	.145	.141	.127
17	-.259	.960	.158	.102	.084	.075	.070	.066	.064	.056
19	.259	.960	-.205	-.110	-.084	-.072	-.066	-.062	-.060	-.059
21	.707	.667	-.654	-.247	-.172	-.143	-.127	-.118	-.112	-.091
23	.966	.217	-.958	-.149	-.092	-.072	-.063	-.057	-.054	-.041
25	.966	-.177	-.958	.200	.102	.075	.063	.056	.052	.038
27	.707	-.333	-.654	.646	.236	.158	.127	.111	.101	.071
29	.259	-.177	-.205	.957	.145	.086	.066	.056	.050	.033
31	-.259	.217	.158	.957	-.197	-.097	-.070	-.057	-.050	-.031



33	-.709	.667	.270	.646	-.644	-.229	-.150	-.118	-.101	-.058
35	-.966	.960	.126	.200	-.957	-.143	-.083	-.062	-.052	-.027
37	-.966	.960	-.126	-.149	-.957	.195	.095	.066	.054	.026
39	-.707	.667	-.270	-.247	-.644	.642	.225	.145	.112	.099
41	-.259	.217	-.158	-.110	-.197	.957	.141	.081	-.060	.023
43	.259	-.177	.205	.102	.145	.957	-.194	-.093	-.064	-.022
45	.707	-.333	.654	.200	.236	.642	-.641	-.222	-.141	-.042
47	.966	-.177	.958	.102	.102	.195	-.956	-.140	-.079	-.020
49	.966	.217	.958	-.110	-.092	-.143	-.956	.194	.092	.019
51	.707	.667	.654	-.247	-.172	-.229	-.641	.640	.220	.038
53	.259	.960	.205	-.149	-.084	-.097	-.194	.955	.140	.018
55	-.259	.960	-.158	.200	.084	.086	.141	.955	-.193	-.017
57	-.707	.667	-.270	.646	.172	.158	.225	.640	-.639	-.033
59	-.966	.217	-.126	.957	.092	.075	.095	.194	-.955	-.016
61	-.966	-.177	.126	.957	-.102	-.072	-.083	-.140	-.955	.016
63	-.707	-.333	.270	.646	-.236	-.143	-.150	-.222	-.639	.030
65	-.259	-.177	.158	.200	-.145	-.072	-.070	-.093	-.193	.015

# ROUND COPPER WIRE

## TABLE 3

SIZE AWG	BARE DIAMETER	AREA □"	ℓ/1000' @25°C	SINGLE FORMVAR	HEAVY FORMVAR	SINGLE GLASS FORMVAR	BARE WT. #/1000'	SINGLE GLASS SILICONE	DOUBLE GLASS SILICONE
36	.0050	.0000196	424	.0056	.0060		.0757		
35	.0056	.0000246	338	.0062	.0066		.0949		
34	.0063	.0000312	266	.0070	.0074		.1201		
33	.0071	.0000396	210	.0079	.0084		.1526		
32	.0080	.0000503	165	.0088	.0094	.0121	.1937		
31	.0089	.0000622	134	.0097	.0104	.0130	.2398		
30	.0100	.0000785	106	.0108	.0116	.0142	.3025	.0132	.0152
29	.0113	.000100	83.1	.0122	.0130	.0156	.3866	.0145	.0165
28	.0126	.000125	66.4	.0135	.0144	.0169	.4806	.0158	.0178
27	.0142	.000158	52.6	.0152	.0161	.0186	.6101	.0174	.0194
26	.0159	.000199	41.7	.0169	.0179	.0203	.7650	.0191	.0211
25	.0179	.000252	33.0	.0190	.0200	.0224	.970	.0211	.0231
24	.0201	.000317	26.2	.0213	.0223	.0263	1.223	.0251	.0276
23	.0226	.000401	20.7	.0238	.0249	.0289	1.546	.0276	.0301
22	.0254	.000507	16.4	.0266	.0277	.0317	1.937	.0303	.0328
21	.0285	.000638	13.0	.0299	.0310	.0349	2.459	.0335	.0360
20	.0320	.000804	10.3	.0334	.0346	.0384	3.099	.0370	.0395
19	.0360	.00102	8.14	.0374	.0386	.0424	3.900	.0409	.0434
18	.0403	.00126	6.59	.0418	.0431	.0468	4.914	.0453	.0478
17	.0453	.00159	5.22	.0469	.0482	.0519	6.213	.0503	.0528
16	.0508	.00204	4.07	.0524	.0538	.0575	7.812	.0558	.0583
15	.0571	.00255	3.26	.0588	.0602	.0639	9.87	.0621	.0646
14	.0641	.00322	2.58	.0659	.0673	.0710	12.44	.0691	.0716
13	.072	.00407	2.04	.0738	.0753	.0789	15.69	.0770	.0795
12	.0808	.00515	1.61	.0827	.0842	.0877	19.76	.0858	.0883
11	.0907	.00650	1.28	.0927	.0942	.0977	24.90	.0957	.0982
10	.102	.00817	1.02	.1039	.1055	.1089	31.43	.1069	.1094
9	.114	.0102	.814	.1165	.1181	.1225	39.62	.1204	.1254
8	.129	.0131	.634	.1306	.1323	.1366	49.98	.1345	.1395
7	.144	.0163	.510	.1465	.1482	.1525	63.03	.1503	.1553
6	.162	.0206	.403	.1643	.1661	.1703	79.44	.1680	.1730
5	.182	.0260	.319	.1842	.1861	.1902	100.2	.1879	.1929
4	.204	.0327	.254				126.3	.2103	.2153
3	.229	.0412	.202				159.3		
2	.258	.0523	.159				200.9		
0	.325	.0830	.100						
2/0	.365	.105	.0791						
4/0	.460	.166	.0500						

CURVE 1




## CURVE 2

From Kennard and Spooner "Surface Iron Losses with Respect to Laminated Materials", Trans. AIEE, Vol. 43, 1924, pp 262-281.

REFER TO ITEM (150) IN SALIENT POLE DESIGN MANUAL FOR SAMPLE USE OF THIS CURVE


DRAWN BY  
J.A.T.






## CURVE-3

FROM E.J. POLLARDS "LOAD LOSSES IN SALIENT POLE  
SYNCHRONOUS MACHINES" A IEE TRANS. VOL. 54  
1935 PP 1332-1340




CURVE 4



CURVE 5

PERCENT COIL EMBRACE

 $C_K$  - SLOT FACTOR FOR APPROXIMATE REACTANCE FORMULA

PERCENT COIL EMBRACE

## NO-LOAD DAMPER LOSS

CURVE 7

$$D.L. = \frac{1.224 P \tau_b b_p P}{10^6 a_b} \left[ \left( \tau_b B_g K_p K_g \right)^2 \left( \frac{K_f (K_{W1})}{(2\lambda_s + \frac{\lambda_g}{K_{\phi 1}})} \right)^2 + \frac{K_{f2} (K_{W2})}{(2\lambda_s + \frac{\lambda_g}{K_{\phi 2}})} \right]^2$$

= LOSS IN KW


$$\lambda_s = \frac{\eta_r}{b_r} + \lambda_e + \lambda_c$$


$$\lambda_g = \frac{\tau_b}{K_g g} = \frac{\tau_b}{g'}$$

 $a_b$  = BAR AREA IN SQ IN. $\tau_b$  = BARS/POLE $P$  = NO. POLES $b$  = LENGTH BAR IN. $K_g$  = CARTER'S COEFFICIENT (TOTAL) $K_p = f_n(b_s/g)$ , CURVE (a) ( $b_s = b_o$  for partially closed slots) $K_f$  AND  $K_{f2} = f_n(\tau_b/\rho)$  CURVE (b) $\rho$  = DAMPER BAR RESISTIVITY (MICROHMS PER CU. IN.) $K_{W1}$  AND  $K_{W2} = f_n(b_s/\tau_s)$ , CURVE (C1) AND (C2) $K_{\phi 1}$  AND  $K_{\phi 2} = f_n(\tau_b/\tau_s)$ , CURVE (d1) AND (d2) $\lambda_c = f_n(b_r/g K_g)$  CURVE (e) $B_g$  IS IN KILOLINES PER SQ INCH


$$\lambda_c = \frac{.75}{K_f} \text{ (FOR ROUND OR SQ. BARS)}$$

$$\lambda_c = \frac{\eta_b}{3b_b K_{f1}} \text{ (FOR RECT. BARS)}$$

 $b_s/g$  (open slots) &  $b_o/g$  (partially closed slots)





CURVE 9




$C_m$   
&  
 $C_q$











CURVE 15

AVERAGE MAGNETIZATION CURVE  
FOR 2-V PERMENDUR BAR STOCK

AMPERE TURNS PER SQUARE INCH

1000

500


100


50

10


5

1





CURVE 17



KE  
 SEMI-LOGARITHMIC  
 KEUFFEL & ESSER CO. MADE IN U.S.A.  
 3 CYCLES X 70 DIVISIONS  
 359-71

*Homopolar Inductor*  
SALIENT-POLE WOUND-POLE SYMBOLS

<u>Calculation Location</u>	<u>Symbol</u>	<u>Explanation</u>
(78)	A	Ampere conductors per inch of stator periphery
(46)	$a_c$	Strand area (stator)
(89)	$a_{cf}$	Field conductor area
(85)	$a_p$	Pole area
(20)	B	Density
(128)	$B_c$	Core density
(125)	$B_g$	Gap density
(140)	$B_p$	Pole density no load
(163)	$B_{p1}$	Pole density full load
(127)	$B_T$	Tooth density
(89)	$b_{bo}$	Width of slot opening (damper)
(89)	$b_{b1}$	Width of rectangular slot (damper)
(76)	$b_h$	Pole head width
(22)	$b_o$	Width of slot opening (stator)
(76)	$b_p$	Pole body width
(22)	$b_s$	Stator slot dimension per Fig. 1
(15)	$b_v$	Width of duct
(22)	$b_1$	Stator slot dimensions per Fig. 1
(22)	$b_2$	
(22)	$b_3$	

<u>Calculation Location</u>	<u>Symbol</u>	<u>Explanation</u>
(74)	$C_m$	Demagnetizing factor
(73)	$C_p$	Average/maximum field form
(75)	$C_q$	Cross magnetization factor
(72)	$C_w$	Winding constant
(71)	$C_1$	Ratio max. to fund.
(32)	$c$	Parallel circuits
(12)	$D$	Stator outside diameter
(11)	$d$	Stator inside diameter
(35)	$d_b$	Diameter of bender pin
(11a)	$d_r$	Rotor outside diameter
(3)	$E$	Line volts
(145)	$E_F$	Field volts no load
(168)	$E_{FFL}$	Field volts full load
(4)	$E_{PH}$	Phase volts
(55)	$E_{F_{top}}$	Eddy factor top
(56)	$E_{F_{bot}}$	Eddy factor bottom
(130)	$F_c$	Stator core ampere turns
(131)	$F_g$	Air gap ampere turns
(165)	$F_{FL}$	Total ampere turns full load
(142)	$F_{NL}$	Total ampere turns no load
(141)	$F_p$	Pole ampere turns at no load
(164)	$F_{PL}$	Pole ampere turns at full load
(136)	$F_{sc}$	Short circuit ampere turns

Calculation Location	Symbol	Explanation
(129)	$F_t$	Stator tooth ampere turns
(147)	F&W	Friction and windage
(5a)	f	Frequency
(69)	$g_e$	Effective air gap
(59a)	$g_{\max}$	Maximum air gap
(22)	$h_o$	Stator slot dimension
(22)	$h_1$	
(22)	$h_2$	
(22)	$h_3$	
(22)	$h_s$	
(22)	$h_t$	
(22)	$h_w$	
(89)	$h_{bo}$	Height of slot opening
(89)	$h_{b1}$	Rectangular bar thickness
(24)	$h_c$	Depth below slot
(76)	$h_p$	Pole Height
(37)	$h_{st}$	Uninsulated strand height
(38)	$h'_{st}$	Distance between center line of strand
(8)	$I_{PH}$	Phase current
(166)	$I_{FFL}$	Field amperes at full load

Calculation Location	Symbol	Explanation
(143)	$I_{FNL}$	Field amperes at no load
(146)	$I^2 R_F$	Field loss
(158)	$I^2 R_S$	Stator copper loss
(9a)	$K_c$	Adjustment factor
(43)	$K_d$	Distribution factor
(18)	$K_i$	Stacking factor
(44)	$K_p$	Pitch factor
(67)	$K_s$	Carter coefficient
(42)	$K_{SK}$	Skew factor
(2)	KVA	Machine rating
(151)	$K_1$	Pole face loss factor
(19)	k	Watts per lb.
(48)	$L_E$	End extension one turn
(113)	$L_F$	Field self inductance
(13)	$\ell$	Gross core length
(93)	$\ell_b$	Damper bar length
(136)	$\ell_{e2}$	Coil extension straight portion
(76)	$\ell_n$	Pole head length
(76)	$\ell_p$	Pole body length
(17)	$\ell_s$	Solid core length
(49)	$\ell_t$	1/2 mean turn
(100)	$\ell_{tr}$	Mean length of field turns
(5)	m	Number of phases



<u>Calculation Location</u>	<u>Symbol</u>	<u>Explanation</u>
(34)	$N_{st}$	Strands per conductor
(92)	$n_b$	Number of damper bars
(45)	$n_e$	Effective conductors
(99)	$n_p$	Number of field turns
(30)	$n_s$	Conductor per slot
(14)	$n_v$	Number of ducts
(9)	P. F.	Power factor
(6)	$p$	Number of poles
(23)	$Q$	Number of slots
(53)	$R_{ph} \text{ (cold)}$	Stator resistance at 20°C
(54)	$R_{ph} \text{ (hot)}$	Stator resistance at X°C
(107)	$R_F \text{ (cold)}$	Field resistance at 20°C
(108)	$R_f \text{ (hot)}$	Field resistance at X°C
(137)	SCR	Short circuit ratio
(47)	$s_s$	Stator current density
(144)	$s_f$	Field current density
(133)	$T_a$	Armature time constant
(134)	$T_d'$	Transient time constant
(135)	$T_d''$	Subtransient time constant
(132)	$T_{do}'$	Open circuit time constant
(149)	$W_c$	Stator core loss
(172)	$W_{DFL}$	Damper loss at full load

Calculation Location	Symbol	Explanation
(157)	$W_{DNL}$	Damper loss at no load
(171)	$W_{PFL}$	Pole face losses at full load
(150)	$W_{PNL}$	Pole face loss at no load
(170)	$W_{TFL}$	Stator tooth loss at full load
(148)	$W_{TNL}$	Stator tooth loss at no load
(98a)	$V_r$	Peripheral speed of rotor
(79)	$X$	Reactance factor
(81)	$X_{ad}$	Reactance direct axis
(82)	$X_{aq}$	Reactance quadrature axis
(83)	$X_d$	Synchronous reactance direct axis
(119)	$X_d'$	Stator transient reactance
(120)	$X_d''$	Subtransient reactance direct axis
(115)	$X_{Dd}$	Leakage reactance direct axis
(117)	$X_{Dq}$	Leakage reactance quadrature axis
(118)	$X_{du}'$	Unsaturated transient reactance
(112)	$X_f$	Field leakage reactance
(80)	$X_\ell$	Leakage
(84)	$X_q$	Synchronous reactance quadrature axis
(121)	$X_q''$	Subtransient reactance quadrature axis
(123)	$X_0$	Zero sequence reactance
(122)	$X_2$	Negative sequence reactance
(96)	$X_D^{\circ C}$	Expected damper bar $^{\circ}C$

Calculation Location	Symbol	Explanation
(103)	$X_F^{\circ C}$	Expected field temp. in $^{\circ}C$
(50)	$X_S^{\circ C}$	Expected temp. stator in $^{\circ}C$
(95)	$\rho_D$	Resistivity of damper bar at $20^{\circ}C$
(51)	$\rho_S$	Resistivity of stator cond at $20^{\circ}C$
(104)	$\rho_F$	Resistivity of field conductor
(138)	$\phi_l$	Leakage flux at no load
(160)	$\phi_{ll}$	Leakage flux at full load
(126)	$\phi_P$	Flux per pole
(139)	$\phi_{PT}$	Total flux per pole at no load
(162)	$\phi_{PTL}$	Total flux per pole at full load
(124)	$\phi_T$	Total flux
(94)	$\tau_b$	Damper bar pitch
(41)	$\tau_p$	Pole pitch
(26)	$\tau_s$	Slot pitch
(27)	$\tau_{s\ 1/3}$	Slot pitch 1/3 distance from narrowest point
(40)	$\tau_{sk}$	Stator slot skew
(70)	$\lambda_a$	Air gap permeance
(63)	$\lambda_E$	End permeance
(86)	$\lambda_{el}$	Pole end leakage permeance
(62)	$\lambda_i$	Stator conductor permeance
(88)	$\lambda_{sl}$	Pole side leakage permeance
(87)	$\lambda_{tl}$	Pole tip leakage permeance

(1)	--	<u>DESIGN NUMBER</u> - To be used for filing purposes
(2)	KVA	<u>GENERATOR KVA</u>
(3)	E	<u>LINE VOLTS</u>
(4)	E <sub>PH</sub>	<p><u>PHASE VOLTS</u> - For 3 phase, <sup>Y</sup> connected generator</p> $E_{PH} = \frac{(\text{Line Volts})}{\sqrt{3} \Delta} = \frac{(3)}{\sqrt{3}}$ <p>For 3 phase, <del>Y</del> connected generator</p> $E_{PH} = (\text{Line Volts}) = (3)$
(5)	m	<u>PHASES</u> - Number of
(5a)	f	<u>FREQUENCY</u> - In cycles per second
(6)	P	<u>POLES</u> - Number of
(7)	RPM	<u>SPEED</u> - In revolutions per minute
(8)	I <sub>PH</sub>	<u>PHASE CURRENT</u> - In amperes at rated load
(9)	P.F.	<u>POWER FACTOR</u> - Given in per unit
(9a)	K <sub>c</sub>	<p><u>ADJUSTMENT FACTOR</u> - When P.F. = 0. to .95 set K<sub>c</sub> = 1. ;</p> <p>when P.F. = .95 to 1. set K<sub>c</sub> = 1.05</p>
(10)	--	<p><u>LOAD POINTS</u> - The computer program is set up to have the</p> <p>0.%, 100%, 150%, 200% load points as standard out-puts. There is an additional space available on the output sheet for one optional load point. This optional</p>

load point will be the designer's choice and can be selected anywhere in the range of 0 to 200% load. When an optional load calculation is required, insert the per unit load value on the input sheet. The optional load point will be calculated in addition to the standard points listed above. For example, insert .33 on the input sheet when the optional load calculation for 33% load is required in addition to the standard points.

If only the standard points are required, insert 0.0 on the input sheet and the optional load column will be blank.

- |       |        |  |
|-------|--------|--|
| (11)  | d      | <u>STATOR PUNCHING I.D.</u> - The inside diameter of the stator punching in inches.  |
| (11a) | $d_r$  | <u>ROTOR O.D.</u> - The outside diameter of the rotor in inches.   |
| (12)  | D      | <u>PUNCHING O.D.</u> - The outside diameter of the stator punching in inches.  |
| (13)  | $\ell$ | <u>GROSS STATOR CORE LENGTH</u> - In inches.   |
| (14)  | $n_v$  | <u>RADIAL DUCTS</u> - Number of.   |
| (15)  | $b_v$  | <u>RADIAL DUCT WIDTH</u> - In inches.  |
| (16)  | $K_i$  | <u>STACKING FACTOR</u> - This factor allows for the coating (core plating) on the punchings, the burrs due to slotting, and the deviations in flatness. Approximate values of $K_i$ are given in Table IV. |

THICKNESS OF LAMINATIONS (INCHES)	GAGE	$K_i$
.014	29	0.92
.018	26	0.93
.025	24	0.95
.028	23	0.97
.063	--	0.98
.125	--	0.99

TABLE IV

- (17)  $\ell_s$  SOLID CORE LENGTH - The solid length is the gross length times the stacking factor. If ventilating ducts are used, their length must be subtracted from the gross length also.


$$\ell_s = (K_i) \times (\ell - (n_v)(b_v)) = (16) (13) - (14) (15)$$

- (18) MATERIAL - This input is used in selecting the proper magnetization curves for stator, yoke, pole, and shaft; when different materials are used. Separate spaces are provided on the input sheet for each section mentioned above. Where curves are available on card decks, use the proper identifying code. Where card decks are not available submit data in the following manner:

The magnetization curve must be available on semi-log paper. Typical curves are shown in this manual on Curves 15 and 16. Draw straight line segments through the curve starting with zero density. Record the coordinates of the points where the

straight line segments intersect. Submit these coordinates as input data for the magnetization curve. The maximum density point must be submitted first.

Refer to Figure below for complete sample



- (19) k WATTS/LB - Core loss per lb of stator lamination material.  
Must be given at the density specified in (20).
- (20) B DENSITY - This value must correspond to the density used  
in Item (19) to pick the watts/lb. The density that  
is usually used is 77.4 kilolines/in<sup>2</sup>.

- (21) 1 TYPE OF STATOR SLOT - Refer to Figure 1, Page  
 2 for type of slot.  
 3 For (a) slot use 1. as an input  
 4 For (b) slot use 2. as an input  
 5 For (c) slot use 3. as an input  
 For (d) slot use 4. as an input  
 Type 5. is not a slot but instead a particular situation for an open slot where the winding has only one conductor per slot.
- (22)  $b_0$  ALL SLOT DIMENSIONS - Given in inches per Figure 1,  
 $b_1$  Page . Where the dimension does not apply  
 $b_2$  to the slot being used, insert 0. on input sheet.  
 $b_3$   
 $b_s = \frac{b_1 + b_3}{2} = \frac{(22) + (22)}{2}$   
 $b_s$   
 $h_0$   
 $h_1$   
 $h_2$   
 $h_3$   
 $h_s$   
 $h_t$   
 $h_w$
- (23)  $Q$  STATOR SLOTS - Number of
- (24)  $h_c$  DEPTH BELOW SLOTS - The depth of the stator core below the slots.



Due to mechanical strength reasons,  $h_c$  should never be less than 70% of  $h_s$ .

$$h_c = \frac{(D) - [(d) + 2(h_s)]}{2} = \frac{(12) - [(11) + 2(22)]}{2}$$

(25) q

SLOTS PER POLE PER PHASE

$$q = \frac{(Q)}{(P)(m)} = \frac{(23)}{(6)(5)}$$

(26)  $\tau_s$

STATOR SLOT PITCH

$$\tau_s = \frac{\pi(d)}{Q} = \frac{\pi(11)}{(23)}$$

(27)  $\tau_{s1/3}$

STATOR SLOT PITCH - 1/3 distance up from narrowest section. For slot (a), (b), (c), and (e)

$$\tau_{s1/3} = \frac{\pi[(d) + .66(h_s)]}{(Q)} = \frac{\pi[(11) + .66(22)]}{(23)}$$

For slot (d)

$$\frac{\pi[(d) + 2(h_0) + 1.32(b_s)]}{(Q)} =$$

$$\frac{\pi[(11) + 2(22) + 1.32(22)]}{(23)}$$

(28) --


TYPE OF WINDING - Record whether the connection is "wye" of "delta". For "wye" conn use 1. for input. For "delta" use 0. for input.

(29) --

TYPE OF COIL - Record whether random wound or formed coils are used. For random wound coils use 0. for input. For formed coils use 1. for input.

- |       |                 |   |
|-------|-----------------|---|
| (30)  | n <sub>S</sub>  | <p><u>CONDUCTORS PER SLOT</u> - The actual number of conductors per slot. For random wound coils use a space factor of 75% to 80%. Where space factor is the percent of the total slot area that is available for insulated conductors after all other insulation areas have been subtracted out.</p> |
| (31)  | Y               | <p><u>THROW</u> - Number of slots spanned. For example, with a coil side in slot 1 and the other coil side in slot 10, the throw is 9.</p>  |
| (31a) |                 | <p><u>PER UNIT OF POLE PITCH SPANNED</u> - Ratio of the number of slots spanned to the number of slots in a pole pitch. This value must be between 1.0 and 0.5 to satisfy the limits of this program.</p> $= \frac{(Y)}{(m)(q)} = \frac{(31)}{(5)(25)}$   |
| (32)  | C               | <p><u>PARALLEL PATHS</u>, No. of - Number of parallel circuits per phase.</p>   |
| (33)  | --              | <p><u>STRAND DIA. OR WIDTH</u> - In inches. For round wire, use strand diameter. For rectangular wire, use strand width. This must be the largest of the two dimensions given for a rectangular wire.</p>   |
| (34)  | N <sub>ST</sub> | <p><u>NUMBER OF STRANDS PER CONDUCTOR IN DEPTH</u> - Applies to rectangular wire. In order to have a more flexible conductor and reduce eddy current loss, a stranded conductor is often used. For</p>  |

example, when the space available for one conductor is .250 width x .250 depth, the actual conductor can be made up of 2 or 3 strands in depth as shown



For a more detailed explanation refer to section titled "Effective Resistance and Eddy Factor" in the Derivations in Appendix.

- (34a)  $N'_{ST}$  NUMBER OF STRANDS PER CONDUCTOR - This number applies to the strands in depth and/or width and is used in calculating the conductor area. Item (34) is different in that it deals with strands in depth only and is used in calculating eddy factors.
- (35)  $d_b$  DIAMETER OF BENDER PIN - in inches - This pin is used in forming coils. Use .25 inch for stator O.D. < 8 inches use .50 inches for stator O.D. > 8 inches.
- (36)  $\ell_{e2}$  COIL EXTENSION BEYOND CORE in Inches - Straight portion of coil that extends beyond stator core.
- (37)  $h_{ST}$  HEIGHT OF UNINSULATED STRAND in Inches - This value is the vertical height of the strand and is used in eddy factor calculations. Set this value = 0 for round wire.
- (38)  $h'_{ST}$  DISTANCE BETWEEN CENTERLINES OF STRANDS IN DEPTH in inches.

(39) - STATOR COIL STRAND THICKNESS in inches - For rectangular conductors only. For round wire insert 0. on input sheet. This must be the narrowest dimension of the two dimensions given for a rectangular wire.

(40)  $\tau_{SK}$  SKEW - Stator slot skew in inches at stator I.D.

(41)  $\tau_P$  POLE PITCH in inches.

$$\tau_p = \frac{\pi(d)}{(P)} = \frac{\pi(11)}{(6)}$$

(42)  $K_{SK}$  SKEW FACTOR - The skew factor is the ratio of the voltage induced in the coils to the voltage that would be induced if there were no skew.

When  $\tau_{SK} = 0$ ,  $K_{SK} = 1$

$$K_{SK} = \frac{\sin \left[ \frac{\pi(\tau_{SK})}{2(\tau_P)} \right]}{\frac{\pi(\tau_{SK})}{2(\tau_P)}} = \frac{\sin \left[ \frac{\pi(40)}{2(41)} \right]}{\frac{\pi(40)}{2(41)}}$$

(42a) PHASE BELT ANGLE - Input

For phase belt angle =  $60^\circ$  insert 60 on input sheet.

For phase belt angle =  $120^\circ$  insert 120 on input sheet.

(43)  $K_d$  DISTRIBUTION FACTOR - The distribution factor is the ratio of the voltage induced in the coils to the voltage that would be induced if the windings

were concentrated in a single slot. See Table 2 for compilation of distribution factors for the various harmonics.

For  $60^\circ$  phase belt angle and  $q = \text{integer}$  when  $(42a) = 60$  and  $(25) = \text{integer}$ .

$$K_d = \frac{\sin 30^\circ}{(q) \sin [30/(q)]} = \frac{\sin 30^\circ}{(25) \sin [30/(25)]}$$

For  $60^\circ$  phase belt angle and  $(q) \neq \text{integer} = N/B$  reduced to lowest terms.

When  $(43a) = 1$  and  $(25) \neq \text{integer} = N/B$  reduced to lowest terms

$$K_d = \frac{\sin 30^\circ}{(N) \sin [30/(N)]} = \frac{\sin 30^\circ}{(43) \sin [30/(43)]}$$

For  $120^\circ$  phase belt angle and  $(q) = \text{integer}$

When  $(43a) = 120$  and  $(25) = \text{integer}$

$$K_d = \frac{\sin 60^\circ}{2(q) \sin [30/(q)]} = \frac{\sin 60^\circ}{2(25) \sin [30/(25)]}$$

For  $120^\circ$  phase belt angle and  $q \neq \text{integer}$

When  $(43a) = 120$  and  $(25) \neq \text{integer} = N/B$  reduced to lowest terms

$$K_d = \frac{\sin 60^\circ}{2(N) \sin [30/(N)]} = \frac{\sin 60^\circ}{2(43) \sin [30/(43)]}$$

(44)  $K_P$

PITCH FACTOR - The ratio of the voltage induced in the coil to the voltage that would be induced in a full pitched coil. See Table 1 for compilation of the pitch factors for the various harmonics.

$$K_P = \sin \left[ \frac{(Y)}{(m)(q)} \times 90^\circ \right] = \sin \left[ \frac{(31)}{(5)(25)} \times 90^\circ \right]$$

(45)  $n_e$

TOTAL EFFECTIVE CONDUCTORS - The actual number of effective series conductors in the stator winding taking into account the pitch and skew factors but not allowing for the distribution factor.

$$n_e = \frac{(Q)(n_s)(K_P)(K_{SK})}{(C)} = \frac{(23)(30)(44)(42)}{(32)}$$

(46)  $a_c$

CONDUCTOR AREA OF STATOR WINDING in (inches)<sup>2</sup> -

The actual area of the conductor taking into account the corner radius on square and rectangular wire. See the following table for typical values of corner radii

$$\text{If } (39) = 0 \text{ then } a_c = .25\pi(\text{Dia})^2 = .25\pi(33)^2$$

$$\text{If } (39) \neq 0 \text{ then } a_c = (N'_{ST}) \left[ (\text{strand width}) (\text{strand depth}) - (.858 r_c^2) \right] = (34a) \left[ (33) (39) - (.858 r_c^2) \right]$$

where  $.858 r_c^2$  is obtained from Table V below.

(39)	(33) .188	.189 (33) .75	(33) .751
.050	.000124	.000124	.000124
.072	.000210	.000124	.000124
.125	.000210	.00084	.000124
.165	.000840	.00084	.003350
.225	.001890	.00189	.003350
.438	--	.00335	.007540
.688	--	.00754	.01340
--	--	.03020	.03020

TABLE V

(47)  $S_S$  CURRENT DENSITY - Amperes per square inch of stator conductor

$$S_S = \frac{(I_{PH})}{(C)(a_c)} = \frac{(8)}{(32)(46)}$$

(48)  $L_E$  END EXTENSION LENGTH in inches - Can be an input or output.

For  $L_E$  to be output, insert 0. on input sheet.

For  $L_E$  to be input, calculate per following:

When (29) = 0. then:

$$L_E = .5 + \frac{K_T \pi(Y) [(d)+(h_s)]}{Q} = .5 + \frac{\left[ \begin{array}{l} 1.3 \text{ If } (6) = 2 \\ 1.5 \text{ If } (6) = 4 \\ 1.7 \text{ If } (6) = 4 \end{array} \right] \pi(31) [(11)+(22)]}{(23)}$$

When (29) = 1. then:

$$\begin{aligned} L_E &= 2 \ell_{e2} + \pi \left[ \frac{h_1}{2} + \text{dia} \right] + y \left[ \frac{\tau_s^2}{\sqrt{\tau_s^2 - b_s^2}} \right] \\ &= 2 \quad (36) + \pi \left[ \frac{(22)}{2} + (35) \right] + (31) \left[ \frac{(26)^2}{\sqrt{(26)^2 - (22)^2}} \right] \end{aligned}$$

(49)  $\ell_t$  1/2 MEAN TURN - The average length of one conductor in inches.

$$\ell_t = (\ell) + (L_E) = (13) + (44)$$

(50)  $X_S^{\circ C}$  STATOR TEMP  $^{\circ}C$  - Input temp at which F.L. losses will be calculated. No load losses and cold resistance will be calculated at  $20^{\circ}C$ .

(51)  $\rho_s$ 

RESISTIVITY OF STATOR WINDING - In micro ohm-inches @ 20°C. If tables are available using units other than that given above, use Table VI for conversion to ohm-inches.

$\rho$	ohm-cm	ohm-in	ohm-cir mil/ft
1 ohm-cm =	1.000	0.3937	$6.015 \times 10^6$
1 ohm-in =	2.540	1.000	$1.528 \times 10^7$
1 ohm-cir mil/ft =	$1.662 \times 10^{-7}$	$6.545 \times 10^{-8}$	1.000

TABLE VI  
Conversion Factors for Electrical Resistivity

(52)  $\rho_{s(\text{hot})}$ 

RESISTIVITY OF STATOR WINDING - Hot at  $X_s^\circ\text{C}$  in micro ohm-inches

$$\rho_{s(\text{hot})} = (\rho_s) \left[ \frac{(X_s^\circ\text{C}) + 234.5}{254.5} \right] = (51) \left[ \frac{(50) + 234.5}{254.5} \right]$$

(53)  $R_{\text{SPH(cold)}}$ 

STATOR RESISTANCE/PHASE - Cold @ 20°C in ohms

$$R_{\text{SPH(cold)}} = \frac{(\rho_s)(n_s)(Q)(\ell_t)}{(m)(a_c)(C)^2} \times 10^{-6} = \frac{(51)(30)(23)(49)}{(5)(46)(32)^2} \times 10^{-6}$$

(54)  $R_{\text{SPH(hot)}}$ 

STATOR RESISTANCE/PHASE - Calculated @  $X^\circ\text{C}$  in ohms

$$R_{\text{SPH(hot)}} = \frac{(\rho_{s \text{ hot}})(n_s)(Q)(\ell_t)}{(m)(a_c)(C)^2} \times 10^{-6} = \frac{(52)(30)(23)(49)}{(5)(46)(32)^2} \times 10^{-6}$$

(55)  $EF_{(\text{top})}$ 

EDDY FACTOR TOP - The eddy factor of the top coil. Calculate this value at the expected operating temperature of the machine. For round wire

$$EF_{\text{top}} = 1$$



$$\begin{aligned}
 EF_{\text{top}} &= 1 + \left\{ .584 + \left[ \frac{N_{\text{st}}^2 - 1}{16} \right] \left[ \frac{h'_{\text{st}} \ell}{h_{\text{st}} \ell_t} \right]^2 \right\} 3.35 \times 10^{-3} \\
 &\quad \left[ \frac{(h_{\text{st}})(n_s)(f)(a_c)}{(b_s)(\rho_{\text{shot}})} \right]^2 \\
 &= 1 + \left\{ .584 + \left[ \frac{(34)^2 - 1}{16} \right] \left[ \frac{(38)(13)}{(37)(49)} \right]^2 \right\} 3.35 \times 10^{-3} \\
 &\quad \left[ \frac{(37)(30)(5a)(46)}{(22)(52)} \right]^2
 \end{aligned}$$

(56) EF  
(bot)

EDDY FACTOR BOTTOM - The eddy factor of the bottom coil at the expected operating temperature of the machine. For round wire  $EF_{(\text{bot})} = 1$

$$\begin{aligned}
 EF_{(\text{bot})} &= (EF_{(\text{top})}) - 1.677 \left[ \frac{(h_{\text{st}})(n_s)(f)(a_c)}{(b_s)(\rho_{\text{shot}})} \right]^2 \times 10^{-3} \\
 &= (55) - 1.677 \left[ \frac{(37)(30)(5a)(46)}{(22)(52)} \right] 10^{-3}
 \end{aligned}$$

(57)  $b_{\text{tm}}$

STATOR TOOTH WIDTH 1/2 way down tooth in inches -  
For slots type (a), (b), (d) and (e), Figure I

$$b_{\text{tm}} = \frac{\pi[(d) + (h_s)]}{(Q)} - (b_s) = \frac{\pi[(11) + (22)]}{(23)} - (22)$$

(57a)	$b_{t \ 1/3}$	<u>STATOR TOOTH WIDTH 1/3 distance up from narrowest section</u> For slots type (a), (b) and (e) $b_{t \ 1/3} = (\tau_{s \ 1/3}) - (b_s) = (27) - (22)$ For slot type (c) $b_{t \ 1/3} = b_{tm} = (57)$ For slot type (d) $b_{t \ 1/3} = (\tau_{1/3}) - \frac{2\sqrt{2}}{3} (b_s) = (27) - .94 (22)$
(58)	$b_t$	<u>TOOTH WIDTH AT STATOR I. D. in inches -</u> For partially closed slot $b_t = \frac{\pi(d)}{(Q)} - b_0 = \frac{\pi(11)}{(23)} - (22)$ For open slot $b_t = \frac{\pi(d)}{(Q)} - b_s = \frac{\pi(11)}{(23)} - (22)$

(59)	$g_{\min}$	<p><u>MINIMUM AIR GAP</u> in inches - For concentric pole face</p> <p><math>g_{\min} = g_{\max}</math>. For non concentric pole face</p> <p><math>g_{\min}</math> = gap at the center of the pole.</p>
(59a)	$g_{\max}$	<u>MAXIMUM AIR GAP</u> in inches
(60)	$C_X$	<p><u>REDUCTION FACTOR</u> - Used in calculating conductor permeance and is dependent on the pitch and distribution factor. This factor can be obtained from Graph 1 with an assumed <math>K_d</math> of .955 or calculated as shown</p> $C_X = \frac{(K_X)}{(K_P)^2 (K_d)^2} = \frac{(61)}{(44)^2 (43)^2}$
(61)	$K_X$	<p><u>FACTOR TO ACCOUNT FOR DIFFERENCE</u> in phase current in coil sides in same slot</p> $K_X = \frac{1}{4} \left[ \frac{3(Y)}{(m)(q)} + 1 \right] \text{ For 3 phase}$ $= \frac{1}{4} \left[ \frac{3(31)}{(5)(25)} + 1 \right]$ $K_X = \frac{(Y)}{(m)(q)} \text{ For 2 phase}$ $= \frac{(31)}{(5)(25)}$ <p>NOTE: See special case for (e) slot. Refer to calculation (62)</p>
(62)	$\lambda_i$	<p><u>CONDUCTOR PERMEANCE</u> - The specific permeance for the portion of the stator current that is embedded in the iron. This permeance depends upon the configuration of the slot.</p>

(a) For open slots

$$\lambda_i = (C_X) \frac{20}{(m)(q)} \left[ \frac{(h_2)}{(b_s)} + \frac{(h_1)}{3(b_s)} + \frac{(b_t)^2}{16(\tau_s)(g)} + \frac{.35(b_t)}{(\tau_s)} \right]$$

$$\lambda_i = (60) \frac{20}{(5)(25)} \left[ \frac{(22)}{(22)} + \frac{(22)}{3(22)} + \frac{(58)^2}{16(26)(59)} + \frac{.35(58)}{(26)} \right]$$

(b) For partially closed slots with constant slot width

$$\lambda_i = (C_X) \frac{20}{(m)(q)} \left[ \frac{(h_o)}{(b_o)} + \frac{2(h_t)}{(b_o) + (b_s)} + \frac{(h_w)}{(b_s)} + \frac{(h_1)}{3(b_s)} + \frac{(b_t)^2}{16(\tau_s)(g)} + \frac{.35(b_t)}{(\tau_s)} \right]$$

$$\lambda_i = (60) \frac{20}{(5)(25)} \left[ \frac{(22)}{(22)} + \frac{2(22)}{(22) + (22)} + \frac{(22)}{(22)} + \frac{(22)}{3(22)} + \frac{(58)^2}{16(26)(59)} + \frac{.35(58)}{(26)} \right]$$

(d) For round slots

$$\lambda_i = (C_X) \frac{20}{(m)(q)} \left[ .62 + \frac{(h_o)}{(b_o)} \right]$$

$$\lambda_i = (60) \frac{20}{(5)(25)} \left[ .62 + \frac{(22)}{(22)} \right]$$

(e) For open slots with a winding of one conductor per slot

$$\lambda_i = (C_X) \frac{20}{(m)(q)} \left[ \frac{(h_2)}{(b_s)} + \frac{(h_1)}{3(b_s)} + .6 + \frac{(g)}{2(\tau_s)} + \frac{(\tau_s)}{4(g)} \right]$$

$$\lambda_i = (60) \frac{20}{(5)(25)} \left[ \frac{(22)}{(22)} + \frac{(22)}{3(22)} + .6 + \frac{(59)}{2(26)} + \frac{(26)}{4(59)} \right]$$

$$\left( (C_X) = \frac{1}{(K_p^2)(K_d^2)} \right)$$

$$(K_X) = 1$$

(63)  $K_E$ LEAKAGE REACTIVE FACTOR for end turn

$$K_E = \frac{\text{Calculated value } (L_E)}{\text{Value } (L_E) \text{ from Graph 1}} \quad (\text{For machines where } (11) > 8'')$$

where  $L_E = (48)$  and abscissa of Graph 1 =  $(\gamma)(\tau_s) = (31)(26)$

$$K_E = \sqrt{\frac{\text{Calculated value of } (L_E)}{\text{Value } (L_E) \text{ from Graph 1}}} \quad (\text{For machines where } (11) < 8'')$$

(64)  $\lambda_E$ END WINDING PERMEANCE - The specific permeance for the end extension portion of the stator winding

$$\lambda_E = \frac{6.28(K_f)}{(\ell)(K_d)^2} \left[ \frac{\phi_E L_E}{2n} \right] = \frac{6.28(63)}{(13)(43)^2} \left[ \frac{Q_E L_E}{2n} \right]$$

The term  $\left[ \frac{\phi_E L_E}{2n} \right]$  is obtained from Graph 1.

The symbols used in this (term) do not apply to those of this design manual. Reference information for the symbol origin is included on Graph 1.

(65) --

WEIGHT OF COPPER - The weight of stator copper in lbs.

$$\# \text{'s copper} = .321(n_s)(Q)(a_c)(\ell_t) = .321(30)(23)(46)(49)$$

(66) --

WEIGHT OF STATOR IRON - in lbs.

$$\begin{aligned} \# \text{'s iron} = & .566 \left\{ (b_{tm})(Q)(\ell_s)(h_s) + \pi \left[ (D) - (h_c) \right] (h_c)(\ell_s) \right\} \\ & .566 \left\{ (57)(23)(17)(22) + \pi \left[ (12) - (24) \right] (24)(17) \right\} \end{aligned}$$

(67)  $K_s$ CARTER COEFFICIENT

$$K_s = \frac{(\tau_s) \left[ 5(g) + (b_s) \right]}{(\tau_s) \left[ 5(g) + (b_s) \right] - (b_s)^2} \quad (\text{For open slots})$$

$$K_s = \frac{(26) [5(59) + (22)]}{(26) [5(59) + (22)] - (22)^2}$$

$$K_s = \frac{\tau_s [4.44(g) + .75(b_o)]}{\tau_s [4.44(g) + .75(b_o)] - (b_o)^2} \quad (\text{For partially closed slots})$$

$$K_s = \frac{(26) [4.44(59) + .75(22)]}{(26) [4.44(59) + .75(22)] - (22)^2}$$

(68) -- AIR GAP AREA - The area of the gap surface at the stator bore

$$\text{Gap Area} = \pi(d)(\mathcal{L}) = \pi(11)(13)$$

(69)  $g_e$  EFFECTIVE AIR GAP

$$g_e = (K_s)(g) = (67)(59)$$

(70)  $\lambda_a$  AIR GAP PERMEANCE - The specific permeance of the air gap

$$\lambda_a = \frac{6.38(d)}{(P)(g_e)} = \frac{6.38(11)}{(6)(69)}$$

(71)  $C_1$  THE RATIO OF MAXIMUM FUNDAMENTAL of the field form to the actual maximum of the field form - This term can be an input or output. For  $C_1$  to be output insert 0. on input sheet. For  $C_1$  to be input, determine  $C_1$  as follows:

For pole heads with only one radius,  $C_1$  is obtained from curve #4. The abscissa is "pole embrace" ( $\alpha$ ) = (77). The graphical flux plotting method of determining  $C_1$  is explained in the section titled "Derivations" in the Appendix.

(72)  $C_W$ 

WINDING CONSTANT - The ratio of the RMS Line voltage for a full pitched winding to that which would be introduced in all the conductors in series if the density were uniform and equal to the maximum value. This value can be an input or output. For  $C_W$  to be an output, insert 0. on input sheet. For  $C_W$  to be an input, calculate as follows:

$$C_W = \frac{(E)(C_1)(K_d)}{\sqrt{2} (E_{PH})(m)} = \frac{(3)(71)(43)}{\sqrt{2} (4)(5)}$$

Assuming  $K_d = .955$ , then  $C_W = .225 C_1$  for three phase delta machines and  $C_W = .390 C_1$  for three phase star machines.

(73)  $C_P$ 

POLE CONSTANT - The ratio of the average to the maximum value of the field form. This ratio can be an input or output. For  $C_P$  to be an output, insert 0. on input sheet. For  $C_P$  to be an input, determine as follows:  
For pole heads with more than one radius  $C_P$  is calculated from the same field form that was used to determine  $C_1$ , and this method is described in the section titled "Derivations" in the Appendix. For pole heads with only one radius  $C_P$  is obtained from curve #4. Note the correction factor at the top of the curve.

(74)  $C_M$ 

DEMAGNETIZING FACTOR - direct axis - This factor can be an input or output. For  $C_M$  to be an output, insert 0. on input sheet. For  $C_M$  to be an input, determine as follows:

$$C_M = \frac{(\alpha)\pi + \sin[(\alpha)\pi]}{4 \sin[(\alpha)\pi/2]} = \frac{(77)\pi + \sin[(77)\pi]}{4 \sin[(77)\pi/2]}$$

$C_M$  can also be obtained from curve 9.

(75)  $C_q$

CROSS MAGNETIZING FACTOR - quadrature axis - This factor can be an input or output. For  $C_q$  to be an output, insert 0. on input sheet. For  $C_q$  to be an input, determine as follows:

$$C_q = \frac{1/2 \cos[(\alpha)\pi/2] + (\alpha)\pi - \sin[(\alpha)\pi]}{4 \sin[(\alpha)\pi/2]}$$

$$= \frac{1/2 \cos[(77)\pi/2] + (77)\pi - \sin[(77)\pi]}{4 \sin[(77)\pi/2]}$$

VALID FOR  
CONCENTRIC  
POLES.

$C_q$  can also be obtained from curve 9.

(76) --

POLE DIMENSIONS LOCATIONS per Figure 2


Where:

$l_p$  length of pole (one end only)

$b_p$  width of pole

$h_p$  height of pole at center

all dimensions in inches



(77)  $\alpha$

POLE EMBRACE

$$\alpha = \frac{b_p}{\tau_p} = \frac{(76)}{(41)}$$



(78)	A	<p><u>AMPERE CONDUCTORS</u> per inch - The effective ampere conductors per inch of stator periphery. This factor indicates the "specific loading" of the machine. Its value will increase with the rating and size of the machine and also will increase with the number of poles. It will decrease with increases in voltage or frequency. A is generally higher in single phase machines than in polyphase ones.</p> $A = \frac{(I_{PH})(n_s)(K_P)}{(C)(\tau_s)} = \frac{(8)(30)(44)}{(32)(26)}$
(79)	X	<p><u>REACTANCE FACTOR</u> - The reactance factor is the quantity by which the specific permeance must be multiplied to give percent reactance. It is the percent reactance for unit specific permeance, or the percent of normal voltage induced by a fundamental flux per pole per inch numerically equal to the fundamental armature ampere turns at rated current. Specific permeance is defined as the average flux per pole per inch of core length produced by unit ampere turns per pole.</p> $X = \frac{100(A)(K_d)}{\sqrt{2} (C_1)(B_g) \times 10^3} = \frac{100 (78)(43)}{\sqrt{2} (71)(125) \times 10^3}$
(80)	$X_\ell$	<p><u>LEAKAGE REACTANCE</u> - The leakage reactance of the stator for steady state conditions. When (5) = 3, calculate as follows:</p> $X_\ell = 2X[(\lambda_i) + (\lambda_E)] = 2(79)[(62) + (64)]$ <p>In the case of two phase machines a component due to belt leakage must be included in the stator leakage reactance. This component is due to the harmonics</p>

caused by the concentration of the MMF into a small number of phase belts per pole and is negligible for three phase machines. When (5) = 2, calculate as follows:

$$\lambda_B = \frac{0.1(d)}{(P)(g_e)} \left[ \frac{\sin \left[ \frac{3(y)}{(m)(q)} \right] 90^\circ}{(K_p)} \right] = \frac{0.1(11)}{(6)(69)} \left[ \frac{\sin \left[ \frac{3(31)}{(5)(25)} \right] 90^\circ}{(44)} \right]$$

$$X_\ell = 2X[(\lambda_1) + (\lambda_E) + (\lambda_B)] \text{ where } \lambda_B = 0 \text{ for 3 phase machines.}$$

$$X_\ell = 2(79)[(62) + (64) + (80)]$$

- |      |          |  |
|------|----------|--|
| (81) | $X_{ad}$ | <p><u>REACTANCE</u> - direct axis - This is the fictitious reactance due to armature reaction in the direct axis.</p> $X_{ad} = (X)(\lambda_a)(C_1)(C_M) = (79)(70)(71)(74)$ |
| (82) | $X_{aq}$ | <p><u>REACTANCE</u> - quadrature axis - This is the fictitious reactance due to armature reaction in the direct axis.</p> $X_{aq} = (X)(C_q)(\lambda_a) = (79)(75)(70)$      |
| (83) | $X_d$    | <p><u>SYNCHRONOUS REACTANCE</u> - direct axis - The steady state short circuit reactance in the direct axis.</p> $X_d = (X_\ell) + (X_{ad}) = (80) + (81)$                   |
| (84) | $X_q$    | <p><u>SYNCHRONOUS REACTANCE</u> - quadrature axis - The steady state short circuit reactance in the quadrature axis.</p> $X_q = (X_\ell) + (X_{aq}) = (80) + (82)$           |
| (85) | $a_p$    | <p><u>POLE AREA</u> - The effective cross sectional area of the pole.</p> $a_p = (b_p)(\ell_p)(K_1) = (76)(76)(16)$  |

(98a)	$V_r$	<p><u>PERIPHERAL SPEED</u> - The velocity of the rotor surface in feet per minute</p> $V_r = \frac{(d_r)(\text{RPM})}{12} = \frac{(11a)(7)}{12}$
(99)	$N_p$	<u>NUMBER OF FIELD TURNS</u>
(100)	$t_r$	<u>MEAN LENGTH OF FIELD TURN</u>
(101)	--	<u>FIELD CONDUCTOR DIMENSIONS</u>
(103)	$X_f^{\circ}\text{C}$	<p><u>FIELD TEMP IN <math>^{\circ}\text{C}</math></u> - Input temp at which full load field loss is to be calculated.</p>
(104)	$\rho_f$	<p><u>RESISTIVITY</u> of field conductor at <math>20^{\circ}\text{C}</math> in micro ohm-inches. Refer to table given in Item (51) for conversion factors.</p>
(105)	$\rho_f$ (hot)	<p><u>RESISTIVITY</u> of field conductor at <math>X_f^{\circ}\text{C}</math></p> $\rho_{f \text{ (hot)}} = \rho_f \left[ \frac{(X_f^{\circ}\text{D}) - 234.5}{254.5} \right] = (104) \left[ \frac{(103) - 234.5}{254.5} \right]$
(106)	$a_{cf}$	<p><u>CONDUCTOR AREA OF FIELD WDG</u> - Calculate same as stator conductor area (46) except substitute (102) for (39) (101) for (33)</p>

(107)  $R_f$  (cold) COLD FIELD RESISTANCE @ 20°C

$$R_f \text{ (cold)} = \rho_f \frac{(N_f) (\ell_{tf})}{(a_{cf})} = (104) \frac{(99) (100)}{(106)}$$

(108)  $R_f$  (hot) HOT FIELD RESISTANCE - Calculated at  $X_f^{\circ}\text{C}$  (103)

$$R_f \text{ (hot)} = \rho_{f \text{ hot}} \frac{(N_f) (\ell_{tf})}{(a_{cf})} = (105) \frac{(99)(100)}{(106)}$$

(108a) -- WEIGHT OF FIELD COPPER in lbs

$$\begin{aligned} \# \text{'s of copper} &= .321 (N_f) (\ell_{tf}) (a_{cf}) \\ &= .321(99) (100)(106) \end{aligned}$$

(108b) -- WEIGHT OF ROTOR IRON - Because of the large number of different pole shapes, one standard formula cannot be used for calculating rotor iron weight. Therefore, the computer will not calculate rotor iron weight.

(113) FIELD SELF INDUCTANCE

$$L_f = (N_f)^2 \left[ C_p \lambda_a \frac{\pi}{2} \ell_p + P_f \right] \times 10^{-8}$$

(118)  $X'_{du}$  UNSATURATED TRANSIENT REACTANCE

$$X'_{du} = (X_{\ell}) + (X_f) = (80) + (112)$$

$X'_d$	<p><u>SATURATED TRANSIENT REACTANCE</u></p> $X'_d = .88(X'_{du}) = .88(118)$
$X''_d$	<p><u>SUBTRANSIENT REACTANCE</u> in direct axis</p> <p>When no damper bars exist, i.e. when (92) = 0</p> $X''_d = (X'_d) = (119)$
$X''_q$	<p><u>SUBTRANSIENT REACTANCE</u> in quadrature axis</p> <p>When no damper bars exist, i.e. when (92) = 0</p> $X''_q = X_q = (84)$
$X_2$	<p><u>NEGATIVE SEQUENCE REACTANCE</u> - The reactance due to the field which rotates at synchronous speed in a direction opposite to that of the rotor.</p> $X_2 = .5 [X''_d + X''_q] = .5 [(120) + (121)]$
$X_0$	<p><u>ZERO SEQUENCE REACTANCE</u> - The reactance drop across any one phase (star connected) for unit current in each of the phases. The machine must be star connected for otherwise no zero sequence current can flow and the term then has no significance.</p>

(132)	$T'_{do}$	<p><u>OPEN CIRCUIT TIME CONSTANT</u> - The time constant of the field winding with the stator open circuited and with negligible external resistance and inductance in the field circuit. Field resistance at room temperature (<math>20^{\circ}\text{C}</math>) is used in this calculation.</p> $T'_{do} = \frac{L_F}{R_F} = \frac{(113)}{(107)}$
(133)	$T_a$	<p><u>ARMATURE TIME CONSTANT</u> - Time constant of the D.C. component. In this calculation stator resistance at room temperature (<math>20^{\circ}\text{C}</math>) is used.</p> $T_a = \frac{X_2}{200\pi(f)(r_a)} = \frac{(122)}{200\pi(5a)(133)}$ <p>where <math>r_a = \frac{(m)(I_{PH})^2(R_{SPH \text{ cold}})}{\text{Rated KVA}} = \frac{(5)(8)^2(53)}{(2)}</math></p>
(134)	$T'_d$	<p><u>TRANSIENT TIME CONSTANT</u> - The time constant of the transient reactance component of the alternating wave.</p> $T'_d = \frac{(X'_d)}{(X_d)} (T'_{do}) = \frac{(119)}{(83)} (132)$
(135)	$T''_d$	<p><u>SUBTRANSIENT TIME CONSTANT</u> - The time constant of the subtransient component of the alternating wave. This value has been determined empirically from tests on large machines. Use following values.</p> $T''_d = .035 \text{ second at 60 cycle}$ $T''_d = .005 \text{ second at 400 cycle}$
(136)	$F_{SC}$	<p><u>SHORT CIRCUIT AMPERE TURNS</u> - The field ampere turns required to circulate rated stator current when the stator is short circuited.</p> $F_{SC} = (X_d)(F_g) = (83)(131)$

$\phi_T$ TOTAL FLUX IN KILO LINES

$$\phi_T = \frac{6(E)10^6}{(C_W)(n_e)(RPM)} = \frac{6(3)10^6}{(72)(45)(17)}$$

 $B_g$ 

GAP DENSITY in Kilo Lines/in<sup>2</sup> - The maximum flux density in the air gap

$$B_g = \frac{(\phi_T)}{\pi(d)(\ell)} = \frac{(124)}{\pi(11)(13)}$$

 $\phi_P$ FLUX PER POLE in Kilo Lines

$$\phi_P = \frac{(\phi_T)(C_P)}{(P)} = \frac{(124)(73)}{(6)}$$

 $B_t$ 

TOOTH DENSITY in Kilo Lines/in<sup>2</sup> - The flux density in the stator tooth at 1/3 of the distance from the minimum section.

$$B_t = \frac{\phi_T}{(Q)(\ell_s)(b_{t1/3})} = \frac{(124)}{(23)(17)(57a)}$$

 $B_c$ 

CORE DENSITY in Kilo Lines/in<sup>2</sup> - The flux density in the stator core

$$B_c = \frac{(\phi_P)}{A_c}$$



 $A_c$ EFFECTIVE AREA OF THE CORE

$$A_c = \frac{(D - 2 \text{ dbs}) \pi d \ell_s}{p}$$

 $F_g$ 


AIR GAP AMPERE TURNS - The field ampere turns per pole required to force flux across the air gap when operating at no load with rated voltage.

$$F_g = \frac{(B_g)(g_e)}{3.19} = \frac{(125)(69)}{3.19}$$






$P_m$  = Leakage permeance path from rotor to stator between pole lobes, or rotor teeth.



$$P_m = \frac{3.19 (\pi d_r) \ell}{P (h_p + g)}$$


$h_p$  = EFFECTIVE POLE HEIGHT WHEN THE ROTOR IS TAPERED AND ACTUAL HEIGHT WHEN THE ROTOR IS STRAIGHT



FLUX LEVEL BETWEEN LOBES  
AT N.L. IS

$$\frac{g_e (B_g)}{g + h_p}$$


- $P_4$  The permeance of the leakage path from the inner (or inboard) edge of the stator stack, to the center shaft portion of the rotor.



$$P_4 = \frac{P}{2} \left\{ \frac{\pi (d+h_s) \frac{b_{coil}}{2} (3.19) \frac{1}{P}}{h_p + h_s} \right\}$$

$$P_4 = \frac{10 (d+h_s) b_{coil}}{h_p + h_s}$$


$P_5$  = Leakage permeance across the field coil.



$$P_5 = \frac{3.19 \left[ \frac{OD_{coil} - ID_{coil}}{2} \right] \left[ \frac{OD_{coil} + ID_{coil}}{2} \right] \pi \left( \frac{2}{3} \right)}{b_{coil}}$$

$P_6$  = Leakage permeance from stator to stator.

$$P_6 = \frac{3.19 \left[ \frac{ID_{coil} - d}{2} \right] \left[ \frac{ID_{coil} + d}{2} \right] \pi}{b_{coil}}$$



$P_7$  = Leakage permeance from stators to shaft and rotor.

$$P_7 = \frac{\pi \left[ \frac{d + d_{\text{SHAFT}}}{2} \right] \left[ \frac{D - d}{2} \right] \frac{3.14}{2}}{\frac{1}{2} [D - d_{\text{SHAFT}}]}$$

- $\phi_m$  = Flux leaking across the rotor area where there is no pole, no load  
 $\phi'_m$  = Approximation of  $\phi_m$   
 $\phi_{ML}$  =  $\phi_m$  leaking under load conditions  
 $\phi_4$  = Flux leaking from the inboard side of a stator stack to the rotor (shaft center section) at no load  
 $\phi'_4$  = Approximation of  $\phi_4$   
 $\phi_{4L}$  =  $\phi_4$  leaking under load conditions  
 $\phi_5$  = Flux leaking across the field coil itself, no load  
 $\phi'_5$  = Approximation of  $\phi_5$   
 $\phi_{5L}$  =  $\phi_5$  leaking under load conditions  
 $\phi_6$  = Flux leaking between stators, below the field coil and at no load  
 $\phi'_6$  = Approximation of  $\phi_6$   
 $\phi_{6L}$  =  $\phi_6$  leaking under load conditions  
 $\phi_7$  = Flux leaking from stator into rotor end shaft extension.  
 $\phi'_7$  = Approximation of  $\phi_7$   
 $\phi_{7L}$  =  $\phi_7$  leaking under load conditions  
 $\phi_{SH}$  = Flux in shaft at no load  
 $\phi'_{SH}$  = Approximation of  $\phi_{SH}$   
 $\phi_{SHL}$  =  $\phi_{SH}$  under load  
 $\phi_y$  = Flux in the yoke outside the stator stack  
 $\phi_{yc}$  = Flux in the yoke around the field coil when the housing is jogged out to accommodate the field coil.  
 $\phi_y$  =  $\phi_{yc}$  in a straight housing.

## CALCULATING THE PERFORMANCE OF THE HOMOPOLAR INDUCTOR

The procedure recommended for hand calculations is as follows:

- 1.0 Calculate  $\phi_T$ ,  $B_T$ ,  $\phi_p$  and make all of the stator calculations listed on the left hand side of the stator design sheet, page 2.

Use  $C_1$  and  $C_p$  values obtained from curve 4, page 11.

- 1.1 Calculate  $P_m$ ,  $P_4$ ,  $P_5$ ,  $P_6$ ,  $P_7$ .

2.0 No load Calculations

- 2.1 Calculate  $AT_g = \frac{B_g g_e}{3.19}$

- 2.2 Calculate  $\phi_m = P_m AT_g$

- 2.3 Calculate  $AT_g + AT_m = AT_g + \frac{P\phi_m g_e}{3.19 A_g}$

- 2.4 Calculate  $\phi_4 = P_4 [AT_g - AT_m]$

$$\phi_5 = P_5 [2AT_g - 2AT_m]$$

$$\phi_6 = P_6 [2AT_g - 2AT_m]$$

$$\phi_7 = P_7 [AT_g - AT_m]$$

$$2.5 \quad B_{TNL} = \frac{\phi_T + \phi_m P}{A_T}$$

$$2.6 \quad B_c = \frac{\phi_P + \phi_m}{A_{core}}$$

$$2.7 \quad \phi_{shaft} = \frac{P}{2} \phi_P + P \phi_m + \phi_4 + \phi_7$$

$$2.8 \quad B_{shaft} = \frac{\phi_{SH}}{A_{SH}}$$

$$2.9 \quad \phi_y = \phi_{SH} + \phi_6 + \phi_5$$

$$2.10 \quad B_y = \frac{\phi_y}{A_y}$$

$$2.11 \quad F_y = \ell_y \left[ \frac{NI}{in} \text{ at } B_y \right]$$

2.12 The total ampere turns drop in the flux circuit is =

$$F_{TNL} = 2 \left[ F_g + F_{\phi_m} + F_T + F_C + F_P \right] + F_{SH} + F_y$$

### 3.0 Full-load Calculations

$$3.1 \quad \text{Calculate } e_d = \cos \phi + x_d \sin \psi$$

$$3.2 \quad \text{Calculate } F'_{TL} = F_T (1 + \cos \phi)$$

$$3.3 \quad F_{dm} = \frac{.45 N_e I_{ph} C_m K_d}{P}$$

$$3.4 \quad \phi'_{mL} = P_m \left[ F_{dm} + F_g e_d \right]$$

$$3.5 \quad F'_{gL} = F_g e_d + \frac{P \phi_m g e}{3.18 Ag}$$

$$3.6 \quad \phi'_{PL} = \phi_P \left[ e_d - .93 X_{ad} \sin \psi \right]$$

$$3.7 \quad B'_{PL} = \frac{\phi'_{PL} + \phi_m}{A_{pole}}$$

$$3.8 \quad F'_{PL} = h_p \left[ NI \text{ at } B'_{PL} \right]$$

$$3.9 \quad \phi'_{4L} = P_4 \left[ F'_{gL} + F'_{TL} + F'_{PL} \right]$$

$$3.10 \quad \phi'_{5L} = P_5 \left[ 2 F'_{gL} + 2 F'_{TL} + 2 F'_{PL} \right]$$

$$3.11 \quad \phi'_{6L} = P_6 \left[ 2 F'_{gL} + 2 F'_{TL} + 2 F'_{PL} \right]$$

$$3.12 \quad \phi'_{7L} = P_7 \left[ F'_{gL} + F'_{TL} + F'_{PL} \right]$$

$$3.13 \quad \phi'_{SHL} = \phi'_{PL} \frac{P}{2} + P \phi_m + \phi'_{4L} + \phi'_{7L}$$

$$3.14 \quad B'_{SHL} = \frac{\phi'_{SHL}}{A_{SH}}$$

$$3.15 \quad F'_{SHL} = \ell_{SH} \left[ NI \text{ at } B'_{SHL} \right]$$

$$3.16 \quad \phi'_{mL} = P_m \left[ F_{dm} + F'_{gL} \right]$$

$$3.17 \quad \phi_{PL} = \phi'_{PL} + \phi_{mL}$$



$$3.18 \quad B_{PL} = \frac{\phi_{PL}}{A_p}$$

$$3.19 \quad F_{PL} = h_p \left[ NI \text{ at } B_{PL} \right]$$

$$3.20 \quad F_{gL} = F_g e_d + \frac{P \phi_{mge}}{Ag \ 3.19}$$

$$3.21 \quad B_{TL} = B_T + \frac{4 \phi_{mL}}{A_T}$$

$$3.22 \quad F_{TL} = h_T \left[ NI \text{ at } B_{TL} \right] (1 + \cos \theta)$$

$$3.23 \quad \phi_{7L} = P_7 \left[ F_{TL} + F_{gL} + F_{PL} \right]$$

$$3.24 \quad \phi_{4L} = P_4 \left[ F_{TL} + F_{gL} + F_{PL} \right]$$

$$3.25 \quad \phi_{\text{shaft } L} = \frac{\phi_{PL} (P)}{2} - \frac{P}{2} \phi_{mL} - \phi_{7L} - \phi_{4L}$$

$$3.26 \quad B_{SHL} = \frac{\phi_{SHL}}{A_{SH}}$$

$$3.27 \quad F_{SHL} = \ell_{SH} \left[ NI \text{ at } B_{SHL} \right]$$

$$3.28 \quad \phi_{5L} = P_5 \left[ 2F_{TL} + 2F_{gL} + 2F_{FL} + F_{SHL} \right]$$

$$3.29 \quad \phi_{6L} = P_6 \left[ 2F_{TL} + 2F_{gL} + 2F_{PL} + F_{SHL} \right]$$

$$3.30 \quad \phi_{\text{core } L} = \phi_{PL} + \frac{\phi_{5L} + \phi_{6L}}{P}$$

$\phi_4$  and  $\phi_7$  are leakage fluxes between pole positions and do not add to the flux density in the core.

$$3.31 \quad B_{\text{core } L} = \frac{\phi_{cL}}{A_{cL}}$$

$$3.32 \quad F_{cL} = \text{dbs} \left[ \text{NI/in at } B_{cL} \right]$$

$$3.33 \quad \phi_{yL} = \phi_{SHL} + \phi_{6L} + \phi_{5L}$$

$$3.34 \quad B_{yL} = \frac{\phi_{yL}}{A_y}$$


$$3.35 \quad F_{yL} = \ell_y \left[ \text{NI/in at } B_{yL} \right]$$

$$3.36 \quad F_{\text{total } L} = 2F_{gL} + 2F_{TL} + 2F_{cL} + 2F_{PL} + F_{SHL} + F_{yL}$$

## YOKE FLUX AND LENGTH

There are three common types of housing or yoke construction and each must be calculated differently.

1. The first type of housing is straight and of uniform thickness




The coil is located between the stator stacks and is between the output winding and the housing or yoke.

$$l_y = b_{\text{coil}} + \frac{2}{3}l$$

assuming that the effective length of the yoke, for the flux density calculated is  $\frac{1}{3}$  of the stack length.

2. In the second type of housing design, the excitation coil is so located that the housing or yoke must be jogged out to accomodate it.



$$l_{ye} = l_{ye} + 2t_{ye} + (d_{ye} - D)$$

The flux in  $l_{ye}$  is  $\phi_{yL}$


The flux in the housing or yoke, that is directly outside the stator stack is:

$$l_y = \frac{2}{3}l$$

$\phi_{y2L} = \phi_{yL} - \phi_{5L}$  since we have calculated a flux value for case 1, the straight, uniform thickness housing.

3. In the third configuration, the housing is tapered over the stator and the yoke density is approximately uniform over most of the stator stack length. The yoke length in this case can be taken as  $3/4 l$  over each stack or

$$l_y = 3/2 l \quad \& \quad l_{yCT} = l_{yc} + 2t_{yc} + [d_{yc} - D] \\ \text{AS IN CASE 2.}$$



The flux in the yoke directly outside the stack is

$$\phi_{y3L} = \phi_{yL} - \phi_{5L}$$

(143)	$I_{FNL}$	<p><u>FIELD CURRENT</u> - at no load</p> $I_{FNL} = (FNL)/(N_F) = (142)/(99)$
(144)	$S_F$	<p><u>CURRENT DENSITY</u> - at no load. Amperes per square inch of field conductor.</p> $S_F = (I_{FNL})/(a_{cf}) = (143)/(106)$
(145)	$E_F$	<p><u>FIELD VOLTS</u> - at no load. This calculation is made with cold field resistance at 20°C for no load condition.</p> $E_F = (I_{FNL})(R_f \text{ cold}) = (143)(107)$
(146)	$I^2R$	<p><u>ROTOR <math>I^2R</math></u> - at no load. The copper loss in the field winding is calculated with cold field resistance at 20°C for no load condition.</p> $I^2R = (I_{FNL})^2 (R_f \text{ cold}) = (143)^2 (107)$

(147)

F&amp;W

FRICTION & WINDAGE LOSS

- The best values are obtained by using existing data. For ratioing purposes, the loss can be assumed to vary approximately as the  $5/2$  power of the rotor diameter and as the  $3/2$  power of the RPM. When no existing data is available, the following calculation can be used for an approximate answer. Insert 0. when computer is to calculate F&W. Insert actual F&W when available. Use same value for all load conditions.

$$F\&W = 2.52 \times 10^{-6} (d_r)^{2.5} 2\ell_n (\text{RPM})^{1.5}$$

$$= 2.52 \times 10^{-6} (11a)^{2.5} 2(76) (7)^{1.5}$$

(148)

W<sub>TNL</sub>STATOR TEETH LOSS - at no load. The no load loss

(W<sub>TNL</sub>) consists of eddy current and hysteresis losses in the iron. For a given frequency the no load tooth loss will vary as the square of the flux density. The losses in the two stators are approximately the same as if all the voltage were generated in a single stator.

$$W_{TNL} = .453(b_{t1/3})(Q)(\ell_s)(h_s)(K_Q)$$

$$= .453(57a)(23)(17)(22)(148)$$

$$\text{Where } K_Q = (k) \left[ \frac{(B_t)}{(B)} \right]^2 = (19) \left[ \frac{(127)}{(20)} \right]^2$$

(149)  $W_c$ 

STATOR CORE LOSS - The stator core losses are due to eddy currents and hysteresis and do not change under load conditions. For a given frequency the core loss will vary as the square of the flux density ( $B_c$ ).

$$W_c = 1.42 \left[ (D) - (h_c) \right] (h_c)(\ell_s)(K_Q)$$

$$= 1.42 \left[ (12) - (24) \right] (24)(17)(149)$$

$$\text{Where } K_Q = (k) \left[ \frac{(B_c)}{(B)} \right]^2 = (19) \left[ \frac{(128)}{(20)} \right]^2$$

(150)  $W_{NPL}$ 

POLE FACE LOSS - at no load. The pole surface losses are due to slot ripple caused by the stator slots. They depend upon the width of the stator slot opening, the air gap, and the stator slot ripple frequency. The no load pole face loss ( $W_{PNL}$ ) can be obtained from Graph 2. Graph 2 is plotted on the bases of open slots. In order to apply this curve to partially open slots, substitute  $b_o$  for  $b_s$ . For a better understanding of Graph 2, use the following sample.

$K_1$  as given on Graph 2 is derived empirically and depends on lamination material and thickness. Those values given on Graph 2 have been used with success.  $K_1$  is an input and must be specified. See item (151) for values of  $K_1$ .

(150) (Cont.)

$K_2$  is shown as being plotted as a function of  $(B_G)^{2.5}$ . Also note that upper scale is to be used. Another note in the lower right hand corner of graph indicates that for a solid line (—), the factor is read from the left scale, and for a broken or dashed line (— - — -), the right scale should be read. For example, find  $K_2$  when  $B_G = 30$  kilo lines. First locate 30 on upper scale. Read down to the intersection of solid line plot of  $K_2 = f(B_G)^{2.5}$ . At this intersection read the left scale for  $K_2$ .  $K_2 = .28$ . Also refer to item (152) for  $K_2$  calculations.

$K_3$  is shown as a solid line plot as a function of  $(F_{SLT})^{1.65}$ . The note on this plot indicates that the upper scale X 10 should be used. Note  $F_{SLT}$  = slot frequency. For an example, find  $K_3$  when  $F_{SLT} = 1000$ . Use upper scale X 10 to locate 1000. Read down to intersection of solid line plot of  $K_3 = f(F_{SLT})^{1.65}$ . At this intersection read the left scale for  $K_3$ .  $K_3 = 1.35$ . Also refer to item (153) for  $K_3$  calculations.

For  $K_4$  use same procedure as outlined above except use lower scale. Do not confuse the dashed line in this plot with the note to use the right scale. The note does not apply in this case. Read left scale. Also refer to item (154) for  $K_4$  calculations.

For  $K_5$  use bottom scale and substitute  $b_o$  for  $b_s$  when using partially closed slot. Read left scale when using solid plot. Use right scale when using dashed plot. Also refer to item (155) for  $K_5$  calculations.



(150)	(Cont.)	<p>For <math>K_6</math> use the scale attached for <math>C_1</math> and read <math>K_6</math> from left scale. Also refer to item (156) for <math>K_6</math> calculations.</p> <p>The above factors (<math>K_2</math>), (<math>K_3</math>), (<math>K_4</math>), (<math>K_5</math>), (<math>K_6</math>) can also be calculated as shown in (152), (153), (154), (155), (156), respectively.</p> $W_{PNL} = \pi(d)(L)(K_1)(K_2)(K_3)(K_4)(K_5)(K_6)$ $= \pi(11)(13)(151)(152)(153)(154)(155)(156)$
(151)	$K_1$	<p><math>K_1</math> is derived empirically and depends on lamination material and thickness. The values used successfully for <math>K_1</math> are shown on Graph 2. They are</p> <p><math>K_1 = 1.17</math> for .028 lam thickness, low carbon steel  <math>= 1.75</math> for .063 lam thickness, low carbon steel  <math>= 3.5</math> for .125 lam thickness, low carbon steel  <math>= 7.0</math> for solid</p> <p><math>K_1</math> is an input and must be specified on input sheet.</p>
(152)	$K_2$	<p><math>K_2</math> can be obtained from Graph 2 (see item 150) for explanation of Graph 2) or it can be calculated as follows:</p> $K_2 = f(B_G) = 6.1 \times 10^{-5} (B_G)^{2.5}$ $= 6.1 \times 10^{-5} (125)^{2.5}$
(153)	$K_3$	<p><math>K_3</math> can be obtained from Graph 2 (see item 150) for explanation of Graph 2) or it can be calculated as follows:</p> $K_3 = f(F_{SLT}) = 1.5147 \times 10^{-5} (F_{SLT})^{1.65}$ $= 1.5147 \times 10^{-5} (153)^{1.65}$ <p>Where <math>F_{SLT} = \frac{(RPM)}{60} (Q)</math></p> $= \frac{(7)}{60} (23)$

(154)  $K_4$ 

$K_4$  can be obtained from Graph 2 (see item (150) for explanation of Graph 2) or it can be calculated as follows:

For  $\tau_s \leq .9$

$$\begin{aligned} K_4 &= f(\tau_s) = .81(\tau_s)^{1.285} \\ &= .81(26)^{1.285} \end{aligned}$$

For  $.9 \leq \tau_s \leq 2.0$

$$\begin{aligned} K_4 &= f(\tau_s) = .79(\tau_s)^{1.145} \\ &= .79(26)^{1.145} \end{aligned}$$

For  $\tau_s > 2.0$

$$\begin{aligned} K_4 &= f(\tau_s) = .92(\tau_s)^{.79} \\ &= .92(26)^{.79} \end{aligned}$$

(155)  $K_5$ 

$K_5$  can be obtained from Graph 2 (see item (150) for explanation of Graph 2) or it can be calculated as follows:

For  $(b_s)/(g) \leq 1.7$

$$\begin{aligned} K_5 &= f(b_s/g) = .3 \left[ (b_s)/(g) \right]^{2.31} \\ &= .3 \left[ (22)/(59) \right]^{2.31} \end{aligned}$$

NOTE: For partially open slots substitute  $b_o$  for  $b_s$  in equations shown.

For  $1.7 < (b_s)/(g) \leq 3$

$$\begin{aligned} K_5 &= f(b_s)/(g) = .35 \left[ (b_s)/(g) \right]^2 \\ &= .35 \left[ (22)/(59) \right]^2 \end{aligned}$$

		<p>For <math>3 &lt; (b_g) / (g) \leq 5</math></p> $K_5 = f(b_g) / (g) = .625 \left[ (b_g) / (g) \right]^{1.4}$ $= .625 \left[ (22) / (59) \right]^{1.4}$ <p>For <math>(b_g) / (g) &gt; 5</math></p> $K_5 = f(b_g) / (g) = 1.38 \left[ (b_g) / (g) \right]^{.965}$ $= 1.38 \left[ (22) / (59) \right]^{.965}$
(156)	$K_6$	<p><math>K_6</math> can be obtained from Graph 2 (see item (150) for explanation of Graph 2) or it can be calculated as follows:</p> $K_6 = f(C_1) = 10 \left[ .9323(C_1) - 1.60596 \right]$ $= 10 \left[ .9323(71) - 1.60596 \right]$
(158)	$I^2 R$	<p><u>STATOR <math>I^2 R</math></u> - at no load. This item = 0. Refer to item (173) for 100% load stator <math>I^2 R</math>.</p>
(158a)	--	<p><u>EDDY LOSS</u> - at no load. This item = 0. Refer to item (173a) for 100% load eddy loss.</p>
(159)	--	<p><u>TOTAL LOSSES</u> - at no load. Sum of all losses</p> <p>Total losses = (Rotor <math>I^2 R</math>) + (F &amp; W) + (Stator Teeth Loss)  + (Stator Core Loss) + (Pole Face Loss)  + (Damper Loss)</p> <p>= (146) + (147) + (148) + (149) + (150) + (157)</p>

(166)	$I_{FFL}$	<p><u>FIELD CURRENT</u> at 100% load</p> <p><math>I_{FFL} = (F_{FL})/(N_F) = (165)/(99)</math></p>
(167)	--	<p><u>CURRENT DENSITY</u> at 100% load</p> <p>Current density = <math>(I_{FFL})/(a_{cf}) = (166)/(106)</math></p>
(168)	$E_{FFL}$	<p><u>FIELD VOLTS</u> at 100% load - This calculation is made with hot field resistance at expected temperature at 100% load.</p> <p>Field Volts = <math>(I_{FFL}) (R_f \text{ hot}) = (166)(108)</math></p>
(169)	$I^2R_F$	<p><u>FIELD <math>I^2R</math></u> at 100% load - The copper loss in the field winding is calculated with hot field resistance at expected temperature for 100% load condition.</p> <p>Field <math>I^2R = (I_{FFL})^2(R_F \text{ hot}) = (166)^2(108)</math></p>
(170)	$W_{TFL}$	<p><u>STATOR TEETH LOSS</u> at 100% load - The stator tooth loss under load increases over that of no load because of the parasitic fluxes caused by the ripple due to flux distortion.</p> $W_{TFL} = \left\{ 2 \left[ 27(X_d) \frac{(\% \text{ Load})}{100} \right]^{1.8} + 1 \right\} (W_{TNL})$ <p>NOTE <math>(X_d)</math> is in per unit</p> $= \left\{ 2 \left[ 27(83) \right] + 1 \right\} (148)$

POLE FACE LOSS at 100% load

$$W_{PFL} = \left\{ \left[ \frac{(K_{sc})(I_{PH}) \frac{(\% \text{ Load})}{100} (n_s)}{(C)(F_g)} \right]^2 + 1 \right\} (W_{PNL})$$

$$= \left\{ \left[ \frac{(171)(8) 1 (30)}{(32)(131)} \right]^2 + 1 \right\} (150)$$

( $K_{sc}$ ) is obtained from Graph 3

(173)	$I^2R$	<p><u>STATOR <math>I^2R</math></u> at 100% load - The copper loss based on the D.C. resistance of the winding. Calculate at the maximum expected operating temperature.</p> $I^2R = (m)(I_{PH})^2 (R_{SPH \text{ hot}}) \frac{(\% \text{ Load})}{100}$ $= (5)(8)^2 (54) 1.$
(173a)	--	<p><u>EDDY LOSS</u> - Stator <math>I^2R</math> loss due to skin effect</p> $\text{Eddy Loss} = \left[ \frac{(EF_{top}) + (EF_{bot})}{2} - 1 \right] (\text{Stator } I^2R)$ $= \left[ \frac{(55) - (56)}{2} - 1 \right] (173)$
(174)	--	<p><u>TOTAL LOSSES</u> at 100% load - sum of all losses at 100% load</p> $\text{Total Losses} = (\text{Field } I^2R) + (F \& W) + (\text{Stator Teeth Loss})$ $+ (\text{Stator Core Loss}) + (\text{Pole Face Loss})$ $(\text{Stator } I^2R) \quad (\text{Eddy Loss})$ $= (169) + (147) + (170) + (149) + (171) + (172) + (173) + (173a)$

(175) -- RATING IN WATTS at 100% load

$$\begin{aligned}\text{Rating} &= 3(E_{PH})(I_{PH}) \quad (\text{P.F.}) \frac{(\% \text{ Load})}{100} \\ &= 3(4)(8) \quad (9)(1.)\end{aligned}$$

(176) -- RATING &  $\Sigma$  LOSSES = (175) + (174)

$$\begin{aligned}\text{(177)} \quad \text{--} \quad \underline{\% \text{ LOSSES}} &= \left[ \Sigma \text{ Losses} / \text{Rating} + \Sigma \text{ Losses} \right] 100 \\ &= \left[ (174) / (177) \right] 100\end{aligned}$$


$$\begin{aligned}\text{(178)} \quad \text{--} \quad \underline{\% \text{ EFFICIENCY}} &= 100\% - \% \text{ Losses} \\ &= 100\% - (177)\end{aligned}$$

Item (160) through (178) are 100% load calculations.

These items can be recalculated for any load condition by simply inserting the values that correspond to the % load being calculated. The factor  $\frac{(\% \text{ Load})}{100}$  takes care of  $(I_{PH})$  as it changes with load.

Note that values for F & W (147) and  $W_C$  (Stator Core Loss) (149) do not change with load,


DISK-TYPE, OR AXIAL AIR-GAP  
LUNDELL TYPE AC GENERATORS



H

AXIAL AIR-GAP, LUNDELL TYPE, A.C. GENERATOR





DISK TYPE LUNDELL


(No Model.)

2 Sheets—Sheet 1.

R. LUNDELL.  
DYNAMO ELECTRIC MACHINE.

No. 490,809.

Patented Jan. 31, 1893.



Witnesses  
C. E. Ashley  
C. W. Chamberlain

Inventor  
Robert Lundell  
By his Attorney  
Charles J. Kintner

The original Lundell generator patented by Robert Lundell in 1893 was an axial air-gap generator with the output windings rotating.

The newer brushless, axial air-gap generator has the field structure rotating and the output winding is stationary. The brushes are eliminated through the use of auxiliary air-gaps.

The weight of this machine is approximately the same as that of a radial gap Lundell generator of the same rating, speed and frequency. It can be built with two stators and one field coil for maximum output at a given diameter.

The output of the disk-type or axial-gap Lundell generator is a function of the third power of the stator diameter,  $(D)^3$ .

If a single-stator axial-gap generator and a radial-gap generator are built with the same KVA, frequency, RPM, air-gap flux density, and stator ampere loading (or the same reactances) the rotor of the disk-type generator will be a minimum of two (2) times the diameter of the radial-gap generator. See derivations in Second Quarterly Report.


At the same rating and conditions of load, the single-stator axial air-gap machine operates at four (4) times the stress level of the radial-gap machine.

The outputs of all of the Lundell generators are functions of the third power of their rotor diameters  $(d)^3$ , but for equal maximum rotor stresses, the radial gap generator will have  $(2)^3$  or 8 times the output of the disk-type machine.


Though the machine weights are comparable, the disk-type machine has more  $WR^2$  and more gyroscopic moment than the radial gap Lundell machines.

The attractive force, due to air-gap flux, between the rotor and stator of the single-stator machine is great and the single-stator configuration cannot be used with fluid bearings. The more balanced two-stator design must be used with fluid bearings.


In some cases, the axial air-gap machines are advantageous because of their physical configuration and the design procedure is included in this study for completeness.




COMPLETE FLUX CIRCUIT OF  
A SINGLE-STATOR, AXIAL-GAP,  
LUNDELL, A-C GENERATOR  
LEAKAGE FLUXES ARE INCLUDED




ELECTROMAGNETIC PARTS OF  
A SINGLE STATOR, AXIAL GAP,  
LUNDELL, A-C GENERATOR



ELECTROMAGNETIC PARTS OF  
A TWO-STATOR, AXIAL GAP, LUNDELL  
A-C GENERATOR




AXIAL AIR-GAP LUNDELL  
OUTPUT VS DIA. OF ROTOR







(a) Open Slots



(b) Constant Slot Width



(c) Constant Tooth Width



(d) Round Slots




FIG 1

TABLE - 1

## CHORD FACTORS $K_0$ FOR HARMONICS AT DIFFERENT PITCHES

[illegible]

VALUES OF  $K_{dn}$  FOR INTEGRAL-SLOT, 30 WINDINGS - TABLE 2

$n$	$K_{dn}$ - HARMONIC DISTRIBUTION FACTORS									
$q =$	2	3	4	5	6	7	8	9	10	$\infty$
1	.966	.960	.958	.957	.957	.957	.956	.955	.955	.955
3	.707	.667	.654	.646	.644	.642	.641	.640	.639	.636
5	.259	.217	.205	.200	.197	.195	.194	.194	.193	.191
7	-.259	-.177	-.158	-.149	-.145	-.143	-.141	-.140	-.140	-.136
9	-.707	-.333	-.270	-.247	-.236	-.229	-.225	-.222	-.220	-.212
11	-.966	-.177	-.126	-.110	-.102	-.097	-.095	-.093	-.092	-.087
13	-.966	.217	.126	.102	.092	.086	.083	.081	.079	.073
15	-.707	.667	.270	.200	.172	.158	.150	.145	.141	.127
17	-.259	.960	.158	.102	.084	.075	.070	.066	.064	.056
19	.259	.960	-.205	-.110	-.084	-.072	-.066	-.062	-.060	-.059
21	.707	.667	-.654	-.247	-.172	-.143	-.127	-.118	-.112	-.091
23	.966	.217	-.958	-.149	-.092	-.072	-.063	-.057	-.054	-.041
25	.966	-.177	-.958	.200	.102	.075	.063	.056	.052	.038
27	.707	-.333	-.654	.646	.236	.158	.127	.111	.101	.071
29	.259	-.177	-.205	.957	.145	.086	.066	.056	.050	.033
31	-.259	.217	.158	.957	-.197	-.097	-.070	-.057	-.050	-.031



33	-.709	.667	.270	.646	-.644	-.229	-.150	-.118	-.101	-.058
35	-.966	.960	.126	.200	-.957	-.143	-.083	-.062	-.052	-.027
37	-.966	.960	-.126	-.149	-.957	.195	.095	.066	.054	.026
39	-.707	.667	-.270	-.247	-.644	.642	.225	.145	.112	.049
41	-.259	.217	-.158	-.110	-.197	.957	.141	.081	-.060	.023
43	.259	-.177	.205	.102	.145	.957	-.194	-.093	-.064	-.022
45	.707	-.333	.654	.200	.236	.642	-.641	-.222	-.141	-.042
47	.966	-.177	.958	.102	.102	.195	-.956	-.140	-.079	-.020
49	.966	.217	.958	-.110	-.092	-.143	-.956	.194	.092	.019
51	.707	.667	.654	-.247	-.172	-.229	-.641	.640	.220	.038
53	.259	.960	.205	-.149	-.084	-.097	-.194	.955	.140	.018
55	-.259	.960	-.158	.200	.084	.086	.141	.955	-.193	-.017
57	-.707	.667	-.270	.646	.172	.158	.225	.640	-.639	-.033
59	-.966	.217	-.126	.957	.092	.075	.095	.194	-.955	-.016
61	-.966	-.177	.126	.957	-.102	-.072	-.083	-.140	-.955	.016
63	-.707	-.333	.270	.646	-.236	-.143	-.150	-.222	-.639	.030
65	-.259	-.177	.158	.200	-.145	-.072	-.070	-.093	-.193	.015

# ROUND COPPER WIRE

## TABLE 3


SIZE AWG	BARE DIAMETER	AREA □"	Ω/1000' @25°C	SINGLE FORMVAR	HEAVY FORMVAR	SINGLE GLASS FORMVAR	BARE WT. #/1000'	SINGLE GLASS SILICONE	DOUBLE GLASS SILICONE
36	.0050	.0000196	424	.0056	.0060		.0757		
35	.0056	.0000246	338	.0062	.0066		.0949		
34	.0063	.0000312	266	.0070	.0074		.1201		
33	.0071	.0000396	210	.0079	.0084		.1526		
32	.0080	.0000503	165	.0088	.0094	.0121	.1937		
31	.0089	.0000622	134	.0097	.0104	.0130	.2398		
30	.0100	.0000785	106	.0108	.0116	.0142	.3025	.0132	.0152
29	.0113	.000100	83.1	.0122	.0130	.0156	.3866	.0145	.0165
28	.0126	.000125	66.4	.0135	.0144	.0169	.4806	.0158	.0178
27	.0142	.000158	52.6	.0152	.0161	.0186	.6101	.0174	.0194
26	.0159	.000199	41.7	.0169	.0179	.0203	.7650	.0191	.0211
25	.0179	.000252	33.0	.0190	.0200	.0224	.970	.0211	.0231
24	.0201	.000317	26.2	.0213	.0223	.0263	1.223	.0251	.0276
23	.0226	.000401	20.7	.0238	.0249	.0289	1.546	.0276	.0301
22	.0254	.000507	16.4	.0266	.0277	.0317	1.937	.0303	.0328
21	.0285	.000638	13.0	.0299	.0310	.0349	2.459	.0335	.0360
20	.0320	.000804	10.3	.0334	.0346	.0384	3.099	.0370	.0395
19	.0360	.00102	8.14	.0374	.0386	.0424	3.900	.0409	.0434
18	.0403	.00126	6.59	.0418	.0431	.0468	4.914	.0453	.0478
17	.0453	.00159	5.22	.0469	.0482	.0519	6.213	.0503	.0528
16	.0508	.00204	4.07	.0524	.0538	.0575	7.812	.0558	.0583
15	.0571	.00255	3.26	.0588	.0602	.0639	9.87	.0621	.0646
14	.0641	.00322	2.58	.0659	.0673	.0710	12.44	.0691	.0716
13	.072	.00407	2.04	.0738	.0753	.0789	15.69	.0770	.0795
12	.0808	.00515	1.61	.0827	.0842	.0877	19.76	.0858	.0883
11	.0907	.00650	1.28	.0927	.0942	.0977	24.90	.0957	.0982
10	.102	.00817	1.02	.1039	.1055	.1089	31.43	.1069	.1094
9	.114	.0102	.814	.1165	.1181	.1225	39.62	.1204	.1254
8	.129	.0131	.634	.1306	.1323	.1366	49.98	.1345	.1395
7	.144	.0163	.510	.1465	.1482	.1525	63.03	.1503	.1553
6	.162	.0206	.403	.1643	.1661	.1703	79.44	.1680	.1730
5	.182	.0260	.319	.1842	.1861	.1902	100.2	.1879	.1929
4	.204	.0327	.254				126.3	.2103	.2153
3	.229	.0412	.202				159.3		
2	.258	.0523	.159				200.9		
0	.325	.0830	.100						
2/0	.365	.105	.0791						
4/0	.460	.166	.0500						

CURVE 1




**DRAWN BY T.A.T.**

REFER TO ITEM (150) IN SALIENT POLE DESIGN MANUAL FOR  
SAMPLE USE OF THIS CURVE




# CURVE-3

FROM E.I. POLLARD'S "LOAD LOSSES IN SALIENT POLE  
SYNCHRONOUS MACHINES" AIEE TRANS. VOL. 54  
1935 PP 1332-1340




CURVE 4



Ginsberg, David - Design  
Calculation for A-C  
Generators. Trans. AIEE,  
Vol. 69, pp 1274-80, 1950.



$C_x$  - SLOT FACTOR FOR APPROXIMATE REACTANCE FORMULA



PERCENT COIL EMBRACE

CURVE 5

PERCENT COIL EMBRACE

# NO-LOAD DAMPER LOSS

CURVE 7

$$D.L. = \frac{1.246 P n_b l_b \rho}{10^6 a_b} \left[ \tau_s B_g K_p K_g \right]^2 \left[ \frac{K_{f1} / K_{w1}}{(2\lambda_s + \frac{\lambda_g}{K_{\phi 1}})}^2 + \frac{K_{f2} / K_{w2}}{(2\lambda_s + \frac{\lambda_g}{K_{\phi 2}})}^2 \right]$$

= LOSS IN KW

$$\lambda_s = \frac{n_r}{b_r} + \lambda_t + \lambda_c$$

$a_b$  = BAR AREA IN SQ IN.

$\tau_b$  = BARS/POLE

$$\lambda_g = \frac{\tau_b}{K_g g} = \frac{\tau_b}{g'}$$

$\rho$  = NO. POLES

$l_b$  = LENGTH BAR IN.

$K_g$  = CARTER'S COEFFICIENT (TOTAL)

$K_p = f_n(b_s/g)$ , CURVE (a) ( $b_s = b_o$  for partially closed slots)

$K_{f1}$  AND  $K_{f2} = f_n(f_s/\rho)$  CURVE (b)

$\rho$  = DAMPER BAR RESISTIVITY (MICROHMS PER CU. IN.)

$K_{w1}$  AND  $K_{w2} = f_n(b_s/\tau_s)$ , CURVE (c1) AND (c2)



$K_{\phi 1}$  AND  $K_{\phi 2} = f_n(\tau_b/\tau_s)$ , CURVE (d1) AND (d2)

$\lambda_t = f_n(b_r/g K_g)$  CURVE (e)

$B_g$  IS IN KILOLINES PER SQ INCH


$\lambda_c = \frac{75}{K_{f1}}$  (FOR ROUND OR SQ. BARS)

$\lambda_c = \frac{n_b}{3 b_b K_{f1}}$  (FOR RECT. BARS)




# NO-LOAD DAMPER LOSS


CURVE 8




CURVE 9




$C_m$   
&  
 $C_q$












SEMI-LOGARITHMIC 359.71  
KUFTEL & ESSER CO. MILWAUKEE, WIS.  
3 CYCLES X 70 DIVISIONS









CURVE 17



# DISC - TYPE SYNCHRONOUS GENERATOR

STATOR	ROTOR																									
STATOR I.D. _____	SINGLE GAP _____ $g_s$																									
STATOR O.D. _____	ROTOR O.D. _____ I.D. _____																									
CORE LENGTH _____	PERIPHERAL SPEED _____																									
DBS X 2 _____	POLE PITCH _____ $\alpha$																									
SLOTS _____	POLE AREA-OUTER _____																									
CARTER COEFF. _____	POLE AREA-INNER _____																									
TYPE WEDGE _____	ROTOR LEAKAGE _____																									
THROW _____	POLE DENSITY _____																									
SKEW & DIST FACT. _____	ROTOR IRON _____																									
CHORD FACTOR _____	DAMPER BARS N <sup>o</sup> _____																									
COND. PER SLOT _____	BAR SIZE _____																									
TOTAL EFF. COND. _____	BAR PITCH _____ $h_o$ $b_o$																									
COND. SIZE _____	FIELD COIL TURNS _____																									
COND. AREA _____	COND. SIZE _____																									
CURRENT DENSITY _____	COND. AREA _____																									
WDG. CONST. _____ $C_1$	MEAN TURN _____																									
TOTAL FLUX _____	RES @ _____ $^{\circ}$																									
GAP AREA _____	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td>% LOAD</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>P.F.</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>AMPS</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>VOLTS</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td><math>I^2 R</math></td> <td></td> <td></td> <td></td> <td></td> </tr> </table>	% LOAD					P.F.					AMPS					VOLTS					$I^2 R$				
% LOAD																										
P.F.																										
AMPS																										
VOLTS																										
$I^2 R$																										
GAP DENSITY _____																										
POLE CONST. _____																										
FLUX PER POLE _____																										
SHAFT FLUX _____																										
TOOTH PITCH _____	AMPS/IN. <sup>2</sup> _____																									
TOOTH DENSITY _____	FIELD SELF IND. _____																									
CORE DENSITY _____	DAMP. LEAK $X_{d_d}$ $X_{d_g}$																									
GRADE IRON _____	REACTION-TIME CONSTANT _____																									
$\frac{1}{2}$ MEAN TURN _____	SYNCH. $X_d$ $X_q$																									
RES/PHASE @ _____ $^{\circ}$	UNSAT. TRANS. _____																									
EDDY FACT TOP _____	SAT. TRANS. _____																									
E.F. AVE _____ EFF. BOT. _____	SUBTRANS. $X_c''$ $X_g''$																									
DEMAG. FACT. $C_m$ $C_g$	NEG. SEQUENCE _____																									
AMP COND. PER IN _____	ZERO SEQUENCE _____																									
REACT. FACTOR _____	OPEN CIR. TIME CON. _____																									
COND. PERM. _____	ARM. TIME CON. _____																									
END PERM. _____	TRANS. TIME CON. _____																									
LEAKAGE REACT. _____	SUBTRANS. TIME CON. _____																									
AIR GAP PERM. _____																										
REACT. OF ARM. $X_{ad}$ $X_{ag}$																										
WT. OF COPPER _____																										
WT. OF IRON _____																										



SATURATION
AIR GAP AT _____
STATOR AT _____
POLE AT _____
NO LOAD AT _____
RATED LOAD AT _____
OVERLOAD AT _____
SHORT CIRCUIT AT _____
LOSSES - EFFICIENCY
% LOAD _____
F & W _____
STA. TEETH _____
STA. CORE _____
POLE FACE _____
DAMPER _____
STA. $I^2 R$ _____
EDDY _____
FIELD $I^2 R$ _____
$\Sigma$ LOSSES _____
RATING _____
RATING & LOSSES _____
% LOSSES _____
% EFF. _____

W.O. \_\_\_\_\_ FOR \_\_\_\_\_ COOLING \_\_\_\_\_  
 \_\_\_\_\_ KVA \_\_\_\_\_ % P.F. \_\_\_\_\_ VOLTS \_\_\_\_\_ AMPS \_\_\_\_\_ PHASE \_\_\_\_\_  
 \_\_\_\_\_ CYCLES/SEC. \_\_\_\_\_ POLES \_\_\_\_\_ RPM \_\_\_\_\_ BY \_\_\_\_\_

# AXIAL AIR-GAP, LUNDELL TYPE A. C. GENERATOR, DESIGN MANUAL

(1)	--	<u>DESIGN NUMBER</u> - To be used for filing purposes.
(2)	KVA	<u>GENERATOR KVA</u>
(3)	E	<u>LINE VOLTS</u>
(4)	E <sub>PH</sub>	<p><u>PHASE VOLTS</u> - For 3 phase, <sup>Y</sup> connected generator</p> $E_{PH} = \frac{(\text{Line Volts})}{\sqrt{3}} = \frac{(3)}{\sqrt{3}}$ <p>For 3 phase, <sup>Δ</sup> connected generator</p> $E_{PH} = (\text{Line Volts}) = (3)$
(5)	m	<u>PHASES</u> - number of
(5a)	f	<u>FREQUENCY</u> - In cycles per second
(6)	P	<u>POLES</u> - Number of
(7)	RPM	<u>SPEED</u> - In revolutions per minute
(8)	I <sub>PH</sub>	<u>PHASE CURRENT</u> - In amperes at rated load
(9)	PF	<u>POWER FACTOR</u> - Given in per unit
(9a)	K <sub>C</sub>	<p><u>ADJUSTMENT FACTOR</u> - When PF = 0. to .95 set K<sub>C</sub> = 1;</p> <p>when PF = .95 to 1. set K<sub>C</sub> = 1.05</p>

(10a) d STATOR EQUIVALENT DIAMETER

$$d = \frac{(\text{O. D.}) + (\text{I. D.})}{2} = \frac{(12) + (11)}{2}$$

(11) I. D. STATOR I. D. - The inside diameter of the stator toroid  
in inches.

(12) O. D. STATOR O. D. - The outside diameter of the stator toroid  
in inches

(13)  $l$  GROSS CORE LENGTH - In inches

$$l = \frac{(\text{O. D.}) - (\text{I. D.})}{2} = \frac{(12) - (11)}{2}$$

(16)  $K_i$  STACKING FACTOR - This factor allows for the coating  
(core plating) on the punchings, and the  
looseness of the ribbon. Approximate values  
are given in Table IV.

THICKNESS OF  
LAMINATIONS  
(INCHES)

GAGE

$K_i$

.014	29	0.92
.018	26	0.93
.025	24	0.95
.028	23	0.97
.063	--	0.98
.125	--	0.99

TABLE IV


- (17)  $\ell_s$  SOLID CORE LENGTH - The solid length is the gross length times the stacking factor.
- $$\ell_s = (K_i) \times (\ell) = (16) \times (13)$$
- (18) -- MAGNETIZATION CURVES are to be available for stator, pole and yoke.
- (19) k WATTS/LB - Core loss per lb of lamination material.  
Must be given at the density specified in (20).
- (20) B DENSITY - This value must correspond to the density used in Item (19) to pick the watts/lb. The density that is usually used is 77.4 kilolines/in<sup>2</sup>.
- (21) TYPE OF STATOR SLOT - Refer to Figure 1 for type of slot.
- (22)  $\left. \begin{array}{l} b_0 \\ b_1 \\ b_2 \\ b_3 \\ b_s \\ h_0 \\ h_1 \\ h_2 \\ h_3 \\ h_s \\ h_t \\ h_w \end{array} \right\}$  ALL SLOT DIMENSIONS - Given in inches per Figure 1.
- Note: For Type (c) slot
- $$b_s = \frac{(b_1) + (b_3)}{2} = \frac{(22) + (22)}{2}$$

(23)  $Q$  STATOR SLOTS - number of

(24)  $h_c$  DEPTH BELOW SLOTS - The depth of the stator core  
below the slots.

$$h_c = t_{to} - h_s = (24) - (22)$$

Where  $t_{to}$  is the thickness of the stator core.



(25)  $q$  SLOTS PER POLE PER PHASE

$$q = \frac{(Q)}{(P)(m)} = \frac{(23)}{(6)(5)}$$

(26)  $\gamma_s$  STATOR SLOT PITCH (average)

$$\gamma_s = \frac{\pi(d)}{Q} = \frac{\pi(10a)}{(23)}$$

(27)  $\gamma_{s\ 1/3}$  STATOR SLOT PITCH - 1/3 distance up from narrowest  
section of tooth.

$$\gamma_{s\ 1/3} = \gamma_s = (26)$$

(28) -- TYPE OF WINDING - Record whether the connection is  
"wvc" of "delta".

(29) -- TYPE OF COIL - Record whether random wound or formed  
coils are used.


- |       |          |  |
|-------|----------|--|
| (30)  | $n_s$    | <p><u>CONDUCTORS PER SLOT</u> - The actual number of conductors per slot. For random wound coils use a space factor of 75% to 80%. Where space factor is the percent of the total slot area that is available for insulated conductors after <b>all</b> other insulation areas have been subtracted out.</p> |
| (31)  | $\gamma$ | <p><u>THROW</u> - Number of slots spanned. For example, with a coil side in slot 1 and the other coil side in slot 10, the throw is 9.</p>   |
| (31a) |          | <p><u>PERCENT OF POLE PITCH SPANNED</u> - Ratio of the number of slots spanned to the number of slots in a pole pitch</p> $= \frac{(\gamma)}{(m)(q)} = \frac{(31)}{(5)(25)}$   |
| (32)  | C        | <p><u>PARALLEL PATHS</u>, no. of - Number of parallel circuits per phase</p>   |
| (33)  | --       | <p><u>STRAND DIA OR WIDTH</u> - In inches. For round wire, use strand diameter. For rectangular wire, use strand width.</p>  |



(34)

 $N_{ST}$ NUMBER OF STRANDS PER CONDUCTOR IN DEPTH -

Applies to rectangular wire. In order to have a more flexible conductor and reduce eddy current loss a stranded conductor is often used. For example, when the space available for one conductor is .250 width x .250 depth, the actual conductor can be made up of 2 or 3 strands in depth as shown.



For a more detailed explanation refer to section titled "Effective Resistance and Eddy Factor" in the Derivations in Appendix.

(35)

 $d_b$ 

DIAMETER OF BENDER PIN in inches - This pin is used in forming coils

(36)

 $l_{e2}$ 

COIL EXTENSION BEYOND CORE in inches - Straight portion of coil that extends beyond stator core.

(37)

 $h_{ST}$ 

HEIGHT OF UNINSULATED STRAND in inches

(38)

 $h'_{st}$ 

DISTANCE BETWEEN CENTERLINES OF STRANDS IN DEPTH in inches.

- (39) -- STATOR COIL STRAND THICKNESS in inches - For rectangular conductors only. For round wire use 0.
- (40)  $\tau_{SK}$  SKEW - Stator slot skew in inches at main air gap. To be measured at the stator O.D. as the deviation from a radial line at that point.
- (41)  $\tau_P$  POLE PITCH in inches (average)
- $$\tau_P = \frac{\pi(d)}{(P)} = \frac{\pi(10a)}{(6)}$$
- (42)  $K_{SK}$  SKEW FACTOR - The skew factor is the ratio of the voltage induced in the coils to the voltage that would be induced if there were no skew
- $$K_{SK} = \frac{\sin \left[ \frac{\pi(\tau_{SK})}{2(\tau_P)} \right]}{\frac{\pi(\tau_{SK})}{2(\tau_P)}} = \frac{\sin \left[ \frac{\pi(40)}{2(41)} \right]}{\frac{\pi(40)}{2(41)}}$$
- (43)  $K_d$  DISTRIBUTION FACTOR - The distribution factor is the ratio of the voltage induced in the coils to the voltage that would be induced in the coils if the winding were concentrated in a single slot. See Table 2 for compilation of distribution factors for the various harmonics.
- $$K_d = \frac{\sin \left[ \frac{(q)\alpha_s}{2} \right]}{(q)\sin \frac{(\alpha_s)}{2}} \quad \text{where } \alpha_s = \frac{180^\circ}{(mq)}$$

$$\therefore K_d = \frac{\sin \left[ 90^\circ / (m) \right]}{(q) \sin \left[ 90^\circ / (m)(q) \right]} = \frac{\sin \left[ 90^\circ / (5) \right]}{(25) \sin \left[ 90^\circ / (5) \times (25) \right]} \text{ For } (25) = \text{Integer}$$

or

$$K_d = \frac{\sin \left[ N \alpha (m) / 2 \right]}{N \sin \left[ \alpha (m) / 2 \right]} \text{ where } N \neq \text{Integer} = \frac{(Q)}{(m)(P)} \times \text{Integer} \text{ \& } \alpha m = \frac{180^\circ}{N \times (m)}$$

$$\therefore K_d = \frac{\sin \left[ 90^\circ / (m) \right]}{N \sin \left[ 90^\circ / N(m) \right]} = \frac{\sin \left[ 90^\circ / (5) \right]}{N \sin \left[ 90^\circ / N \times (5) \right]} \text{ For } (25) = \text{Integer}$$

- (44)  $K_P$  PITCH FACTOR - The ratio of the voltage induced in the coil to the voltage that would be induced in a full pitched coil. See Table 1 for compilation of the pitch factors for the various harmonics.

$$K_P = \sin \left[ \frac{(Y)}{(m)(q)} \times 90^\circ \right] = \sin \left[ \frac{(31)}{(5)(25)} \times 90^\circ \right]$$

- (45)  $n_e$  TOTAL EFFECTIVE CONDUCTORS - The actual number of effective series conductors in the stator winding taking into account the pitch and skew factors but not allowing for the distribution factor.

$$n_e = \frac{(Q)(n_s)(K_P)(K_{SK})}{(C)} = \frac{(23)(30)(44)(42)}{(32)}$$

- (46)  $a_c$  CONDUCTOR AREA OF STATOR WINDING in (inches)<sup>2</sup> -

The actual area of the conductor taking into account the corner radius on square and rectangular wire. See the following table for typical values of corner radii

$$\text{If } (39) = 0 \text{ then } a_c = .25\pi(\text{Dia})^2 = .25\pi(33)^2$$

If (39)  $\neq$  0 then  $a_c = (N_{ST}) \left[ (\text{strand width}) (\text{strand depth}) - (.858 r_c^2) \right]$

$$= (34) \left[ (33) (39) - \{.858 r_c^2\} \right]$$

where  $.858 r_c^2$  is obtained from Table V below.

(39)	(33) .188	.189 (33) .75	(33) .751
.050	.000124	.000124	.000124
.072	.000210	.000124	.000124
.125	.000210	.00084	.000124
.165	.000840	.00084	.003350
.225	.001890	.00189	.003350
.438	--	.00335	.007540
.688	--	.00754	.01340
--	--	.03020	.03020

TABLE V

(47)  $S_S$  CURRENT DENSITY - Amperes per square inch of stator conductor

$$S_S = \frac{(I_{PH})}{(C)(a_c)} = \frac{(8)}{(32)(46)}$$

(48)  $L_E$  END EXTENSION LENGTH in inches

When (29) = 0 then:

$$L_E = \frac{.5 + K_T \pi(Y) [O.D.]}{Q} = \frac{.5 + \left[ \begin{array}{l} 1.3 \text{ if } (6) = 2 \\ 1.5 \text{ if } (6) = 4 \\ 1.7 \text{ if } (6) > 4 \end{array} \right] \pi(31) [(12)]}{(23)}$$

When (29) = 1. then:

$$L_E = 2 l_{e2} + \pi \left[ \frac{(\text{dia})}{2} \right] + \gamma \left[ \frac{\tau_s^2}{\tau_s^2 - b_s^2} \right]$$

$$= 2 \times (36) + \pi \left[ \frac{(35)}{2} \right] + (31) \left[ \frac{(26)^2}{(26)^2 - (22)^2} \right]$$

(49)  $\ell_t$  1/2 MEAN TURN - The average length of one conductor in inches

$$\ell_t = (\ell) + (L_E) = (13) + (44)$$

(50)  $X_s^{\circ}\text{C}$  STATOR TEMP  $^{\circ}\text{C}$  - Input temp at which F. L. losses will be calculated. No load losses and cold resistance will be calculated at  $20^{\circ}\text{C}$ .

(51)  $\rho_s$  RESISTIVITY OF STATOR WINDING - In micro ohm-inches @  $20^{\circ}\text{C}$ . If tables are available using units other than that given above, use Table VI for conversion to ohm-inches.

$\rho$	ohm-cm	ohm-in	ohm-cir mil/ft
1 ohm-cm =	1.000	0.3937	$6.015 \times 10^6$
1 ohm-in =	2.540	1.000	$1.528 \times 10^7$
1 ohm-cir mil/ft =	$1.662 \times 10^{-7}$	$6.545 \times 10^{-8}$	1.000

TABLE VI  
Conversion Factors for Electrical Resistivity

(52)  $\rho_{s(\text{hot})}$  RESISTIVITY OF STATOR WINDING - Hot at  $X_s^{\circ}\text{C}$  in micro ohm-inches

$$\rho_{s(\text{hot})} = (\rho_s) \left[ \frac{(X_s^{\circ}\text{C}) + 234.5}{254.5} \right] = (51) \left[ \frac{(50) + 234.5}{254.5} \right]$$

(53)  $R_{SPH}$   
(cold)

STATOR RESISTANCE/PHASE - Cold @ 20°C in ohms

$$R_{SPH(cold)} = \frac{(\rho_s)(n_s)(Q)(\ell_t) \times 10^{-6}}{(m)(a_c)(C)^2} = \frac{(51)(30)(23)(49) \times 10^{-6}}{(5)(46)(32)^2}$$

(54)  $R_{SPH}$   
(hot)

STATOR RESISTANCE/PHASE - Calculated @ X°C in ohms

$$R_{SPH(hot)} = \frac{(\rho_{s \text{ hot}})(n_s)(Q)(\ell_t) \times 10^{-6}}{(m)(a_c)(C)^2} = \frac{(52)(30)(23)(49) \times 10^{-6}}{(5)(46)(32)^2}$$

(55) EF  
(top)

EDDY FACTOR TOP - The eddy factor of the top coil.

Calculate this value at the expected operating temperature of the machine.

$$EF_{top} = 1 + \left\{ .584 + \left[ \frac{N_{st}^2 - 1}{16} \right] \left[ \frac{h'_{st} \ell}{h_{st} \ell_t} \right]^2 \right\} 3.35 \times 10^{-3}$$

$$\left[ \frac{(h_{st})(n_s)(f)(a_c)}{(b_s)(\rho_{shot})} \right]^2$$

$$= 1 + \left\{ .584 + \left[ \frac{(34)^2 - 1}{16} \right] \left[ \frac{(38)(13)}{(37)(49)} \right]^2 \right\} 3.35 \times 10^{-3}$$

$$\left[ \frac{(37)(30)(5a)(46)}{(22)(52)} \right]^2$$

(56) EF  
(bot)

EDDY FACTOR BOTTOM - The eddy factor of the bottom coil  
at the expected operating temperature of the machine

$$EF_{(bot)} = (EF_{(top)}) - 1.677 \left[ \frac{(h_{st})(n_s)(f)(a_c)}{(b_s)(\rho_{shot})} \right]^2 \times 10^{-3}$$

$$= (55) \left[ \frac{(30) - (46)}{(22)(52)} \right] 10^{-3}$$

(57)  $b_{tm}$  STATOR TOOTH WIDTH - 1/2 way down tooth in inches - slot type (a), (b), (d) and (e), Figure I

$$b_{tm} = (\gamma_s) - (b_s) = (26) - (22)$$

For slot type (c), Figure I

$$b_{tm} = (\gamma_s) - (b_3) = (26) - (22)$$

(57a)  $b_{t \ 1/3}$  STATOR TOOTH WIDTH - 1/3 distance up from narrowest section

For slots type (a), (b) and (e)

$$b_{t \ 1/3} = (\gamma_{s \ 1/3}) - (b_s) = (27) - (22)$$

For slot type (c)

$$b_{t \ 1/3} = b_{tm} = (57)$$

For slot type (d)

$$b_{t \ 1/3} = (\gamma_{1/3}) - \frac{2\sqrt{2}}{3} (b_s) = (27) - .94(22)$$

(58)  $b_t$  TOOTH WIDTH AT STATOR - Main air gap in inches

For partially closed slot

$$b_t = \frac{\pi(d)}{(Q)} - b_0 = \frac{\pi(10a)}{(23)} - (22)$$

For open slot

$$b_t = \frac{\pi(d)}{(Q)} - b_s = \frac{\pi(10a)}{(23)} - (22)$$

- (59)  $g$  MAIN AIR GAP - given in inches
- (59a)  $g_2$  AUXILIARY AIR GAP ( $g_2$ ) - given in inches
- (59c)  $g_3$  AUXILIARY AIR GAP ( $g_3$ ) - given in inches
- (60)  $C_X$  REDUCTION FACTOR - Used in calculating conductor permeance and is dependent on the pitch and distribution factor. This factor can be obtained from Graph 1 with an assumed  $K_d$  of .955 or calculated as shown

$$C_X = \frac{(K_X)}{(K_P)^2 (K_d)^2} = \frac{(61)}{(44)^2 (43)^2}$$

- (61)  $K_X$  FACTOR TO ACCOUNT FOR DIFFERENCE in phase current in coil sides in same slot.

For  $60^\circ$  phase belt winding, i.e. when  $(42a) = 60$

$$K_X = 1/4 \left[ \frac{3(y)}{(m)(q)} + 1 \right] \text{ where } 2/3 \leq (y)/(m)(q) \leq 1.0$$

$$K_X = 1/4 \left[ \frac{3(31)}{(5)(25)} + 1 \right] \text{ where } 2/3 \leq (31a) \leq 1.0$$

or

$$K_X = 1/4 \left[ \frac{6(y)}{(m)(q)} - 1 \right] \text{ where } 1/2 \leq (31a) \leq 2/3$$

$$K_X = 1/4 \left[ \frac{6(31)}{(5)(25)} - 1 \right] \text{ where } 1/2 \leq (31a) \leq 2/3$$



For 120° phase belt winding, i.e. when (42a) = 120

$$K_X = .75 \text{ when } 2/3 \leq (y)/(m)(q)$$

$$K_X = .75 \text{ when } 2/3 \leq (3la)$$

or

$$K_X = .05 \left[ \frac{24(y)}{(m)(q)} - 1 \right] \text{ where } 1/2 \leq \frac{(y)}{(m)(q)} \leq 2/3$$

$$K_X = .05 \left[ \frac{24(3l)}{(3)(25)} - 1 \right] \text{ where } 1/2 \leq (3la) \leq 2/3$$

(62)  $\lambda_i$  CONDUCTOR PERMEANCE - The specific permeance for the portion of the stator current that is embedded in the iron. This permeance depends upon the configuration of the slot.

(a) For open slots

$$\lambda_i = (C_X) \frac{20}{(m)(q)} \left[ \frac{(h_2)}{(b_s)} + \frac{(h_1)}{3(b_s)} + \frac{(b_t)^2}{16(\tau_s)(g)} + \frac{.35(b_t)}{(\tau_s)} \right]$$

$$\lambda_i = (60) \frac{20}{(5)(25)} \left[ \frac{(22)}{(22)} + \frac{(22)}{3(22)} + \frac{(58)^2}{16(26)(59)} + \frac{.35(58)}{(26)} \right]$$

(b) For partially closed slots with constant slot width

$$\lambda_i = (C_X) \frac{20}{(m)(q)} \left[ \frac{(h_o)}{(b_o)} + \frac{2(h_t)}{(b_o) + (b_s)} + \frac{(h_w)}{(b_s)} + \frac{(h_1)}{3(b_s)} + \frac{(b_t)^2}{16(\tau_s)(g)} + \frac{.35(b_t)}{(\tau_s)} \right]$$

$$\lambda_i = (60) \frac{20}{(5)(25)} \left[ \frac{(22)}{(22)} + \frac{2(22)}{(22) + (22)} + \frac{(22)}{(22)} + \frac{(22)}{3(22)} + \frac{(58)^2}{16(26)(59)} + \frac{.35(58)}{(26)} \right]$$

(c) For partially closed slots (tapered sides)

$$\lambda_i = (C_X) \frac{20}{(m)(q)} \left[ \frac{(h_o)}{(b_o)} + \frac{2(h_t)}{(b_o) + (b_1)} + \frac{2(h_w)}{(b_1)(b_2)} + \frac{(h_1)}{3(b_2)} + \frac{(b_t)^2}{16(\tau_s)(g)} + \frac{.35(b_t)}{(\tau_s)} \right]$$

$$\lambda_i = (60) \frac{20}{(5)(25)} \left[ \frac{(22)}{(22)} + \frac{2(22)}{(22) + (22)} + \frac{2(22)}{(22)(22)} + \frac{(22)}{3(22)} + \frac{(58)^2}{16(26)(59)} + \frac{.35(58)}{(26)} \right]$$

(d) For round slots

$$\lambda_i = (C_X) \frac{20}{(m)(q)} \left[ .62 + \frac{(h_o)}{(b_o)} \right]$$

$$\lambda_i = (60) \frac{20}{(5)(25)} \left[ .62 + \frac{(22)}{(22)} \right]$$

(e) For open slots with a winding of one conductor per slot

$$\lambda_i = (C_X) \frac{20}{(m)(q)} \left[ \frac{(h_2)}{(b_s)} + \frac{(h_1)}{3(b_s)} + .6 + \frac{(g)}{2(\tau_s)} + \frac{(\tau_s)}{4(g)} \right]$$

$$\lambda_i = (60) \frac{20}{(5)(25)} \left[ \frac{(22)}{(22)} + \frac{(22)}{3(22)} + .6 + \frac{(59)}{2(26)} + \frac{(26)}{4(59)} \right]$$

(63)

$K_E$

LEAKAGE REACTIVE FACTOR for end turn

$$K_E = \frac{\text{Calculated value } (L_E)}{\text{Value } (L_E) \text{ from Graph 1}} \quad (\text{For machines where } (11) > 8'')$$

where  $L_E = (48)$  and abscissa of Graph 1 =  $(\gamma)(\tau_s) = (31)(26)$

$$K_E = \sqrt{\frac{\text{Calculated value of } (L_E)}{\text{Value } (L_E) \text{ from Graph 1}}} \quad (\text{For machines where } (11) < 8'')$$

(64)

$\lambda_E$

END WINDING PERMEANCE - The specific permeance for the end extension portion of the stator winding

$$\lambda_E = \frac{6.28(K_s)}{(L)(K_d)^2} \left[ \frac{\phi_E L_E}{2n} \right] = \frac{6.28(63)}{(13)(43)^2} \left[ \frac{Q_E L_E}{2n} \right]$$

The term  $\left[ \frac{\phi_E L_E}{2n} \right]$  is obtained from Graph 1.

The symbols used in this (term) do not apply to those of this design manual. Reference information for the symbol origin is included on Graph 1.

(65) -- WEIGHT OF COPPER - the weight of stator copper in lbs.

$$\# \text{'s copper} = .321(n_s)(Q)(a_c)(\ell_t) = .321(30)(23)(46)(49)$$

(66) -- WEIGHT OF STATOR IRON - in lbs.

$$\begin{aligned} \# \text{'s iron} &= .283 \left\{ (b_{tm})(Q)(\ell_s)(h_s) + \pi (d) (h_c)(\ell_s) \right\} \\ &= .283 \left\{ (57)(23)(17)(22) + \pi (10a) (24)(17) \right\} \end{aligned}$$

(67)  $K_s$  CARTER COEFFICIENT

$$K_s = \frac{(\tau_s) [5(g) + (b_s)]}{(\tau_s) [5(g) + (b_s)] - (b_s)^2} \quad (\text{For open slots})$$

$$K_s = \frac{(26) [5(59) + (22)]}{(26) [5(59) + (22)] - (22)^2}$$

$$K_s = \frac{\tau_s [4.44(g) + .75(b_o)]}{\tau_s [4.44(g) + .75(b_o)] - (b_o)^2} \quad (\text{For partially closed slots})$$

$$K_s = \frac{(26) [4.44(59) + .75(22)]}{(26) [4.44(59) + .75(22)] - (22)^2}$$

(68)  $A_g$  MAIN AIR GAP AREA - The area of the gap surface at the stator bore

$$A_g = \frac{\pi}{4} \left[ (\text{O. D.})^2 - (\text{I. D.})^2 \right] = \frac{\pi}{4} \left[ (12)^2 - (11)^2 \right]$$

(69)  $g_e$  EFFECTIVE AIR GAP (MAIN)

$$g_e = (K_s)(g) = (67)(59)$$

- |       |          |   |
|-------|----------|---|
| (70)  | $A_{g2}$ | <p><u>AREA OF OUTER AUXILIARY AIR GAP (<math>g_2</math>)</u> - Calculate from layout. This gap must be uniform circumferentially with no saturated sections if parasitic losses in the gap surfaces are to be prevented.</p>  |
| (70a) | $A_{g3}$ | <p><u>AREA OF THE INNER AUXILIARY GAP (<math>g_3</math>)</u> - The same comment applies to <math>g_3</math> as to <math>g_2</math> above. Avoid discontinuity in the circumferential flux pattern.</p>  |
| (71)  | $C_1$    | <p><u>THE RATIO OF MAXIMUM FUNDAMENTAL</u> of the field form to the actual maximum of the field form.</p> <p>For pole heads with only one radius, <math>C_1</math> is obtained from Curve #4. The abscissa is "pole embrace" (<math>\alpha</math>) = (77). The graphical flux plotting method of determining <math>C_1</math> is explained in the section titled "Derivations" in the Appendix.</p> |
| (72)  | $C_W$    | <p><u>WINDING CONSTANT</u> - The ratio of the RMS line voltage for a full pitched winding to that which would be introduced in all the conductors in series if the density were uniform and equal to the Maximum value.</p>   |

$$C_W = \frac{(E)(C_1)(K_d)}{\sqrt{2}(E_{PH})(m)} \quad \frac{(3)(71)(43)}{\sqrt{2}(4)(5)}$$

Assuming  $K_d = .955$ , then  $C_W = .225 C_1$  for three phase delta machines and  $C_W = .390 C_1$  for three phase star machines.

(73)  $C_P$  POLE CONSTANT - The ratio of the average to the maximum value of the field form.  $C_P$  is obtained from Curve #4. Note the correction factor at the top of the curve.

(74)  $C_M$  DEMAGNETIZING FACTOR - direct axis.

$$C_M = \frac{(\infty)\pi + \sin[(\infty)\pi]}{4 \sin[(\infty)\pi/2]} = \frac{(77)\pi + \sin(77)}{4 \sin[(77)\pi/2]}$$

(75)  $C_q$  CROSS MAGNETIZING FACTOR - quadrature axis

$$C_q = \frac{1/2 \cos[(\infty)\pi/2] + (\infty)\pi - \sin[(\infty)\pi]}{4 \sin[(\infty)\pi/2]} \left. \vphantom{\frac{1/2 \cos[(\infty)\pi/2] + (\infty)\pi - \sin[(\infty)\pi]}{4 \sin[(\infty)\pi/2]}} \right\} \begin{array}{l} \text{valid for} \\ \text{concentric} \\ \text{poles.} \end{array}$$

$$= \frac{1/2 \cos[(77)\pi/2] + (77)\pi - \sin[(77)\pi]}{4 \sin[(77)\pi/2]}$$

$C_q$  can also be obtained from Curve 9.

(76) -- POLE DIMENSIONS LOCATIONS per Figure 2 b

$b_{p1}$  = minimum width of pole (usually at tip) measured at the edge of the stator toroid.

$b_{p2}$  = maximum width of pole (usually at entering edge) at edge of stator toroid.

$b_p$  = average width of pole

$$b_p = \frac{b_{p1} + b_{p2}}{2}$$

(79)


 $A_{po}$ AREA OF POLE AT ENTERING EDGE OF STATOR TOROID

(outer pole) - Obtain from layout.

(79a)


 $A_{pi}$ AREA OF POLE AT ENTERING EDGE OF STATOR TOROID

(inner pole) - Obtain from layout.



UNIFORM POLE WIDTH

FIGURE 2a



$$b_p = \frac{b_{p1} + b_{p2}}{2} = \text{EFFECTIVE WIDTH OF POLE}$$

FIGURE 2b




FIG 3






FIG 4

(80)

 $P_1$ POLE TIP TO ROTOR LEAKAGE PERMEANCE - Add the

leakage permeance from the inside pole to the outer flux ring and the outside pole to the shaft section. PER FIG 5

$$P_1 = \left[ \frac{\mu_{a1}}{\ell_1} + \frac{\mu_{a'1}}{\ell'_1} \right] \left[ \frac{P}{2} \right]$$

(81)

 $P_2$ SIDE LEAKAGE FROM POLE -TO-POLE

$$P_2 = \frac{\mu a}{\ell} \quad \text{PER FIG 5}$$

$a$  = area of leakage path between poles x poles

$\ell$  = median length of leakage path between a pair of poles

(82)

 $P_3$ LEAKAGE PERMEANCE FROM UNDERSIDE OF POLE TO ROTOR.

Add the leakage permeance from inner pole to outer flux ring and from outer pole to shaft. Multiply this sum by  $\frac{P}{2}$  PER FIG 6 & 7

$$P_3 = \left[ \frac{\mu_{a3}}{\ell_3} + \frac{\mu_{a'3}}{\ell'_3} \right] \frac{P}{2}$$




FIG 5




FIG 6





FIG 7

(83)

 $P_4$ 

LEAKAGE PERMEANCE FROM UNDERSIDE OF POLE  
TO UNDERSIDE OF POLE -

$$P_4 = \left[ \frac{\mu a_4}{l_4} \right] (P) \quad \text{PER FIG 8}$$



LEAKAGE FLUX FROM UNDERSIDE OF  
 POLE TO UNDERSIDE OF POLE,  $P_4$

FIG 8

(84)  $P_5$  LEAKAGE PERMEANCE THROUGH FIELD COIL

$$P_5 = \frac{\mu a_5}{l_5} \quad \text{PER FIG 7}$$

Where  $a_5 = \pi(d_c)(b_c) \text{ inches}^2$

Where  $b_c = \text{width of field coil}$

Where  $d_c = \text{field coil diameter}$

$$= \frac{\text{Coil O. D.} + \text{Coil I. D.}}{2} \text{ inches}$$

Where  $l_5 = \frac{\text{Coil O. D.} - \text{Coil I. D.}}{2} \text{ inches}$

$$\mu = 3.19$$

(86)  $P_7$  STATOR TO FLUX RING AND SHAFT LEAKAGE

PER FIG 7

(88)  $\phi_T$  TOTAL FLUX in Kilolines

$$\phi_T = \frac{6(E)10^6}{(C_W)(n_e)(RPM)} = \frac{6(3)10^6}{(72)(45)(17)}$$

(89)  $\phi_{l7}$  LEAKAGE FLUX FROM STATOR TO SHAFT AND OUTER FLUX RING

$$\begin{aligned} \phi_{l7} &= \frac{P_7 \left[ 2(F_T) + 2(F_c) + (F_{g2}) + (F_{g3}) + (F_{po}) + (F_{pi}) \right] \times 10^{-3}}{2} \\ &= (86) \left[ 2(97) + 2(98) + (123) + (120) + (104) + (104b) \right] \times 10^{-3} \end{aligned}$$




FIG 9



(91)	$B_t$	<p><u>TOOTH DENSITY</u> in Kilolines/in<sup>2</sup> - The flux density in the stator tooth at 1/3 of the distance from the minimum section.</p> $B_t = \frac{\phi_T}{(Q)(\ell_s)(b_t \text{ } 1/3)} = \frac{(88)}{(23)(17)(57a)}$
(92)	$\phi_P$	<p><u>FLUX PER POLE</u> in Kilolines</p> $\phi_P = \frac{(\phi_T)(CP)}{(P)} = \frac{(88)(73)}{(6)}$
(94)	$B_c$	<p><u>CORE DENSITY</u> in Kilolines/in<sup>2</sup> - The flux density in the stator core</p> $B_c = \frac{(\phi_P)}{2(h_c)(\ell_s)} = \frac{(92)}{2(24)(17)}$
(95)	$B_g$	<p><u>GAP DENSITY</u> in Kilolines/in<sup>2</sup> - The maximum flux density in the air gap</p> $B_g = \frac{(\phi_T)}{(A_g)} = \frac{(88)}{(68)}$
(96)	$F_g$	<p><u>AIR GAP AMPERE TURNS</u> - The field ampere turns per pole required to force flux across the air gap when operating at no load with rated voltage.</p> $F_g = \frac{(B_g)(g_e)}{3.19} \times 10^3 = \frac{(95)(69)}{3.19} \times 10^3$

(97)  $F_T$  STATOR TOOTH AMPERE TURNS

$$F_T = (h_s) \left[ \text{NI/inch at density } (B_t) \right]$$

$$= (22) \left[ \begin{array}{l} \text{look up on stator magnetization curve} \\ \text{given in (18) at density (91)} \end{array} \right]$$

(98)  $F_c$  STATOR CORE AMPERE TURNS

$$F_c = \frac{\pi(d)}{4(P)} \left[ \text{NI/inch at density } (B_c) \right]$$

$$F_c = \frac{\pi(10a)}{4(6)} \left[ \begin{array}{l} \text{Look up on stator magnetization curve} \\ \text{at density (94)} \end{array} \right]$$

(100)  $\phi_l$  LEAKAGE FLUX - at no load

$$\begin{aligned} \phi_l &= [(P_1)+(P_2)+(P_3)+(P_4)] [2(F_T)+2(F_c)+(F_{g2})+(F_{g3})] \times 10^{-3} \\ &= [(80)+(81)+(82)+(83)] [2(97)+2(98)+(123)+(120)] \times 10^{-3} \end{aligned}$$

(102)  $\phi_{pt}$  TOTAL FLUX PER POLE - at no load

$$\phi_{pt} = \phi_p + \frac{\phi_l}{P} = (92) + \frac{(100)}{(6)}$$

(103)  $B_{po}$  FLUX DENSITY IN OUTER POLE (NL)

$$B_{po} = \frac{(\phi_{pt})}{(a_{po})} = \frac{(102)}{(79)}$$

(104)  $F_{po}$  AMPERE TURN DROP THROUGH OUTER POLE @ N. L.

$$F_{po} = (\ell_{po}) \left[ \text{NI/inch at density } (B_{po}) \right]$$

$$= (104) \left[ \begin{array}{l} \text{Look up on pole magnetization curve} \\ \text{at density (103).} \end{array} \right]$$

Where  $\ell_{po}$  = length of outer pole.

(104a)  $B_{pi}$  FLUX DENSITY IN INNER POLE @ N. L.

$$B_{pi} = \frac{\phi_{pt}}{A_{pi}} = \frac{(102)}{(79a)}$$

(104b)  $F_{pi}$  AMPERE TURN DROP THROUGH THE INNER POLE @ N. L.

$$F_{pi} = (\ell_{pi}) \left[ \text{NI/inch at density } (B_{pi}) \right]$$

$$= (104b) \left[ \begin{array}{l} \text{Look up on pole magnetization curve at} \\ \text{density (104a)} \end{array} \right]$$

Where  $(\ell_{pi})$  = length of inner pole

(104c)  $\phi_r$  FLUX IN ROTATING OUTER FLUX RING AT NO LOAD

$$\phi_r = \phi_{g2} = \phi_{g3} = \phi_{sh}$$

$$= (108) = (110a) = (111)$$

(104d)  $B_r$  FLUX DENSITY IN ROTATING OUTER RING at no load

$$B_r = \frac{(\phi_r)}{(A_r)} = \frac{(104c)}{(104d)}$$

Where  $A_r$  = ring cross-section area adjacent to the  
outer pole ( $P_o$ )

(104e)  $F_r$  AMPERE TURN DROP IN RING at no load.

$$F_r = (\ell_r) \left[ \text{NI/inch at density } (B_r) \right]$$

$$= (104e) \left[ \begin{array}{l} \text{Look up on ring magnetization curve} \\ \text{at density (104d)} \end{array} \right]$$

Where  $\ell_4$  = length of ring

(108)  $\phi_{g2}$  FLUX IN AUXILIARY GAP at no load

$$\phi_{g2} = \phi_{g3} = \phi_r = \phi_{sh} = \phi_{pt} \frac{(P)}{2} + \phi_7$$

$$= 102 \frac{(6)}{2} + (89)$$

(111)  $\phi_{sh}$  FLUX IN SHAFT at no load

$$\phi_{sh} = \phi_{g2} = \phi_r = \phi_{g3}$$

$$= (108) = (104c) = (118a)$$

(112)	$A_{sh}$	<u>AREA OF SHAFT</u> (cross-sectional to flux)
(113)	$B_{sh}$	<u>FLUX DENSITY IN SHAFT</u> at no load  $B_{sh} = \frac{\phi_{sh}}{A_{sh}} = \frac{(111)}{(112)}$
(114)	$F_{sh}$	<u>AMPERE TURN DROP IN SHAFT</u> at no load  $F_{sh} = l_{sh} \left[ \text{NI/inch at density } (B_{sh}) \right]$ $= (114) \left[ \text{Look up on shaft magnetization curve} \right]$ $\text{at density } (113)$ <p>Where <math>l_{sh}</math> = effective length of shaft</p>
(118)	$\phi_5$	<u>LEAKAGE FLUX ACROSS THE FIELD COIL</u> in Kilolines  $\phi_{l5} = (P_5) \left[ (F_{g2}) + (F_{g3}) + 2(F_t) + 2(F_c) + (F_{po}) \right. \\ \left. + (F_{pi}) + (F_r) + (F_{sh}) \right] \times 10^{-3}$ $= (84) \left[ (123) + (120) + 2(97) + 2(98) + (104) \right. \\ \left. + (104b) + (104e) + (114) \right] \times 10^{-3}$
(118a)	$\phi_{g3}$	<u>FLUX IN AUXILIARY GAP</u> $g_3$  $\phi_{g3} = \phi_{g2} = (108)$
(119)	$B_{g3}$	<u>FLUX DENSITY IN AUXILIARY GAP</u> $g_3$  $B_{g3} = \frac{(\phi_{g3})}{(A_{g3})} = \frac{(118a)}{(70a)}$

(120)  $F_{g3}$  AMPERE TURN DROP ACROSS THE AUXILIARY AIR GAP  $g_3$

$$F_{g3} = \frac{(B_{g3})}{3.19} (g_3) \times 10^3 = \frac{(119)}{3.19} (59c) \times 10^3$$

(122)  $B_{g2}$  FLUX DENSITY IN AUXILIARY AIR GAP

$$B_{g2} = \frac{(\phi_{g2})}{(A_{g2})} = \frac{(108)}{(70)}$$

(123)  $F_{g2}$  AMPERE TURN DROP ACROSS AUXILIARY GAP ( $g_2$ )

$$F_{g2} = \frac{(B_{g2})(g_2)}{3.19} \times 10^3 = \frac{(122)(59a)}{3.19} \times 10^3$$

(126a)  $\phi_y$  FLUX IN YOKE

(126b)  $B_y$  YOKE DENSITY

$$B_y = \frac{(\phi_y)}{(A_y)} = \frac{(126a)}{(126b)}$$

Where  $a_y$  = yoke cross-sectional area

(126c)  $F_y$  AMPERE TURN DROP IN YOKE at no load

$$F_y = \ell_y \left[ \text{NI/inch at density } (B_y) \right]$$

$$= (126c) \left[ \begin{array}{l} \text{Look up on yoke magnetization curve} \\ \text{at density } (126b) \end{array} \right]$$

Where  $\ell_y$  = length of yoke

(127)	$F_{NL}$	<p><u>TOTAL AMPERE TURNS</u> at no load</p> $F_{NL} = [2(F_C) + 2(F_T) + (F_{PO}) + (F_{PI}) + (F_R) + (F_{SH}) + (F_{G2}) + (F_{G3}) + (F_Y)]$ $= 2(98) + 2(97) + (104) + (104b) + (104e) + (114) + (123) + (120) + (126c)$
(127a)	$I_{FNL}$	<p><u>FIELD CURRENT</u> - at no load</p> $I_{FNL} = (F_{NL}) / (N_F) = 127 / (146)$
(127b)	$E_{FNL}$	<p><u>FIELD VOLTS</u> - at no load. This calculation is made with cold field resistance at 20°C for no load condition.</p> $E_F = (I_{FNL})(R_f \text{ cold}) = (127a)(154)$
(127c)	$S_F$	<p><u>CURRENT DENSITY</u> - at no load. Amperes per square inch of field conductor.</p> $S_F = (I_{FNL}) / (a_{cf}) = (127) / (153)$
(128)	A	<p><u>AMPERE CONDUCTORS</u> per inch - The effective ampere conductors per inch of stator periphery. This factor indicates the "specific loading" of the machine. Its value will increase with the rating and size of the machine and also will increase with the number of poles. It will decrease with increases in voltage or frequency. A is generally higher in single phase machines than in polyphase ones.</p> $A = \frac{(I_{PH})(n_s)(K_P)}{(C)(\gamma_s)} = \frac{(8)(30)(44)}{(32)(26)}$

(129) X

REACTANCE FACTOR - The reactance factor is the quantity by which the specific permeance must be multiplied to give percent reactance. It is the percent reactance for unit specific permeance, or the percent of normal voltage induced by a fundamental flux per pole per inch numerically equal to the fundamental armature ampere turns at rated current. Specific permeance is defined as the average flux per pole per inch of core length produced by unit ampere turns per pole.

$$X = \frac{100(A)(K_d)}{\sqrt{2} (C_1)(B_g) \times 10^3} = \frac{100 (128)(43)}{\sqrt{2} (71) (95) \times 10^3}$$

(130)  $X_L$ 

LEAKAGE REACTANCE - The leakage reactance of the stator for steady state conditions. When (5) = 3, calculate as follows:

$$X_L = X[(\lambda_i) + (\lambda_E)] = (79)[(62) + (64)]$$

In the case of two phase machines a component due to belt leakage must be included in the stator leakage reactance. This component is due to the harmonics caused by the concentration of the MMF into a small number of phase belts per pole and is negligible for three phase machines. When (5) = 2, calculate as follows:

$$\lambda_B = \frac{0.1(d)}{(P)(g_e)} \left[ \frac{\sin \left[ \frac{3(y)}{(m)(q)} \right] 90^\circ}{(K_P)} \right] = \frac{0.1(11)}{(6)(69)} \left[ \frac{\sin \left[ \frac{3(31)}{(5)(25)} \right] 90^\circ}{(44)} \right]$$

$$X_L = X[(\lambda_i) + (\lambda_E) + (\lambda_B)] \text{ where } \lambda_B = 0 \text{ for 3 phase machines.}$$

$$X_L = (79)[(62) + (64) + (80)]$$



(131)	$X_{ad}$	<p><u>REACTANCE</u> - direct axis - This is the fictitious reactance due to armature reaction in the direct axis.</p> $X_{ad} = (X)(\lambda_a)(C_1)(C_M) = (129)(70)(71)(74)$
(132)	$X_{aq}$	<p><u>REACTANCE</u> - quadrature axis - This is the fictitious reactance due to armature reaction in the quad. axis.</p> $X_{aq} = (X)(C_q)(\lambda_a) = (129)(75)(70)$
(133)	$X_d$	<p><u>SYNCHRONOUS REACTANCE</u> - direct axis - The steady state short circuit reactance in the direct axis.</p> $X_d = (X_\rho) + (X_{ad}) = (130) + (131)$
(134)	$X_q$	<p><u>SYNCHRONOUS REACTANCE</u> - quadrature axis - The steady state short circuit reactance in the quadrature axis.</p> $X_q = (X_\rho) + (X_{aq}) = (130) + (132)$
(145)	$V_r$	<p><u>PERIPHERAL SPEED</u> - The velocity of the rotor surface in feet per minute</p> $V_r = \frac{\pi(d_r)(RPM)}{12} = \frac{\pi(11a)(7)}{12}$
(146)	$N_F$	<u>NUMBER OF FIELD TURNS</u>
(147)	$\ell_{tF}$	<u>MEAN LENGTH OF FIELD TURN</u>
(148)	--	<u>FIELD CONDUCTOR DIA OR WIDTH</u> in inches
(149)	--	<u>FIELD CONDUCTOR THICKNESS</u> in inches - Set this item = 0. for round conductor.

(150)  $X_f^{\circ C}$  FIELD TEMP IN  $^{\circ}C$  - Input temp at which full load field loss is to be calculated.

(151)  $\rho_f$  RESISTIVITY of field conductor @  $20^{\circ}C$  in micro ohm-inches.  
Refer to table given in item (51) for conversion factors.

(152)  $\rho_{f \text{ (hot)}}$  RESISTIVITY of field conductor at  $X_f^{\circ}C$

$$\rho_{f \text{ (hot)}} = \rho_f \left[ \frac{(X_f^{\circ}C) + 234.5}{254.5} \right] = (104) \left[ \frac{(150) + 234.5}{254.5} \right]$$

(153)  $a_{cf}$  CONDUCTOR AREA OF FIELD WINDING - Calculate same as stator conductor area (46) except substitute

(149) for (39)

(148) for (33)

(154)  $R_f \text{ (cold)}$  COLD FIELD RESISTANCE @  $20^{\circ}C$

$$R_f \text{ (cold)} = (\rho_f) \frac{(N_f) (\ell_{tf})}{(a_{cf})} = (151) \frac{(146) (147)}{(153)}$$

(155)  $R_f \text{ (hot)}$  HOT FIELD RESISTANCE - Calculated at  $X_f^{\circ}C$  (103)

$$R_f \text{ (hot)} = (\rho_{f \text{ hot}}) \frac{(N_f) (\ell_{tf})}{(a_{cf})} = (152) \frac{(146) (147)}{(153)}$$

(156) -- WEIGHT OF FIELD COIL in lbs.

$$\#s \text{ of copper} = .321(N_f)(\ell_{tf})(a_{cf})$$

$$= .321(146)(6)(147)(153)$$

(157) --

WEIGHT OF ROTOR IRON - Because of the large number of different pole shapes, one standard formula cannot be used for calculating rotor iron weight. Therefore, the computer will not calculate rotor iron weight. The space is allowed on the input sheet for record purposes only. By inserting 0. in the space allowed for rotor iron weight, the computer will show "0". on the output sheet. If the rotor iron weight is available and inserted on input sheet, then the output sheet will show this same weight on the output sheet.

(160)  $X_F$ FIELD LEAKAGE REACTANCE

$$X_F = (X_{ad}) \left[ 1 - \frac{\frac{[(C_1)/(C_m)]}{2(C_p) + \frac{4(\lambda_F)}{\pi(\lambda_a)}}}{\pi(\lambda_a)} \right]$$

$$= (81) \left[ 1 - \frac{\frac{[(71)/(74)]}{2(73) + \frac{4(160c)}{\pi(70)}}}{\pi(70)} \right]$$

(160a)  $P_e$ ROTOR LEAKAGE PERMEANCE

$$P_e = P [P_1 + P_2 + P_3 + P_4] + P_5$$

$$= (6) [(80) + (81) + (82) + (83)] + (84)$$

(160c)  $\lambda_F$ ROTOR LEAKAGE PERMEANCE per inch of stator stack

$$\lambda_F = \frac{P_e}{\ell} = \frac{(160a)}{(13)}$$

(161)  $L_f$ FIELD SELF INDUCTANCE

$$L_f = (N_f)^2 (\ell_p) \left[ (C_P)(\lambda_a) \frac{\pi}{2} + (\lambda_f) \right] \times 10^{-8}$$

$$= (99)^2 (76) \left[ (73)(70) \frac{\pi}{2} + (160c) \right] \times 10^{-8}$$

(166)  $X'_{du}$  UNSATURATED TRANSIENT REACTANCE

$$X'_{du} = (X'_d) + (X'_f) = (130) + (160)$$

(167)  $X'_d$  SATURATED TRANSIENT REACTANCE

$$X'_d = .88(X'_{du}) = .88(166)$$

(168)  $X''_d$  SUBTRANSIENT REACTANCE in direct axis

$$X''_d = (X'_d) = (167)$$

(169)  $X''_q$  SUBTRANSIENT REACTANCE in quadrature axis

$$X''_q = (X_q) = (134)$$

(170)  $X_2$  NEGATIVE SEQUENCE REACTANCE - The reactance due to the field which rotates at synchronous speed in a direction opposite to that of the rotor.

$$X_2 = .5 [X''_d + X''_q] = .5 [(168) + (169)]$$

(172)  $X_0$  ZERO SEQUENCE REACTANCE - The reactance drop across any one phase (star connected) for unit current in each of the phases. The machine must be star connected for otherwise no zero sequence current can flow and the term then has no significance.

If (28) = 0, then  $X_0 = 0$

If (28)  $\neq$  0, then

$$X_o = X \left\{ \frac{(K_{xo})}{(K_{x1})} [(\lambda_i) + (\lambda_{Bo})] + \frac{1.667 [(h_1) + 3(h_3)]}{(m)(q)(K_p)^2 (K_d)^2 (b_s)} + .2(\lambda_F) \right.$$

$$= (79) \left\{ \frac{(173)}{(174)} [(62) + (123c)] + \frac{1.667 [(22) + 3(22)]}{(5)(25)(44)^2 (43)^2 (22)} + .2 \right.$$

(173)  $K_{xo}$ If (30) = 1 Then  $K_{xo} = 1$ 

$$\text{If (30) } \neq 1 \quad \text{Then } K_{xo} = \frac{3(\gamma)}{(m)(q)} - 2$$

$$= \frac{3(31)}{(5)(25)} - 2$$

(174)  $K_{x1}$ If (30) = 1 Then  $K_{x1} = 1$ If (30)  $\neq 1$  Then:

$$K_{x1} = \left[ \frac{3(\gamma)}{4(m)(q)} + \frac{1}{4} \right] = \left[ \frac{3(31)}{4(5)(25)} + \frac{1}{4} \right] \quad \text{If (31a)} \geq .667$$

$$K_{x1} = \left[ \frac{3(\gamma)}{4(m)(q)} - \frac{1}{4} \right] = \left[ \frac{3(31)}{4(5)(25)} - \frac{1}{4} \right] \quad \text{If (31a)} < .667$$

(175)  $\lambda_{Bo}$ 

$$\lambda_{Bo} = \frac{(K_{xo})}{(K_p)^2} [ .07(\lambda_a) ] = \frac{(173)}{(44)^2} [ .07(70) ]$$

(176)  $T'_{do}$ 

OPEN CIRCUIT TIME CONSTANT - The time constant of the field winding with the stator open circuited and with negligible external resistance and inductance in the field circuit. Field Resistance at room temperature (20°C) is used in this calculation.

$$T'_{do} = \frac{L_F}{R_F} = \frac{(161)}{(154)}$$

(177)  $T_a$ 

ARMATURE TIME CONSTANT - Time constant of the D.C. component. In this calculation stator resistance at room temperature (20°C) is used.

$$T_a = \frac{X_2}{200\pi(f)(r_a)} = \frac{(170)}{200\pi(5a)(177)}$$

Where  $r_a = \frac{(m)(I_{PH})^2(R_{SPH \text{ cold}})}{\text{Rated KVA} \times 10^3} = \frac{(5)(8)^2(53)}{(2) \times 10^3}$

(178)  $T'_d$ 

TRANSIENT TIME CONSTANT - The time constant of the transient reactance component of the alternating wave.

$$T'_d = \frac{(X'_d)}{(X_d)} (T'_{do}) = \frac{(167)}{(133)} (176)$$

(179)  $T''_d$ 

SUBTRANSIENT TIME CONSTANT - The time constant of the subtransient component of the alternating wave.

This value has been determined empirically from tests on large machines. Use following values:

$$T''_d = .035 \text{ second at 60 cycle}$$

$$T''_d = .005 \text{ second at 400 cycle}$$

(180)  $F_{SC}$ 

SHORT CIRCUIT AMPERE TURNS - The field ampere turns required to circulate rated stator current when the stator is short circuited.

$$F_{SC} = (X_d)(F_g) = (133)(96)$$

- |       |          |  |
|-------|----------|--|
| (181) | SCR      | <p><u>SHORT CIRCUIT RATIO</u> - The ratio of the field current to produce rated voltage on open circuit to the field current required to produce rated current on short circuit. Since the voltage regulation depends on the leakage reactance and the armature reaction, it is closely related to the current which the machine produces under short circuit conditions and, therefore, is directly related to the SCR.</p> $\text{SCR} = (F_{NL})/(F_{SC}) = (127)/(180)$  |
| (182) | $I^2R_F$ | <p><u>FIELD <math>I^2R</math></u> - at no load. The copper loss in the field winding is calculated with cold field resistance at 20°C for no load condition.</p> $\text{Field } I^2R = (I_{FNL})^2 (R_f \text{ cold}) = (127a)^2 (154)$  |
| (183) | F&W      | <p><u>FRICTION &amp; WINDAGE LOSS</u> - The best results are obtained by using existing data. For ratioing purposes, the loss can be assumed to vary approximately as the 5/2 power of the rotor diameter and as the 3/2 power of the RPM. When no existing data is available, the following calculation can be used for an approximate answer. Insert 0. when computer is to calculate F&amp;W. Insert actual F&amp;W when available. Use same value for all load conditions.</p> $\begin{aligned} \text{F\&W} &= 2.52 \times 10^{-6} (d_r)^{2.5} (\ell_p) (\text{RPM})^{1.5} \\ &= 2.52 \times 10^{-6} (11a)^{2.5} (76) (7)^{1.5} \end{aligned}$ |

(184)  $W_{TNL}$ STATOR TEETH LOSS - at no load. The no load loss

( $W_{TNL}$ ) consists of eddy current and hysteresis losses in the iron. For a given frequency the no load tooth loss will vary as the square of the flux density.

$$W_{TNL} = .453(b_t^{1/3})(Q)(\ell_s)(h_s)(K_Q)$$

$$= .453(57a)(23)(17)(22)(184)$$

$$\text{Where } K_Q = (k) \left[ \frac{(B_t)}{(B)} \right]^2 = (19) \left[ \frac{(91)}{(20)} \right]^2$$

(185)  $W_C$ STATOR CORE LOSS - The stator core losses are due to

eddy currents and hysteresis and do not change under load conditions. For a given frequency the core loss will vary as the square of the flux density ( $B_C$ ).

$$W_C = 1.42 \left[ (D) - (h_c) \right] (h_c)(\ell_s)(K_Q)$$

$$= 1.42 \left[ (12) - (24) \right] (24)(17)(185)$$

$$\text{Where } K_Q = (k) \left[ \frac{(B_C)}{(B)} \right]^2 = (19) \left[ \frac{(94)}{(20)} \right]^2$$

(186)  $W_{NPL}$ POLE FACE LOSS - at no load. The pole surface losses are

due to slot ripple caused by the stator slots. They depend upon the width of the stator slot opening, the air gap, and the stator slot ripple frequency. The no load pole face loss ( $W_{PNL}$ ) can be obtained from Graph 2. Graph 2 is plotted on the bases of open



slots. In order to apply this curve to partially open slots, substitute  $b_0$  for  $b_s$ . For a better understanding of Graph 2, use the following sample:

$K_1$  is given on Graph 2 is derived empirically and depends on laminar material and thickness. Those values given on Graph 2 have been used with success.  $K_1$  is an input and must be specified. See Item (187) for values of  $K_1$ .

$K_2$  is shown as being plotted as a function of  $(B_G)^{2.5}$ . Also note that upper scale is to be used. Another note in the lower right hand corner of graph indicates that for a solid line (\_\_\_\_), the factor is read from the left scale, and for a broken or dashed line (\_\_\_\_ \_), the right scale should be read. For example, find  $K_2$  when  $B_G = 30$  kilolines. First locate 30 on upper scale. Read down to the intersection of solid line plot of  $K_2 = f(B_G)^{2.5}$ . At this intersection read the left scale for  $K_2$ .  $K_2 = .28$ . Also refer to Item (188) for  $K_2$  calculations.

$K_3$  is shown as a solid line plot as a function of  $(F_{SLT})^{1.65}$ . The note on this plot indicates that the upper scale X 10 should be used. Note  $F_{SLT}$  = slot frequency. For an example, find  $K_3$  when  $F_{SLT} = 1000$ . Use upper scale X 10 to locate 1000. Read down to intersection of solid line plot of  $K_3 = f(F_{SLT})^{1.65}$ . At this intersection read the left scale

for  $K_3$ .  $K_3 = 1.35$ . Also refer to Item (189) for  $K_3$  calculations.

For  $K_4$  use same procedure as outlined above except use lower scale. Do not confuse the dashed line in this plot with the note to use the right scale. The note does not apply in this case. Read left scale. Also refer to Item (190) for  $K_4$  calculations.

For  $K_5$  use bottom scale and substitute  $b_0$  for  $b_s$  when using partially closed slot. Read left scale when using solid plot. Use right scale when using dashed plot. Also refer to Item (191) for  $K_5$  calculations.

For  $K_6$  use the scale attached for  $C_1$  and read  $K_6$  from left scale. Also refer to Item (192) for  $K_6$  calculations.

The above factors ( $K_2$ ), ( $K_3$ ), ( $K_4$ ), ( $K_5$ ), ( $K_6$ ) can also be calculated as shown in (188), (189), (190), (191), (192) respectively.

$$W_{PNL} = \pi(d)(K_1)(K_2)(K_3)(K_4)(K_5)(K_6)$$

$$= \pi(11)(13)(187)(188)(189)(180)(199)(192)$$

(187)  $K_1$

$K_1$  is derived empirically and depends on lamination material and thickness. The values used successfully for  $K_1$  are shown on Graph 2. They are:

$K_1 = 1.17$  for .028 lam thickness, low carbon steel  
 $= 1.75$  for .063 lam thickness, low carbon steel  
 $= 3.5$  for .125 lam thickness, low carbon steel  
 $= 7.0$  for solid core

$K_1$  is an input and must be specified on input sheet.

(188)  $K_2$

$K_2$  can be obtained from Graph 2 (see Item 186 for explanation of Graph 2) or it can be calculated as follows:

$$\begin{aligned}
 K_2 &= f(B_G) = 6.1 \times 10^{-5} (B_G)^{2.5} \\
 &= 6.1 \times 10^{-5} (95)^{2.5}
 \end{aligned}$$

(189)  $K_3$

$K_3$  can be obtained from Graph 2 (see Item 186 for explanation of Graph 2) or it can be calculated as follows:

$$\begin{aligned}
 K_3 &= f(F_{SLT}) = 1.5147 \times 10^{-5} (F_{SLT})^{1.65} \\
 &= 1.5147 \times 10^{-5} (189)^{1.65}
 \end{aligned}$$

$$\text{Where } F_{SLT} = \frac{(RPM)}{60} (Q)$$

$$= \frac{(7)}{60} (23)$$

(190)  $K_4$

$K_4$  can be obtained from Graph 2 (see Item 186 for explanation of Graph 2) or it can be calculated as follows:

For  $\gamma_s \leq .9$

$$\begin{aligned}
 K_4 &= f(\gamma_s) = .81(\gamma_s)^{1.285} \\
 &= .81(26)^{1.285}
 \end{aligned}$$

For  $.9 \leq \gamma_s \leq 2.0$

$$\begin{aligned} K_4 &= f(\gamma_s) = .79(\gamma_s)^{1.145} \\ &= .79(26)^{1.145} \end{aligned}$$

For  $\gamma_s > 2.0$

$$\begin{aligned} K_4 &= f(\gamma_s) = .92(\gamma_s)^{.79} \\ &= .92(26)^{.79} \end{aligned}$$

(191)  $K_5$

$K_5$  can be obtained from Graph 2 (see item 186 for explanation of Graph 2) or it can be calculated as follows:

For  $(b_s)/(g) = 1.7$

$$\begin{aligned} K_5 &= f(b_s/g) = .3 \left[ (b_s)/(g) \right]^{2.31} \\ &= .3 \left[ (22)/(59) \right]^{2.31} \end{aligned}$$

NOTE: For partially open slots substitute  $b_o$  for  $b_s$  in equations shown.

For  $1.7 < (b_s)/(g) \leq 3$

$$\begin{aligned} K_5 &= f(b_s)/(g) = .35 \left[ (b_s)/(g) \right]^2 \\ &= .35 \left[ (22)/(59) \right]^2 \end{aligned}$$

For  $3 < (b_s)/(g) \leq 5$

$$\begin{aligned} K_5 &= f(b_s)/(g) = .625 \left[ (b_s)/(g) \right]^{1.4} \\ &= .625 \left[ (22)/(59) \right]^{1.4} \end{aligned}$$

For  $(b_s)/(g) > 5$

$$K_5 = f(b_s)/(g) = 1.38 \left[ (b_s)/(g) \right]^{.965}$$

$$= 1.38 \left[ (22)/(59) \right]^{.965}$$

- (192)  $K_6$   $K_6$  can be obtained from Graph 2 (see Item 186 for explanation of Graph 2) or it can be calculated as follows:

$$K_6 = f(C_1) = 10 \left[ .9323(C_1) - 1.60596 \right]$$

$$= 10 \left[ .9323(71) - 1.60596 \right]$$

- (194)  $I^2R$  STATOR  $I^2R$  - at no load. This item = 0. Refer to Item (245) for 100% load stator  $I^2R$ .

- (195) -- EDDY LOSS - at no load. This item = 0. Refer to Item (246) for 100% load eddy loss.

- (196) -- TOTAL LOSSES - at no load. Sum of all losses.
- Total losses = (Field  $I^2R$ ) + (F&W) + (Stator Teeth Loss)  
 + (Stator Core Loss) + (Pole Face Loss)
- = (182) + (183) + (184) + (185) + (186)

NOTE: The output sheet shows the next items to be:  
 (Rating), (Rating + Losses), (% Losses),  
 (% Efficiency). These items do not apply to  
 the no load calculation since the rating is  
 zero. Refer to Items (175), (176), (177), (178)  
 for these calculations under load.

The no load calculations should all be repeated now  
 for 100% load.

- (196a)  $\phi_{\ell\ell}$  <sup>ROTOR</sup> LEAKAGE FLUX PER POLE at 100% load
- $$\phi_{\ell\ell} = \phi_{\ell} \left\{ \frac{(e_d)(F_g) + [1 + \cos(\theta)](F_T) + (F_C)}{(F_g) + (F_T) + (F_C)} \right\}$$
- $$= (100) \left\{ \frac{(198)(96) + [1 + \cos(198a)](97) + (98)}{(96) + (97) + (98)} \right\}$$
- (198)  $e_d$  Where  $e_d = \cos \epsilon + (X_d) \sin \Psi$
- $$= \cos(198a) + (83) \sin(198b)$$
- (198a)  $\theta$  Where  $\theta = \cos^{-1} [(\text{Power Factor})]$
- $$= \cos^{-1} [(9)]$$
- Where  $\Psi = \tan^{-1} \left[ \frac{\sin(\theta) + (X_q) / (100)}{\cos(\theta)} \right]$
- $$= \tan^{-1} \left[ \frac{\sin(198a) + (134) / (100)}{\cos(198a)} \right]$$
- Where  $\epsilon = \Psi - \theta = (198a) - (198a)$
- (207)  $\phi_{7L}$  STATOR TO ROTOR FLUX LEAKAGE at full load
- $$\phi_{7L} = \frac{P_7 [2(F_C) + 2(F_T) [1 + \cos(\theta)] + (F_{g2L}) + (F_{g3L}) + (F_{p0L}) + (F_{piL})]}{2} \times 10^{-3}$$
- $$= \frac{(86) [2(98) + 2(97) [1 + \cos(198a)] + (225) + (231) + (222a) + (222c)]}{2} \times 10^{-3}$$
- (213)  $\phi_{PL}$  FLUX PER POLE at 100% load
- For P. F. 0 to .95
- $$\phi_{PL} = (\phi_P) \left[ (e_d) - \frac{.93(X_{ad})}{100} \sin(\Psi) \right]$$
- $$= (92) \left[ (198a) - \frac{.93(131)}{100} \sin(198a) \right]$$

For P. F. .95 to 1.0

$$\phi_{PL} = (\phi_P)(K_C) = (126)(9a)$$

(213a)  $\phi_{PTL}$  TOTAL FLUX PER POLE at 100% load

$$\phi_{PTL} = \phi_{PL} + \frac{\phi_{21}}{P} = (213) + \frac{(196a)}{(6)}$$

(221)  $\phi_{g2L}$  AUXILIARY GAP ( $g_2$ ) FLUX

$$\begin{aligned}\phi_{g2L} &= (\phi_{g3L}) = (\phi_{rL}) = (\phi_{shL}) = (\phi_{pL}) \frac{P}{2} + (\phi_{7L}) \\ &= (213) \frac{(6)}{2} + (207)\end{aligned}$$

(222)  $B_{poL}$  FLUX DENSITY IN OUTER POLE at full load

$$B_{po} = \frac{\phi_{PTL}}{A_{po}} = \frac{(213a)}{(79)}$$

(222a)  $F_{poL}$  AMPERE TURN DROP THROUGH OUTER POLE at full load

$$\begin{aligned}F_{poL} &= (\ell_{po}) \left[ \text{NI/inch at density } (B_{poL}) \right] \\ &= (104) \left[ \begin{array}{l} \text{Look up on pole magnetization curve} \\ \text{at density (222)} \end{array} \right]\end{aligned}$$

(222b)  $B_{piL}$  FLUX DENSITY IN INNER POLE at full load

$$B_{pi} = \frac{\phi_{PTL}}{A_{pi}} = \frac{(213a)}{(79a)}$$

(222c)  $F_{piL}$  AMPERE TURN DROP THROUGH INNER POLE at full load

$$F_{piL} = l_{pi} \left[ \text{NI/inch at density } (B_{piL}) \right]$$

$$= (104b) \left[ \begin{array}{l} \text{Look up on pole magnetization curve at} \\ \text{density (222b)} \end{array} \right]$$

(222d)  $B_{rL}$  FLUX DENSITY IN ROTATING OUTER RING at no load

$$B_{rL} = \frac{\phi_{rL}}{A_r} = \frac{(221)}{(104d)}$$

(222e)  $F_{rL}$  AMPERE TURN DROP IN RING at full load

$$F_{rL} = (l_r) \left[ \text{NI/inch at density } (B_r) \right]$$

$$= (104e) \left[ \begin{array}{l} \text{Look up on ring magnetization curve at} \\ \text{density (222d)} \end{array} \right]$$

(224)  $B_{g2L}$  FLUX DENSITY IN AUXILIARY GAP under load

$$B_{g2L} = \frac{\phi_{g2L}}{A_{g2}} = \frac{(221)}{(70)}$$

(225)  $F_{g2L}$  AMPERE TURN DROP IN AUXILIARY GAP ( $g_2$ )

$$F_{g2L} = \frac{(B_{g2L})}{3.19} (g_2) \times 10^3$$

$$= \frac{(224)}{3.19} (59a) \times 10^3$$



(226)  $\phi_{5L}$ LEAKAGE ACROSS FIELD COIL

$$\phi_{5L} = P_5 \left[ 2(F_c) + 2(F_T) \left[ 1 + \cos(\theta) \right] (F_{g2}) + (F_{g3}) + (F_{poL}) + (F_{piL}) \right. \\ \left. + (F_{rL}) + (F_{shL}) \right] \times 10^{-3}$$

$$= (84) \left[ 2(98) + 2(97) \left[ 1 + \cos(198a) \right] + (225) + (231) + (222a) + (222c) \right. \\ \left. + (222e) + (233) + (229c) \right] \times 10^{-3}$$

(229a)  $\phi_{yL}$ FLUX IN YOKE BACK OF COIL at full load(229b)  $B_{yL}$ FLUX DENSITY IN YOKE BACK OF COIL at full load

$$B_y = \frac{(\phi_y)}{(A_y)} = \frac{(227a)}{(126b)}$$

(229c)  $F_{yL}$ AMPERE TURN DROP IN YOKE at full load

$$F_{yL} = l_y \left[ \text{NI/inch at density } (B_{yL}) \right]$$

$$= (123c) \left[ \text{Look up on yoke magnetization curve} \right. \\ \left. \text{at density } (229b) \right]$$

(230)  $B_{g3L}$ GAP DENSITY IN AUXILIARY GAP ( $g_3$ ) at full load

$$B_{g3L} = \frac{(\phi_{g3L})}{(A_{g3})} = \frac{(221)}{(70a)}$$

(231)  $F_{g3L}$ AMPERE TURN DROP ACROSS GAP at full load

$$F_{g3} = \frac{(B_{g3L})}{3.19} (g_3) \times 10^3$$

$$= \frac{(230)}{3.19} (59c) \times 10^3$$

(232)  $B_{shL}$  SHAFT DENSITY at full load

$$B_{shL} = \frac{(\phi_{shL})}{(A_{sh})} = \frac{(221)}{(112)}$$

(233)  $F_{shL}$  SHAFT AMPERE TURN DROP

$$F_{shL} = (l_{sh}) \left[ \text{NI/inch at density } (B_{sh}) \right]$$

$$= (114) \left[ \begin{array}{l} \text{Look up on shaft magnetization curve} \\ \text{at density (232)} \end{array} \right]$$

(236)  $F_{FL}$  TOTAL AMPERE TURNS at full load

$$\begin{aligned} F_{FL} &= 2(F_C) + 2(F_T) \left[ 1 + \cos(\theta) \right] + (F_{g2L}) + (F_{g3L}) + (F_{poL}) + (F_{piL}) \\ &\quad + (F_{rL}) + (F_{shL}) + (F_{yL}) \\ &= 2(98) + 2(97) \left[ 1 + \cos(198a) \right] + (225) + (231) + (222a) + (222c) \\ &\quad + (222e) + (233) + (229c) \end{aligned}$$

(237)	$I_{FFL}$	<p><u>FIELD CURRENT</u> at 100% load</p> $I_{FFL} = (F_{FL})/(N_F) = (236)/(146)$
(239)	--	<p><u>CURRENT DENSITY</u> at 100% load</p> $\text{Current Density} = (I_{FFL})/(a_{cf}) = (237)/(153)$
(238)	$E_{FFL}$	<p><u>FIELD VOLTS</u> at 100% load - This calculation is made with hot field resistance at expected temperature at 100% load.</p> $\text{Field Volts} = (I_{FFL})(R_f \text{ hot}) = (237)(155)$
(241)	$I^2R_{FL}$	<p><u>FIELD <math>I^2R</math></u> at 100% load - The copper loss in the field winding is calculated with hot field resistance at expected temperature for 100% load condition.</p> $\text{Field } I^2R = (I_{FFL})^2(R_f \text{ hot}) = (237)^2(155)$
(242)	$W_{TFL}$	<p><u>STATOR TEETH LOSS</u> at 100% load - The stator tooth loss under load increases over that of no load because of the parasitic fluxes caused by the ripple due to the rotor damper bar slot openings.</p> $W_{TFL} = \left\{ 2 \left[ .27 \left( \frac{X_d}{100} \right) \left( \frac{\% \text{ Load}}{100} \right) \right]^{1.8} + 1 \right\} (W_{TNL})$ $= \left\{ 2 \left[ .27 \left( \frac{133}{100} \right) 1 \right]^{1.8} + 1 \right\} (148)$

(243)  $W_{PFL}$  POLE FACE LOSS at 100% load

$$W_{PFL} = \left\{ \left[ \frac{(K_{SC})(I_{PH}) \frac{(\% \text{ Load})}{100} (n_s)}{(C)(F_g)} \right]^2 + 1 \right\} (W_{PNL})$$

$$= \left\{ \left[ \frac{(242)(8) 1 (30)}{(32)(96)} \right]^2 + 1 \right\} (186)$$

$(K_{SC})$  is obtained from Graph 3

(245)  $I^2 R_L$  STATOR  $I^2 R$  at 100% load - The copper loss based on the D.C resistance of the winding. Calculate at the maximum expected operating temperature.

$$I^2 R = (m)(I_{PH})^2 (R_{SPH \text{ hot}}) \frac{(\% \text{ Load})}{100}$$

$$= (5)(8)^2 (54) 1$$

(246) -- EDDY LOSS - Stator  $I^2 R$  loss due to skin effect

$$\text{Eddy Loss} = \left[ \frac{(EF \text{ top}) + (EF \text{ bot})}{2} - 1 \right] (\text{Stator } I^2 R)$$

$$= \left[ \frac{(55) - (56)}{2} - 1 \right] (245)$$

(247) -- TOTAL LOSSES at 100% load - sum of all losses at 100% load

$$\begin{aligned} \text{Total Losses} &= (\text{Field } I^2 R) + (F\&W) + (\text{Stator Teeth Loss}) \\ &\quad + (\text{Stator Core Loss}) + (\text{Pole Face Loss}) \\ &\quad + (\text{Stator } I^2 R) + (\text{Eddy Loss}) \\ &= (241) + (183) + (242) + (185) + (243) + (245) + (246) \end{aligned}$$

(248) -- RATING IN KILOWATTS at 100% load

$$\text{Rating} = 3(E_{PH})(I_{PH}) - (P.F.) \frac{(\% \text{ Load})}{100} \times 10^{-3}$$

$$= 3(4)(8) \quad (9)(1.) \times 10^{-3}$$

(249) -- RATING AND LOSSES = (248) + (247)  $\times 10^{-3}$

$$\begin{aligned} \% \text{ LOSSES} &= \left[ \frac{\text{LOSSES} \times 10^{-3}}{\text{Rating} + \text{LOSSES}} \right] 100 \\ &= \left[ \frac{(247) \times 10^{-3}}{249} \right] 100 \end{aligned}$$

$$\begin{aligned} (251) \quad \% \text{ EFFICIENCY} &= 100\% - \% \text{ Losses} \\ &= 100\% - (250) \end{aligned}$$

These items can be recalculated for any load condition by simply inserting the values that correspond to the % load being calculated. The factor  $\frac{(\% \text{ Load})}{100}$  takes care of  $(I_{PH})$  as it changes with load.

Note that values for F&W (183) and  $W_C$  (Stator Core Loss) (185) do not change with load, therefore, they can be calculated only once.

## AXIAL AIR GAP LUNDELL GENERATORS

Axial air gap synchronous generators have definite design limits that allow the prediction of generator output from stator O.D. and RPM.

### Discussion

When the axial air gap machine is worked to definite limits of current loading and air gap density, simply specifying the speed and the KVA output determines the diameter of the stator.

To determine the size of a specific type of generator at different speeds and ratings, a stator current loading limit and an air gap density limit should be assumed. For the determination of the size of the axial gap generators, an ampere loading of 900 ampere-conductors per inch of circumference of the stator has been used. This circumference is at the average diameter  $\frac{OD + ID}{2}$ . The gap density has been fixed at 40 Kl/in<sup>2</sup>. This density is the actual maximum of the flux wave under each pole. The equations used assume a sine wave of flux, or that the maximum fundamental of the pole flux wave is equal to the actual maximum of the flux wave. For concentric poles (square flux waves), this occurs at a pole embrace of 55%.

40 Kl/in<sup>2</sup> gap density and 900 amp-conductors per inch are set as the design limits.

The following discussion explains the derivation of the output equation used to determine generator sizes.

The output of a three phase generator is  $KVA = \frac{I_{LL} E_{LL} \sqrt{3}}{10^3}$

The voltage is defined by -

$$E_{LL} = \frac{\phi_T (\text{RPM}) Cw N_e}{60 \times 10^5}$$

See derivation elsewhere in report.

Where  $\phi_T$  = Hypothetical total flux in air gap in Kilolines,

$$C_w = \frac{E_{LL}}{M E_{ph}} \cdot \frac{C_1 K_d}{\sqrt{2}} = .39 C_1$$

m = No. of phases

$C_1$  = Ratio  $\frac{\text{maximum fundamental}}{\text{actual maximum}}$  of the flux wave = 1.0 for sine wave

Ne = Total effective conductors in the machine

The basic voltage equation is substituted in the output equation.

$$KVA = E_{LL} I_L \frac{\sqrt{3}}{10^3} = \frac{\phi_T \text{ RPM } C_w \text{ Ne } I \sqrt{3}}{60 \times 10^5 \times 10^3}$$

$$\phi_T = B_{\text{Gap}} A_{\text{Gap}} \text{ and}$$

$$I = \frac{A \pi D}{\text{Ne}} \text{ where}$$

A = Ampere wire/inch loading of stator based on the average diameter of stator

$$KVA = \frac{B_g (\pi D \ell_c) \text{ RPM } (.39 C_1) \text{ Ne } \sqrt{3} A \pi D}{60 \times 10^8 \text{ Ne}}$$



$$KVA = \frac{B_g 9.85 D^2 \ell_c \text{ RPM } .39 C_1 A \sqrt{3}}{60 \times 10^8}$$

$$KVA = \frac{B_g D^2 \ell_c \text{ RPM } A}{90 \times 10^7} \text{ Basic eqn.}$$

For axial air gap machines

D = average diameter of stator

$$= \frac{OD + ID}{2}$$





For radial air gap machines

$D$  = rotor diameter.

To allow a general treatment of the axial air gap machine, the typical design will be considered to have the following characteristics:

$$\text{Stator OD} = \frac{3}{2} \text{ stator ID}$$

$$\text{Gap density} = B_g = 40 \text{ Kl/in}^2$$

$$\text{Ampere loading} = A = 900 \frac{\text{Amp. Cond.}}{\text{in.}}$$

$$C_1 = \text{Field form factor} = 1.0 \text{ (assume sine wave)}$$

Then,

$$\text{KVA} = \frac{B_g D_{\text{avg}}^2 \ell_c \text{ RPM } A}{90 \times 10^7}$$

$$D_{\text{avg}} = \frac{\text{OD} + \frac{2}{3} \text{OD}}{2} = \frac{5}{6} \text{OD}$$

$$\ell_c = \frac{1}{6} \text{OD}$$

and,

$$\text{KVA} = 40 \frac{25}{36} (\text{OD})^2 \frac{1}{6} (\text{OD}) \frac{\text{RPM (900)}}{90 \times 10^7}$$

$$\text{KVA} = \frac{4.63 (\text{OD})^3 \text{ RPM}}{10^6}$$

$$\text{Area of stator} = .437 (\text{OD})^2$$

$$\text{Total flux} = 40 (\text{Area of stator}) = 17.5 (\text{OD})^2 \text{ Kl.}$$

$$\phi_P = \text{approx. } \frac{\phi_T}{\text{Poles}} \times .56$$

$$\phi_{\text{shaft}} = \text{approx. } \phi_T \times .27$$

When the ID of the stator is fixed at  $\frac{2}{3}$  OD, the diameter which divides the stator into two equal areas is .85 OD. The average diameter is  $\frac{5}{6}$  OD or .835 OD -- a 1.75% difference. This difference will be ignored and the average diameter  $\frac{5}{6}$  OD will be used as the design diameter for all calculations.

For axial air gap generators

$$\text{KVA} = \frac{4.63}{10^6} (\text{OD})^3 \text{ RPM}$$

OD	(OD) <sup>3</sup>	$\times \frac{4.63}{10^6}$	$\times 6000$	12000
3	27	.125 (10 <sup>-3</sup> )	.75	1.5
4	64	.296 (10 <sup>-3</sup> )	1.77	3.54
5	125	.58 (10 <sup>-3</sup> )	3.48	6.96
6	216	1.00 (10 <sup>-3</sup> )	6.00	12.0
7	343	1.59 (10 <sup>-3</sup> )	9.55	19.1
8	512	2.37 (10 <sup>-3</sup> )	14.2	28.4
9	730	3.38 (10 <sup>-3</sup> )	20.3	40.6
10	10 <sup>3</sup>	4.63 (10 <sup>-3</sup> )	27.7	55.4
11	1330	6.16 (10 <sup>-3</sup> )	37.0	74.0
12	1728	8.0 (10 <sup>-3</sup> )	48.0	96.0
13	2197	10.15 (10 <sup>-3</sup> )	61.0	122.0
14	2744	12.7 (10 <sup>-3</sup> )	76.3	152.6

## KVA for RPM Shown

OD	6000	8000	10, 000	12, 000	15, 000	20, 000	24, 000
3	.75	1.0	1.25	1.5	1.88	2.5	3.0
4	1.77	2.36	2.95	3.54	4.42	5.9	7.08
5	3.48	4.63	5.8	6.96	8.7	11.6	13.92
6	6.00	8.0	10.0	12.0	15.0	20.0	24.0
7	9.55	12.7	15.9	19.1	23.9	31.8	38.2
8	14.2	18.9	23.6	28.4	35.5	47.2	56.8
9	20.3	27.1	33.8	40.6	50.7	67.6	81.2
10	27.7	36.9	46.2	55.4	69.2	92.4	110.8
11	37.0	49.3	61.7	74.0	92.5	123.4	148.0
12	48.0	64.0	80.0	96.0	120.0	160.0	192.0
13	61.0	81.3	102.0	122.0	153.0	204.0	244.0
14	76.3	101.5	127.0	152.6	191.0	254.0	305.2

ESTIMATING THE COIL WEIGHT AND  $I^2R$  LOSS

Based on 80% ratio of  $\frac{\text{Field Copper Area}}{\text{Total Coil Area}}$  for field coils and a current density of 5000 amps/in<sup>2</sup>, 4000 ampere turns would require one square inch of coil cross section.

Assume a square copper coil in all cases then using the coil inner diameter;  $d_c$ :

$$WT = \left[ d_c + \frac{AT}{4000} \times \frac{AT}{4000} \right] .321 \text{ lbs.} \quad (1)$$

Where  $d_c$  = coil inner dia, inches

Here the weight of coil hangers and insl. is estimated at 20% of the total.

$$\frac{I^2 R \text{ Loss}}{\text{Lb. Cu.}} = \left( \frac{\text{Amps}}{\text{In.}^2} \right)^2 \frac{\rho}{\#/\text{in}^3} = 25 \frac{(10^6)}{.321} \rho (.8)$$

Where  $\rho$  = Coil resistivity in microhm inches

at 400°F and 5000 amps/in<sup>2</sup> in CU, use Wt. obtained in equation (1) x .8

$$I^2 R \text{ Loss} = \frac{25 (1.17)}{.321} .8 \text{ (WT Coil)}_{\text{Gross}} = 73 \text{ (WT.) Watts} \quad (2)$$

@ 400°F (240°C)

### ROTOR STRESSES

The speed and rating obtainable from a generator are functions of allowable rotor stresses.

The brushless generator rotors can be made into composite cylinders and preliminary stress treatment can be on the basis of a cylinder of homogeneous material.

Maximum stress in a homogeneous solid disk is -

$$\text{Max. } S_r = \text{MAX}_{st} S_t = \frac{1}{8} \frac{\gamma W^2}{386.4} (3 + \nu) R^2$$

$R$  = disk outside radius, inches ;  $W$  = RAD/SEC

$\nu$  = Poisson's Ratio = .26 for steel (general approximation)

$\gamma$  = density LB/in<sup>3</sup> = .283 for steel ;  $N$  = REV/MIN

$$S = \frac{.283}{8} \frac{(2\pi)^2 N^2}{386.4 (3600)} (3.26) R^2 \quad ; S = \text{PSI}$$

$$= \frac{3.26}{10^6} N^2 R^2$$

A more realistic condition usually is represented by a cylinder with a hole in the center.

The maximum stress in a homogeneous circular disk or a cylinder with a small hole in the center is:

$$\text{Max } S_t = \frac{1}{4} \frac{\gamma W^2}{386.4} \left[ (3 + \nu) R^2 + (1 - \nu) R_o^2 \right]$$

$R$  = disk outside radius, inches

$R_o$  = disk inside radius, inches


If  $R_o$  is small and insignificant

$$\text{Max } S_t = \frac{1}{4} \frac{\gamma W^2}{386.4} (3 + \nu) R^2 \quad \text{PSI}$$

This equation gives twice the stress calculated in a disk without a hole or -


$$S_t = \frac{6.52}{10^6} N^2 R^2$$

STRESS IN CYLINDER HAVING A SMALL,  
AXIAL, THROUGH HOLE



$$\text{MAX. } S_t = \frac{1}{4} \frac{d\omega^2}{386.4} [3.26 R^2]$$

$$S_t = 6.53(RPM)^2 R^2 10^{-6}$$



EQUIVALENT CIRCUITS FOR  
SYNCHRONOUS GENERATORS

## Introduction

In the statement of work describing this study, an equivalent circuit is requested. The description in part reads: "The circuit and parameters chosen and evaluated should be capable of completely describing both steady state and transient performances including various overloading and short-circuit capabilities."

"Parameters for the equivalent circuit are to be derived and evaluated."

"Transfer functions and time constants are to be derived and evaluated."

"All applicable reactances are to be derived and evaluated e.g., synchronous, positive and negative sequence, transient and subtransient, direct and quadrature axes, armature, leakage, armature reaction, etc."

This section contains a derivation of an equivalent circuit submitted to satisfy the requirement for a circuit describing steady state and transient performance. This circuit also describes the performance of the generator when subjected to unbalanced loading.

The derivation of the equivalent circuit described here is an original work by Liang Liang.

Overloading, short-circuit capabilities, time constants and reactance are derived and calculated elsewhere in the study.

The equivalent circuits themselves are on Pages 31, 33, 72 and 73. The symbols are on Pages 2 and 3. Derivations and explanations are given step-by-step.



Nomenclature

<u>Symbol</u>	<u>Subscript</u>
$\tau$ - torque	R - resultant
$l$ - distance	$\alpha, \beta$ - reference frames
$v$ - velocity	$em$ - electromagnetic
F - force	d - direct axis
$e$ - voltage	q - quadratic axis
$i$ - current	a - armature
$\psi$ - flux linkage	f - excitation field
$\omega$ - frequency in rad/sec	md - direct axis magnetizing component
R - resistance	mq - quadratic axis magnetizing component
L - inductance	Dd - direct axis damper bar
$\Theta$ - power factor angle	Dq - quadratic axis damper bar
$\chi$ - reactance	g - generator
p - power	al - armature leakage
J - moment of inertia	$\mathcal{f}l$ - field leakage
D - damping factor	o - zero sequence
K - conversion constant	s - shaft
f - frequency in cycles per sec	t - terminal
P - number of poles	L - load
M - mutual inductance	a - )
N - turns of winding	b - ) phases
Z - impedance	c - )
s - Laplace operator	A - load of phase
$G(s)$ - transfer function	B - load of phase b
$\Phi(s)$ - power density spectrum	C - load of phase c
$\phi(t)$ - correlation function	i - input

<u>Symbol</u>	<u>Subscript</u>
T - time constant	ab - between phase a and b
A - amplifier	bc - between phase b and c
C - capacitor	ca - between phase c and a
$\Sigma$ - summing junction	r - rated
t - time	fb - feedback
$E(s)$ - voltage	g - generator
$\varepsilon$ - error signal	e - excitation
$\int$ - integrator	ss - steady state
$\rightarrow$ - operation amplifier	
$\times$ , $\boxtimes$ - multiplier	
$\sqrt{\phantom{x}}$ - square root	
$\bigcirc$ - potentiometer	
$\triangleleft$ - high gain amplifier	
$\square$ - square	
$\underline{x}$ - state vector	
$\underline{m}$ - control vector	
$\underline{n}$ - disturbance vector	
A - coefficient matrix	
B - driving matrix	
Exp - exponential	
ln - natural logarithm	
S - sensitivity	

# I FUNDAMENTALS

## 1. Assumptions

- (a) Symmetrical three phase, delta or Y-connected machine with field structure symmetrical about the axis of the field winding and inter-polar space.
- (b) Armature phase mmf in effect, sinusoidally distributed.
- (c) Magnetic and electric materials are rigidly connected.
- (d) Neglect eddy current in armature iron.
- (e) Neglect hysteresis effect.
- (f) Neglect magnetic saturation (optional).
- (g) Rotor considered as stationary reference frame.
- (h) Parameters are time invariant.

## 2. Classical Approach

For all electric machines, the dynamic equation of Lagrange applies (in tensor):

$$\tau^\alpha = \frac{d}{dt} \left( \frac{\partial \tau_R}{\partial v^\alpha} \right) - \frac{\partial \tau_R}{\partial \ell^\alpha} + \frac{\partial F_{em}}{\partial v^\alpha} \quad (1)$$

The stator and the rotor of the machine are considered as reference frames respectively. This holonomic expression has to be transformed into unholonomic before the two-reaction theory can be applied. That is, to choose an arbitrary frame (stator or rotor) as stationary and the other considers it as reference. Thus -

$$\tau^\alpha = \frac{d}{dt} \left( \frac{\partial \tau_R}{\partial v^\alpha} \right) - \frac{\partial \tau_R}{\partial \ell^\alpha} + \frac{\partial F_{em}}{\partial v^\alpha} + \frac{\partial \tau_R}{\partial v^\alpha} v^\beta Q_{\alpha\beta}^\delta \quad (2)$$

$$Q_{\alpha\beta}^\delta = \left( \frac{\partial C_\alpha^\delta}{\partial \ell^\beta} - \frac{\partial C_\beta^\delta}{\partial \ell^\alpha} \right) C_\alpha^\kappa C_\beta^\eta$$

= non-holonomic object

$$C_\alpha^k, C_\beta^n = \text{transformation tensors}$$

The complexity in solving the problem directly is obvious; therefore, other approaches are used.

### 3. Basic Equations

By means of the two-reaction method and by choosing the rotor as the stationary reference frame, the representation of the dynamic behavior of synchronous generators can be written in set of ordinary differential equations. The reference frame is resolved into direct and quadratic axis.

Armature -

$$e_d = -R_a i_d + \frac{d}{dt} \Psi_d - \Psi_q \omega_g \quad (3)$$

$$e_q = -R_a i_q + \frac{d}{dt} \Psi_q + \Psi_d \omega_g \quad (4)$$

$$e_t = \sqrt{e_d^2 + e_q^2} \quad (5)$$

$$\Psi_d = L_{md} i_f - (L_{md} + L_{al}) i_d + L_{md} i_{Dd} \quad (6)$$

$$\Psi_q = -(L_{mq} + L_{al}) i_q + L_{mq} i_{Dq} \quad (7)$$

Field -

$$e_f = R_f i_f + \frac{d}{dt} \Psi_f \quad (8)$$

$$\Psi_f = (L_{md} + L_{fl}) i_f - L_{md} i_d + L_{md} i_{Dd} \quad (9)$$

Damper bar -

$$e_{Dd} = R_{Dd} i_{Dd} + \frac{d}{dt} \Psi_{Dd} = 0 \quad (10)$$

$$e_{Dq} = R_{Dq} i_{Dq} + \frac{d}{dt} \Psi_{Dq} = 0 \quad (11)$$

$$\Psi_{Dd} = L_{md} i_f - L_{md} i_d + (L_{md} + L_{Dd}) i_{Dd} \quad (12)$$

$$\Psi_{Dq} = -L_{mq} i_q + (L_{mq} + L_{Dq}) i_{Dq} \quad (13)$$

Zero sequence -

$$e_o = -R_o i_o + \frac{d}{dt} \Psi_o \quad (14)$$

$$\Psi_o = -L_o i_o \quad (15)$$

Electromagnetic torque -

$$\tau_{em} = \psi_d i_q - \psi_q i_d$$

(16)




Fig. 1 Physical Arrangement






Fig. 2 Representation



(I) Under excited



(II) Over excited

Fig. 3 Steady state vector representation

#### 4. Simplification

If detailed accuracy is not essential, it can be traded for simplification. Damper bar, armature resistances and leakage reactances have relatively small effects on voltage, current and phase relationship in a normal steady state operation. Therefore, they can be ignored.

$$e_f = R_f i_f + \frac{d}{dt} \psi_f \quad (17)$$

$$e_d = \frac{d}{dt} \psi_d - \psi_g \omega_g \quad (18)$$

$$e_g = \frac{d}{dt} \psi_g + \psi_d \omega_g \quad (19)$$

$$\psi_f = L_{md} (i_f - i_d) \quad (20)$$

$$\psi_d = \psi_f \quad (21)$$

$$\psi_g = -L_{mg} i_g \quad (22)$$

$$\tau_{em} = \psi_d i_g - \psi_g i_d \quad (23)$$

Additional simplification can be made in a situation where only the steady state condition of a synchronous generator is considered in a complex system. Since all the time dependent variables become constant as the transient settles down, their rates of change approach to zero. A set of algebraic equations is derived below.

$$e_f = R_f i_f \quad (24)$$

$$e_d = -\psi_g \omega_g \quad (25)$$

$$e_g = \psi_d \omega_g \quad (26)$$

$$\psi_f = L_{md} (i_f - i_d) \quad (27)$$

$$\psi_d = \psi_f \quad (28)$$

$$\psi_g = -L_{mg} i_g \quad (29)$$

$$\tau_{em} = \psi_d i_g - \psi_g i_d \quad (30)$$



## 5. Inputs and Outputs

- (a) Most literature in discussing the synchronous generator choose the frequency  $\omega_g$  and the field excitation voltage  $e_f$  as inputs and the terminal voltage which is resolved into two-axis components as outputs. They are applied to the balanced loads while the direct and quadratic currents feedback to the generator.





Fig. 4                      Balanced load simulation

It should be recognized that the functions of  $e_d$ ,  $e_q$  and  $i_d$ ,  $i_q$  can be reversed.

- (b) For a more detail representation, electric-mechanical relation can be included. Thus, the fluctuations of the frequency and of its dependent variables can be observed. Otherwise, the shaft speed  $\omega_s$  has to be assumed well regulated to stand against any disturbance. Consider the shaft is rigid.



*Figure. 5*

$$p_i = T_i \omega_s \quad (31)$$

$$T_i - T_{em} = J \cdot \frac{d\omega_s}{dt} + D\omega_s \quad (32)$$

$$\omega_g = \frac{P}{2} \cdot \frac{\omega_s}{30} \quad (33)$$

Where  $p_i$  is the input power,  $T_i$  input torque, and  $P$ , number of poles.

The moment of inertia  $J$  should include that of the prime mover. The damping factor  $D$  is a non-linear element which consists of mechanical losses like friction and windage. The latter is proportional to square of shaft speed  $\omega_s$ .

- (c) The power supply for the field excitation of a synchronous generator ideally comes from a battery. In practice, it is either from a DC generator or by means of static excitation for the purpose of regulation.
- (i) The transfer function of the output voltage and the excitation voltage of a DC generator in frequency domain is

$$\frac{E_g(s)}{E_e(s)} = \frac{K_g}{R_f + L_f s} \quad (34)$$




Fig. 6 DC generator

- (ii) Static excitation for synchronous generator becomes widely accepted for obvious reasons like faster response and the elimination of rotating excitation machine. A typical approach is stated as follows: Excitation is provided to the generator from load currents through current transformers and rectifiers. The voltage regulator plays the role of no-load excitation and regulation of terminal voltage under different load conditions.

Such a method can be applied, for instance, for a two-coil Lundell generator with both the armature and the field stationary.




Fig. 7  
Static Excitation

$$e_f = R_f i_f + \frac{d}{dt} \psi_f \quad (35)$$

$$i_f = i_{fT} + i_{fR} \quad (35a)$$

$$\psi_f = \psi_{fT} + \psi_{fR} \quad (36)$$

$$i_{fT} = K i_L \quad (37)$$

$$\psi_{fT} = (L_{md} + L_{fL}) i_{fT} \quad (38)$$

- (d) For a detail study of synchronous generator, unbalanced load simulation is suggested. The affects of all kinds of faults due to the load can be pictured simply by adjusting the load parameters. Balanced load condition is only a special case. The major feature of an analog simulation is to convert DC representing voltages of  $e_d$  and  $e_q$  into three phase AC components  $e_a$ ,  $e_b$  and  $e_c$  which are applied to the unbalanced load. The AC components  $i_a$ ,  $i_b$  and  $i_c$  are converted back into DC level before feeding back to the generator. Certainly the price to pay for is complexity.




Fig. 8 Unbalanced load analog simulation

## 6. Conversion

For the unbalanced load simulation, the direct and quadratic output voltages of the generator have to be converted into corresponding three phases before applying to the load. Similarly, the currents from the load have to be converted back into direct and quadratic components before returning to the machine.

$$e_a = e_d \sin(\omega_g t) - e_q \cos(\omega_g t) + e_o \quad (39)$$

$$e_b = e_d \sin\left(\omega_g t - \frac{2\pi}{3}\right) - e_q \cos\left(\omega_g t - \frac{2\pi}{3}\right) + e_o \quad (40)$$

$$e_c = e_d \sin\left(\omega_g t - \frac{4\pi}{3}\right) - e_q \cos\left(\omega_g t - \frac{4\pi}{3}\right) + e_o \quad (41)$$

$$i_d = -\frac{2}{3} \left[ i_a \cos(\omega_g t) + i_b \cos\left(\omega_g t - \frac{2\pi}{3}\right) + i_c \cos\left(\omega_g t - \frac{4\pi}{3}\right) \right] \quad (42)$$

$$i_q = \frac{2}{3} \left[ i_a \sin(\omega_g t) + i_b \sin\left(\omega_g t - \frac{2\pi}{3}\right) + i_c \sin\left(\omega_g t - \frac{4\pi}{3}\right) \right] \quad (43)$$

$$e_o = \frac{1}{3} (e_a + e_b + e_c) \quad (44)$$

$$i_o = \frac{1}{3} (i_a + i_b + i_c) \quad (45)$$

The load is normally expressed in Y-connection. If delta load is used, proper connection of load can be made as in the analog simulation or convert them into Y-connection by using the following equations:




Fig. 9 Delta to Y-connection conversion

$$Z_a = \frac{Z_{ab} Z_{ac}}{Z_{ab} + Z_{bc} + Z_{ac}} \quad (46)$$

$$Z_b = \frac{Z_{ab} Z_{bc}}{Z_{ab} + Z_{bc} + Z_{ac}} \quad (47)$$

$$Z_c = \frac{Z_{ac} Z_{bc}}{Z_{ab} + Z_{bc} + Z_{ac}} \quad (48)$$

## 7. Load

### (a) Balanced load -

Balanced load can also be resolved into two-axis, direct and quadratic components. Only the resistive and inductive load are considered.

$$e_d = R_L i_d + L_L \frac{di_d}{dt} - L_L i_q \omega_g \quad (49)$$

$$e_q = R_L i_q + L_L \frac{di_q}{dt} + L_L i_d \omega_g \quad (50)$$

The load can be expressed in another form.

$$i_d = \frac{\cos \theta}{|Z_L|} e_d + \frac{\sin \theta}{|Z_L|} e_q \quad (51)$$

$$i_q = \frac{-\sin \theta}{|Z_L|} e_d + \frac{\cos \theta}{|Z_L|} e_q \quad (52)$$

$$|Z_L| = \sqrt{R_L^2 + X_L^2} \quad (53)$$

$$\theta = \tan^{-1}(X_L/R_L) \quad (54)$$

Thus, the load is governed by the power factor, or vice versa.

### (b) Unbalanced load -

Again, only resistive and inductive load are considered. However, mutual inductances among the loads are included.

$$e_a = R_A i_a + L_A \frac{di_a}{dt} - M_{ab} \frac{di_b}{dt} - M_{ca} \frac{di_c}{dt} \quad (55)$$

$$e_b = R_B i_b + L_B \frac{di_b}{dt} - M_{ab} \frac{di_a}{dt} - M_{bc} \frac{di_c}{dt} \quad (55a)$$

$$e_c = R_C i_c + L_C \frac{di_c}{dt} - M_{bc} \frac{di_b}{dt} - M_{ca} \frac{di_a}{dt} \quad (55b)$$

## 8. Parameter

All the machine parameters are practically time invariant. Their derivations can be found in the enclosed design manual or other standard texts on synchronous generator. Usually inductive reactance are given. To obtain the absolute inductive value, divide the reactance by the rated generator frequency. The unit of frequency should be in radians per second. The direct and the quadratic reactances computed from the design manual have taken care of whether the armature winding is Y or delta-connected as well as the number of pole pairs.

## 9. Time Constants

Direct-axis open-circuit transient time constant

$$T'_{d0} = \frac{L_{fd} + L_{md}}{R_f} \quad (56)$$

Direct-axis short-circuit time constant

$$T'_d = T'_{d0} \cdot \frac{L'_d}{L_d} \quad (56a)$$

where

$$L_d = L_{md} + L_{ad} \quad (56b)$$

$$L'_d = L_{ad} + \frac{L_{md} \cdot L_{fd}}{L_{md} + L_{fd}} \quad (56c)$$

With external inductive load, the direct-axis short-circuit time constant is adjusted to

$$T'_{de} = T'_d \cdot \frac{L'_d + L_L}{L_d + L_L} \cdot \frac{L_d}{L'_d} \quad (57)$$

There is no definite formula to compute the direct-axis short-circuit sub-transient time constant. Usually it is obtained from measurement.






Fig. 10

Short circuit transient time  
constants measurement

## 10. Non-Linear Elements

(a) The basic equations -

$$e_d = -R_a i_d + \frac{d}{dt} \psi_d - \psi_g \omega_g \quad (3)$$

etc., are non-linear. The non-linear term  $\psi_g \omega_g$  in this equation is introduced because of the transformation from holonomic reference frames into non-holonomic and so as the other analogous.

(b) Magnetic saturation -

It is an inherent property of magnetic material. Usually for the design of generators a steel of low retentivity is used. The hysteresis loop is narrow and thus its effect can be neglected. An average saturation curve can be used to describe the characteristics of the magnetic path.




Fig. 11a

Magnetization curve

The average magnetization curve can also be expressed in terms of  $e_t$  and  $i_f$




Fig. 11b Magnetic saturation approximation

The compensation  $\delta$  versus the terminal voltage  $e_t$  is derived from the difference between the air gap line and the no-load saturation curve.

Further approximation can be developed by assuming  $\chi_{mq}$  independent of saturation (corresponds to path mostly in air). Only  $\chi_{md}$  varies with the flux. As the generator starts to saturate,  $\chi_{md}$  changes accordingly. This can be approximated by adding a factor to  $i_f$  by the amount proportional to the difference between the air gap line and the no-load saturation curve. If the operating point is below the knee of the curve, a linear relation can be assumed.

(c) Mechanical elements -

As in the more detail simulation, the mechanical relation between the prime mover and the generator is included.

- (i) If gear is used for coupling, there will be backlash.




Fig. 12 Backlash

- (ii) Sometimes a mechanical damper is used to eliminate the mechanical resonance near the low speed end.




Fig. 13 Mechanical Damper Response

- (iii) The windage and friction loss is proportional to the square of the shaft speed.

Analog simulations of

(i) Magnetic saturation - (approximated)




Fig. 11a

(ii) Mechanical relation -




Fig. 11b

## 11. Linearization

In the basic equation

$$e_d = -R_a i_d + \frac{d}{dt} \psi_d - \omega_g \psi_f$$

the non-linearity is introduced by the product of two time varying functions  $\omega_g$  and  $\psi_f$ . Since all the variables are continuous functions of time and are likely to be monotonic, linearization is possible. For small increment of change, the equation can be written in a linear form. (Derivation is in section II-2.  $\bar{\omega}_g$ , etc., are steady state values.)

$$\Delta e_d = -R_a (\Delta i_d) + \frac{d}{dt} (\Delta \psi_d) - \bar{\psi}_f (\Delta \omega_g) - \bar{\omega}_g (\Delta \psi_f) \quad (58)$$

For constant drive generator,  $\Delta \omega_g = 0$

$$\Delta e_d = -R_a (\Delta i_d) + \frac{d}{dt} (\Delta \psi_d) - \bar{\omega}_g (\Delta \psi_f) \quad (59)$$

To compare with the original equation by setting  $\omega_g = \bar{\omega}_g$ , the choice of magnitude of the increments for accuracy becomes obvious. Indeed they can be simply expressed as -

$$e_d = -R_a i_d + \frac{d}{dt} \psi_d - \bar{\omega}_g \psi_f \quad (60)$$

Another alternative is that the flux linkages are kept constant. Thus all currents are invariant. Neglecting  $R_a$ ,

$$e_d = -\bar{\psi}_f \omega_g \quad (61)$$

the voltage will be directly proportional to the generation frequency.

However, when the change  $\Delta \omega_g$  and  $\Delta \psi_f$  are considered simultaneously, the constraints of the increments are imposed. A larger value of increment will sacrifice the accuracy. Since a steady state value of  $\bar{\omega}_g$  has been chosen as the coefficient of  $\Delta \psi_f$ , on the other hand,  $\Delta \omega_g$  is time varying and its relatively large change will make  $\bar{\omega}_g$  invalid. Similar argument applies to the term  $\bar{\psi}_f (\Delta \omega_g)$  and other related equations.

The linear transfer relations are:




Fig. 15

(a) Constant speed

(b) Constant flux linkage

### 12. Per unit system

It may be convenient for some individuals to use per unit system instead of absolute value.

$$\text{Quantity in per unit} = \frac{\text{actual quantity}}{\text{base value of quantity}} \quad (62)$$

$$P_{base} = E_{base} I_{base} \quad (63)$$

$$R_{base}, X_{base}, Z_{base} = \frac{E_{base}}{I_{base}} \quad (64)$$

$$T_{base} = \frac{P_{base}}{\omega_{base}} \quad (65)$$

### 13. Power density spectrum

If the input is in power density spectrum form and the generator is linearized and expressed in frequency domain as  $G(S)$  and its conjugate  $G(-S)$

$$\Phi_{oo}(s) = G(s) G(-s) \Phi_{ii}(s) \quad (66)$$

assuming the input and output spectrums are autocorrelated. The output can be converted into mean square value, say of  $e_t$ .

$$\begin{aligned} \overline{e_t(t)^2} &= \Phi_{oo}(0) \\ &= \int_{-\infty}^{\infty} \Phi_{\infty}(s) e^{st} ds \Big|_{t=0} \\ &= \int_{-\infty}^{\infty} G(s) G(-s) \Phi_{ii}(s) ds \end{aligned} \quad (67)$$

The evaluation can be implemented analogously or by using the table of integrals which can be found in many advanced control engineering texts.




Fig. 16a      Power density spectrum




Fig. 16b      Analog simulation



#### 14. Faults

Faults are restricted to the load. They may be line to line, line to neutral, etc. In the unbalanced load simulation, the faults can be pictured simply by appropriate arrangement or by adjusting the load parameters of the corresponding phase. For example, if phase *a* is shorted to neutral, set  $R_A = 0$  ;  $L_A = 0$  .

When it is open, theoretically  $R_A$  and  $L_A$  become infinity. In computer practice they can be set many orders larger than the normal value. Use the same tactic as in cases like  $1/L_A$ , while  $L_A$  is zero.

#### 15. Converter

In the unbalanced load simulation, converters are required to generate  $\cos \omega_g t$  and  $\sin \omega_g t$  as functions of  $\omega_g$ . (Refer to eqs. (39) - (43) ) By Laplace transformation

$$\mathcal{L} [\cos \omega_g t] = \frac{s}{s^2 + \omega_g^2} = A \quad (68a)$$

$$\mathcal{L} [\sin \omega_g t] = \frac{\omega_g}{s^2 + \omega_g^2} = B \quad (68b)$$

$$A = \frac{B}{\omega_g} \cdot s \quad (68c)$$

The analog simulation -




Fig. 17 DC to AC converter analog

### 16. Minimum Time Starting

It has been proved theoretically that switching control can achieve the minimum time for a system to reach its steady state value after a step disturbance. Due to the inherent defect of physical components like dead-band and frictions, dual-mode control is suggested. That is, the switching control takes care of large error signal while the linear control takes care of the small error signal in the feedback control loop to generate the manipulated input, say excitation voltage  $e_f$  for the synchronous generator. (Constant shaft drive)




Fig. 18      Dual-mode control for minimum time starting

To start a synchronous generator, considering the shaft drive has assumed its constant speed, the reference as a step function is applied. The optimum switching boundary computer recognizes the zero initial state and the final state from the reference signal and decides the switching points according to the orders of dynamics of the plant. (For an  $n^{\text{th}}$  order linear time invariant controllable system, with poles real and non-positive, requires no more than  $n-1$  switchings and an initial-on and a final-off operation to reach final steady state in minimum time.) When the error signal falls within the dead-band of bang-bang controller, the linear control takes over.




Fig. 18a      Second order system step function response


17. Modern Control Formulation

Fig. 19a      Multivariable process

- $\underline{x}$  - state vector  
 $\underline{m}$  - control vector  
 $\underline{n}$  - disturbance vector

For a stationary process, the dynamic characteristics are -

$$\dot{\underline{x}}(t) = A \underline{x}(t) + B \underline{m}(t) + \underline{n}(t) \quad (69a)$$

- $\dot{\underline{x}}$  - differential state vector  
 $A$  - coefficient matrix  
 $B$  - driving matrix

The solution will be - (from initial state at time  $t_0$  to final state at  $t$ )

$$\underline{x}(t) = \text{Exp } A(t-t_0) \underline{x}(t_0) + \int_{t_0}^t [\text{Exp } A(t-\tau)] [B \underline{m}(\tau) + \underline{n}(\tau)] d\tau$$

Exp: Exponential

(69b)

## II BALANCED LOAD

### 1. Analog Simulation

Use the basic synchronous generator dynamic eqs. (3) to (13), (16) and balanced load eqs. (51) to (54). The operating frequency is absorbed into the reactances such as  $X_{md} = \omega_r L_{md}$  where  $\omega_r$  is the rated frequency. Per unit system is used. After some manipulation, a block diagram is concluded in Fig. 1 where

$$T_{Dd} = \frac{X_{md} + X_{Dd}}{R_{Dd}} \quad (71a)$$

$$T_{Dq} = \frac{X_{mq}}{R_{Dq}} \quad (71b)$$

For the sake of convenience, Laplace operator  $S$  is used for differentiation while  $1/S$ , for integration with initial condition, equals to zero. Magnetic saturation is approximated.

The inputs to the generator are frequency  $\omega_g$  and excitation voltage  $e_f$ .

The transfer functions appear in the block diagram.


$$H_d(s) = R_a + \frac{S}{\omega_r} \left[ X_{al} + \frac{X_{md} X_{Dd}}{X_{md} + X_{Dd}} \right] + \frac{X_{md}^2}{X_{md} + X_{Dd}} \cdot \frac{S/\omega_r}{1 + T_{Dd} \cdot S/\omega_r} \quad (72a)$$

$$H_q(s) = R_a + \frac{S}{\omega_r} \left[ X_{al} + \frac{X_{mq} X_{Dq}}{X_{mq} + X_{Dq}} \right] + \frac{X_{mq}^2}{X_{mq} + X_{Dq}} \cdot \frac{S/\omega_r}{1 + T_{Dq} \cdot S/\omega_r} \quad (72b)$$

$$D_d(s) = \frac{S}{\omega_r} \cdot \frac{X_{mq} X_{Dq}}{X_{md} + X_{Dd}} + \frac{X_{md}^2}{X_{md} + X_{Dd}} \cdot \frac{S/\omega_r}{1 + T_{Dd} \cdot S/\omega_r} \quad (72c)$$


$$D_q(s) = X_{al} + \frac{X_{mq} X_{Dq}}{X_{mq} + X_{Dq}} + \frac{X_{mq}^2}{X_{mq} + X_{Dq}} \cdot \frac{1}{1 + T_{Dq} \cdot S/\omega_r} \quad (72d)$$

$$L(s) = \frac{R_L}{Z_L^2} + \frac{S}{\omega_r} \cdot \frac{X_L}{Z_L^2} \quad (72e)$$




I. SYNCHRONOUS GENERATOR  
BALANCED LOAD  
REPRESENTATION

The analog computer simulation is in Fig. II. Notice the difference between the circuit representing the first order transfer function and the differentiator.



$$\frac{e_{OUT}}{e_{IN}} = - \frac{(R_{fb} C) s}{(R_i C) s + 1} \quad (73)$$

Fig. 20a First order transfer function



$$\frac{e_{OUT}}{e_{IN}} = -(R_{fb} C) s$$

Fig. 20b Differentiator





FIG. II ANALOG COMPUTER SIMULATION OF SYNCHRONOUS GENERATOR. (BALANCED LOAD)



The basic values of the components in the presenting analog computer are;



$$\frac{e_{OUT}}{e_{IN}} = - \frac{Z_{fb}}{Z_i} \quad (75)$$

Fig. 21

$Z_{fb}$  = 100 K resistor

$Z_i$  = 100 K resistor

for an operational amplifier with unity gain. While

$Z_{fb}$  = 10 microfarad capacitor

$Z_i$  = 100 K resistor

for an integrator with unity gain and a time constant of one sec.


<u>Pot. No.</u>	<u>Variable</u>	<u>Setting</u>
2	Scaling constant	0.2
7	$\frac{\chi_{m_g}^2}{\chi_{m_g} + \chi_{D_g}} \cdot \frac{10^{-2}}{T_{D_g}}$	0.253
8	$\frac{10^{-2}}{T_{D_g}}$	0.318
9	$\frac{(\frac{1}{\omega_r}) \chi_{m_d}^2}{10^3 (\chi_{m_d} + \chi_{D_d})}$	0.054
10	$\chi_{al} + \frac{\chi_{m_g} \chi_{D_g}}{\chi_{m_g} + \chi_{D_g}}$	0.137
11	$\frac{\chi_L}{ Z_L }$ AT 0.75 P.F.	0.661
12	$\frac{R_L}{ Z_L }$ AT 0.75 P.F.	0.75
14	$\frac{\chi_{m_d}^2}{\omega_r (\chi_{m_d} + \chi_{D_d})}$	0.536
15	$2 \omega_g \chi_{fl}$	0.248

<u>Pot. No.</u>	<u>Variable</u>	<u>Setting</u>
16	$\frac{X_L}{ Z_L }$ AT 0.75 P.F.	0.661
17	Scaling constant	0.5
18	$\frac{X_{m^2} g}{W_r (X_{mg} + X_{dg})}$	0.317
19	$\frac{R_L}{ Z_L }$ AT 0.75 P.F.	0.75
21	$X_{al}$	0.083
22	$2 W_g R_f \cdot 10^{-2}$	0.173
23	$\frac{1}{2} X_{md}$	0.361
26	$\frac{50 W_r}{100 (E_f)_{base}}$	0.27
28	$\frac{1}{20 X_{od}}$	0.98

<u>Pot. No.</u>	<u>Variable</u>	<u>Setting</u>
48	$\omega/\omega_r$	1.0
50	Scaling constant	0.2
55	$R_a$	0.205
56	$\frac{1}{\omega_r} \left( X_{al} + \frac{X_{mg} X_{Dg}}{X_{mg} + X_{Dg}} \right) \cdot 10^{-1}$	0.055
57	$R_a$	0.205
58	$\frac{1}{\omega_r} \left( X_{al} + \frac{X_{md} X_{Dd}}{X_{md} + X_{Dd}} \right) \cdot 10^{-1}$	0.053

<u>Component</u>	<u>Value</u>	<u>Component</u>	<u>Value</u>
$R_1$	306 K 	$C_1$	10 uf
$R_2$	10 K 	$C_2$	1 uf
$R_3$	185 K 		
$R_4$	100 K 		

Time scale: Real time: Computer time = 100:1



## 2. Digital Computation

### (i) Linearization:

For 
$$e_d = -R_a i_d + \frac{d}{dt} \psi_d - \psi_g \omega_g$$

Let

$$\begin{aligned} e_d &= \bar{e}_d + \Delta e_d \\ i_d &= \bar{i}_d + \Delta i_d \\ \psi_d &= \bar{\psi}_d + \Delta \psi_d \\ \psi_g &= \bar{\psi}_g + \Delta \psi_g \\ \omega_g &= \bar{\omega}_g + \Delta \omega_g \end{aligned}$$

where  $\bar{e}_d$  is the steady state value and  $\Delta e_d$ , a small increment of change. The same definition is applied to other variables.

Let

$$x = \psi_g \omega_g$$

$$\Delta x = \frac{\partial x}{\partial \psi_g} \Delta \psi_g + \frac{\partial x}{\partial \omega_g} \Delta \omega_g$$

$$\frac{\partial x}{\partial \psi_g} \triangleq \omega_g$$

$$\frac{\partial x}{\partial \omega_g} \triangleq \bar{\psi}_g$$

Substitute the relations into the original equation.

$$\Delta e_d = -R_a \Delta i_d + \frac{d}{dt} \Delta \psi_d - (\omega_g \Delta \psi_g + \bar{\psi}_g \Delta \omega_g)$$

Similar procedure is applied to the other basic equations. The results are expressed in matrix.

Load:

$$\begin{bmatrix} \Delta e_d \\ \Delta e_g \end{bmatrix} = \begin{bmatrix} R_L + S L_L & -\bar{\omega}_g L_L \\ \bar{\omega}_g & R_L + S L_L \end{bmatrix} \begin{bmatrix} \Delta i_d \\ \Delta i_g \end{bmatrix} + \begin{bmatrix} -L_L i_g \\ L_L \bar{i}_d \end{bmatrix} \begin{bmatrix} \Delta \omega_g \end{bmatrix} \quad (76)$$

Flux linkages:

$$\begin{bmatrix} \Delta \psi_d \\ \Delta \psi_q \\ \Delta \psi_f \\ \Delta \psi_{od} \\ \Delta \psi_{oq} \end{bmatrix} = \begin{bmatrix} -L_{sd} & 0 & L_{md} & L_{md} & 0 \\ 0 & -L_{sq} & 0 & 0 & L_{mq} \\ -L_{md} & 0 & L_{md} + L_{fl} & L_{md} & 0 \\ -L_{md} & 0 & L_{md} & L_{od} & 0 \\ 0 & -L_{mq} & 0 & 0 & L_{oq} \end{bmatrix} \begin{bmatrix} \Delta i_d \\ \Delta i_q \\ \Delta i_f \\ \Delta i_{od} \\ \Delta i_{oq} \end{bmatrix} \quad (77)$$

Voltages:

$$\begin{bmatrix} \Delta e_d \\ \Delta e_q \\ \Delta e_f \\ 0 \\ 0 \end{bmatrix} = \begin{bmatrix} s & -\bar{\omega}_q & 0 & 0 & 0 \\ \bar{\omega}_q & s & 0 & 0 & 0 \\ 0 & 0 & s & 0 & 0 \\ 0 & 0 & 0 & s & 0 \\ 0 & 0 & 0 & 0 & s \end{bmatrix} \begin{bmatrix} \Delta \psi_d \\ \Delta \psi_q \\ \Delta \psi_f \\ \Delta \psi_{od} \\ \Delta \psi_{oq} \end{bmatrix}$$

$$+ \begin{bmatrix} -R_a & 0 & 0 & 0 & 0 \\ 0 & -R_a & 0 & 0 & 0 \\ 0 & 0 & R_f & 0 & 0 \\ 0 & 0 & 0 & R_{od} & 0 \\ 0 & 0 & 0 & 0 & R_{oq} \end{bmatrix} \begin{bmatrix} \Delta i_d \\ \Delta i_q \\ \Delta i_f \\ \Delta i_{od} \\ \Delta i_{oq} \end{bmatrix} + \begin{bmatrix} -\bar{\psi}_q \\ \bar{\psi}_d \\ 0 \\ 0 \\ 0 \end{bmatrix} \begin{bmatrix} \Delta \omega_q \end{bmatrix} \quad (78)$$

Laplace transformation has been applied with initial conditions equal to zero. In order to simplify the problem, neglect damper bar, armature resistance, magnetic saturation, armature and field leakage inductances. Eqs. (76) to (78) and the balanced load equations become:

$$\begin{bmatrix} \Delta e_d \\ \Delta e_q \end{bmatrix} = \begin{bmatrix} R_L + S L_L & -L_L \bar{\omega}_g \\ L_L \bar{\omega}_g & R_L + S L_L \end{bmatrix} \begin{bmatrix} \Delta i_d \\ \Delta i_q \end{bmatrix} + \begin{bmatrix} -L_L \bar{i}_q \\ L_L \bar{i}_d \end{bmatrix} [\Delta \omega_g] \quad (79)$$

$$\begin{bmatrix} \Delta e_f \\ \Delta e_d \\ \Delta e_q \end{bmatrix} = \begin{bmatrix} S & 0 & 0 \\ 0 & S & -\bar{\omega}_g \\ 0 & \bar{\omega}_g & S \end{bmatrix} \begin{bmatrix} \Delta \psi_f \\ \Delta \psi_d \\ \Delta \psi_q \end{bmatrix} + \begin{bmatrix} 0 \\ -\bar{\psi}_q \\ \bar{\psi}_d \end{bmatrix} [\Delta \omega_g] \\ + \begin{bmatrix} R_f & 0 & 0 \\ 0 & 0 & 0 \\ 0 & 0 & 0 \end{bmatrix} \begin{bmatrix} \Delta i_f \\ \Delta i_d \\ \Delta i_q \end{bmatrix} \quad (80)$$

$$\begin{bmatrix} \Delta \phi_f \\ \Delta \phi_d \\ \Delta \phi_q \end{bmatrix} = \begin{bmatrix} L_{md} & -L_{md} & 0 \\ L_{md} & -L_{md} & 0 \\ 0 & 0 & -L_{mq} \end{bmatrix} \begin{bmatrix} \Delta i_f \\ \Delta i_d \\ \Delta i_q \end{bmatrix} \quad (81)$$

$$\begin{bmatrix} \Delta e_f \\ \Delta e_d \\ \Delta e_q \end{bmatrix} = \begin{bmatrix} R_f + S L_{md} & -S L_{md} & 0 \\ S L_{md} & -S L_{md} & \bar{\omega}_g L_{mq} \\ \bar{\omega}_g L_{md} & \bar{\omega}_g L_{md} & -S L_{mq} \end{bmatrix} \begin{bmatrix} \Delta i_f \\ \Delta i_d \\ \Delta i_q \end{bmatrix} \quad (82)$$



Assume constant generator frequency.

That is  $\Delta\omega_g = 0$ . From eqs. (79) to (82). First solve for  $\Delta i_d$  and  $\Delta i_q$ .

$$\begin{bmatrix} \Delta e_f \end{bmatrix} = \begin{bmatrix} R_f + sL_{md} \end{bmatrix} \begin{bmatrix} \Delta i_f \end{bmatrix} - \begin{bmatrix} sL_{md} & 0 \end{bmatrix} \begin{bmatrix} \Delta i_d \\ \Delta i_q \end{bmatrix} \quad (83)$$

$$\begin{bmatrix} \Delta e_d \\ \Delta e_q \end{bmatrix} = \begin{bmatrix} sL_{md} \\ \bar{\omega}_g L_{md} \end{bmatrix} \begin{bmatrix} \Delta i_f \end{bmatrix} + \begin{bmatrix} -sL_{md} & \bar{\omega}_g L_{mq} \\ \bar{\omega}_g L_{md} & -sL_{mq} \end{bmatrix} \begin{bmatrix} \Delta i_d \\ \Delta i_q \end{bmatrix} \quad (84)$$

$$\begin{bmatrix} R_f + sL_{md} \end{bmatrix} \begin{bmatrix} \Delta e_d \\ \Delta e_q \end{bmatrix} = \begin{bmatrix} sL_{md} \\ \bar{\omega}_g L_{md} \end{bmatrix} \begin{bmatrix} \Delta e_f \end{bmatrix} + \begin{bmatrix} -sL_{md} R_f & s\bar{\omega}_g L_{md} L_{mq} + \bar{\omega}_g L_{mq} R_f \\ -\bar{\omega}_g L_{md} R_f & -s^2 L_{md} L_{mq} - sL_{mq} R_f \end{bmatrix} \begin{bmatrix} \Delta i_d \\ \Delta i_q \end{bmatrix} \quad (85)$$

$$\begin{bmatrix} s^2 L_{md} L_L + s(L_{md} R_f + L_{md} R_L + L_L R_f) + R_f R_L \\ s \bar{\omega}_g L_{md} L_L + \bar{\omega}_g R_f (L_{md} + L_L) \\ -s \bar{\omega}_g L_{md} (L_{mq} + L_L) - \bar{\omega}_g R_f (L_{mq} + L_L) \\ s^2 L_{md} (L_{mq} + L_L) + s(L_{md} R_L + L_L R_f + L_{mq} R_f) + R_f R_L \end{bmatrix} \begin{bmatrix} \Delta i_d \\ \Delta i_q \end{bmatrix} = \begin{bmatrix} sL_{md} \\ \bar{\omega}_g L_{md} \end{bmatrix} \begin{bmatrix} \Delta e_f \end{bmatrix} \quad (86)$$

i.e.

$$\begin{bmatrix} A \end{bmatrix} \begin{bmatrix} \Delta i_d \\ \Delta i_f \end{bmatrix} = \begin{bmatrix} sL_{md} \\ \bar{\omega}_g L_{md} \end{bmatrix} \begin{bmatrix} \Delta e_f \end{bmatrix} \quad (87)$$

$$\therefore \begin{bmatrix} \Delta i_d \\ \Delta i_f \end{bmatrix} = \begin{bmatrix} A \end{bmatrix}^{-1} \begin{bmatrix} sL_{md} \\ \bar{\omega}_g L_{md} \end{bmatrix} \begin{bmatrix} \Delta e_f \end{bmatrix}$$

$$= \begin{bmatrix} \frac{K_1 (s^3 + c_{11}s^2 + b_{11}s + a_{11})}{s^4 + d_p s^3 + c_p s^2 + b_p s + a_p} \\ \frac{K_2 (s^2 + b_{22}s + a_{22})}{s^4 + d_p s^3 + c_p s^2 + b_p s + a_p} \end{bmatrix} \begin{bmatrix} \Delta e_f \end{bmatrix}$$

$$= \begin{bmatrix} G_1(s) \\ G_2(s) \end{bmatrix} \begin{bmatrix} \Delta e_f \end{bmatrix} \quad (88)$$

$$K_1 = \frac{1}{L_L} \quad (89a)$$

$$K_2 = \frac{\bar{\omega}_g (L_{m_f} + Z L_L)}{L_L (L_{m_f} + L_L)} \quad (89b)$$

$$a_p = \frac{R_f^2 R_L^2}{L_{md}^2 L_L (L_{m_f} + L_L)} + \frac{R_f^2 \bar{\omega}_g^2 (L_{md} + L_L)}{L_{md}^2 L_L} \quad (89c)$$

$$b_p = \frac{R_f R_L [2L_{md} R_L + 2L_L R_f + L_{mg} R_f + L_{md} R_f]}{L_{md}^2 L_L (L_{mg} + L_L)} + \frac{\bar{\omega}_g^2 R_f (L_{md} + 2L_L)}{L_{md} L_L} \quad (89d)$$

$$c_p = \frac{R_f R_L}{L_{md} L_L} + \frac{R_f R_L}{L_{md} (L_{mg} + L_L)} + \bar{\omega}_g^2 + \frac{(L_{md} R_f + L_{md} R_L + L_L R_f)(L_{md} R_L + L_L R_f + L_{mg} R_f)}{L_{md}^2 L_L (L_{mg} + L_L)} \quad (89e)$$

$$d_p = \frac{L_{md} R_f + L_{md} R_L + L_L R_f}{L_{md} L_L} + \frac{L_{md} R_L + L_L R_f + L_{mg} R_f}{L_{md} (L_{mg} + L_L)} \quad (89f)$$

$$a_{11} = \frac{\bar{\omega}_g^2 R_f (L_{md} + L_L)}{L_{md} (L_{mg} + L_L)} \quad (89g)$$

$$b_{11} = \frac{R_f R_L}{L_{md} (L_{mg} + L_L)} - \frac{\bar{\omega}_g^2 L_L}{L_{mg} + L_L} \quad (89h)$$

$$C_{11} = \frac{R_L}{L_{mq} + L_L} + \frac{R_f}{L_{md}} \quad (89i)$$

$$a_{22} = \frac{R_f R_L}{L_{md} (L_{mq} + 2L_L)} \quad (89j)$$

$$b_{22} = \frac{R_f + R_L}{L_{mq} + 2L_L} + \frac{R_f}{L_{md}} \quad (89k)$$

Generally,  $\bar{\omega}_g L_{md}, \bar{\omega}_g L_{mq} \gg \bar{\omega}_g L_L, R_f, R_L$   
AND  $R_f, R_L \gg L_{md}, L_{mq}, L_L$

The coefficients can be approximated.

$$K_1 = \frac{1}{L_L} \quad (90a)$$

$$K_2 = \frac{\bar{\omega}_g}{L_L} \quad (90b)$$

$$a_p = \frac{R_f^2}{L_{md} L_L} \left( \frac{R_L^2}{L_{md} L_{mq}} + \bar{\omega}_g^2 \right) \quad (90c)$$

$$b_p = \frac{R_f}{L_L} \left[ \frac{R_L (2 L_{md} R_L + L_{mq} R_f + L_{md} R_f)}{L_{md}^2 L_{mq}} + \bar{\omega}_g^2 \right] \quad (90d)$$

$$c_p = \frac{R_f R_L}{L_{md} L_L} + \frac{(R_L + R_f)(L_{md} R_L + L_{mq} R_f)}{L_{md} L_{mq} L_L} + \bar{\omega}_g^2 \quad (90e)$$

$$d_p = \frac{R_f + R_L}{L_L} \quad (90f)$$

$$a_{11} = \frac{\bar{\omega}_g^2 R_f}{L_{mq}} \quad (90g)$$

$$b_{11} = \frac{1}{L_{mq}} \left( \frac{R_f R_L}{L_{md}} - \bar{\omega}_g^2 L_L \right) \quad (90h)$$

$$c_{11} = \frac{R_L}{L_{mq}} + \frac{R_f}{L_{md}} \quad (90i)$$

$$a_{22} = \frac{R_f R_L}{L_{md} L_{mq}} \quad (90j)$$

$$b_{22} = \frac{R_f R_L}{L_{mq}} + \frac{R_f}{L_{md}} \quad (90k)$$

Thus, solve for  $\Delta e_d$ ,  $\Delta e_q$ .

$$\begin{aligned}
 \begin{bmatrix} \Delta e_d \\ \Delta e_q \end{bmatrix} &= \begin{bmatrix} R_L + sL_L & -\bar{\omega}_g L_L \\ \bar{\omega}_g L_L & R_L + sL_L \end{bmatrix} \begin{bmatrix} \Delta i_d \\ \Delta i_q \end{bmatrix} \\
 &= \begin{bmatrix} (R_L + sL_L)G_1(s) - \bar{\omega}_g L_L G_2(s) \\ \bar{\omega}_g L_L G_1(s) + (R_L + sL_L)G_2(s) \end{bmatrix} \begin{bmatrix} \Delta e_f \end{bmatrix} \\
 &= \begin{bmatrix} \frac{K_3(s^4 + d_{33}s^3 + c_{33}s^2 + b_{33}s + a_{33})}{s^4 + dps^3 + cps^2 + bps + ap} \\ \frac{K_4(s^3 + c_{44}s^2 + b_{44}s + a_{44})}{s^4 + dps^3 + cps^2 + bps + ap} \end{bmatrix} \begin{bmatrix} \Delta e_f \end{bmatrix} \\
 &= \begin{bmatrix} G_3(s) \\ G_4(s) \end{bmatrix} \begin{bmatrix} \Delta e_f \end{bmatrix} \tag{91}
 \end{aligned}$$

$$K_3 = 1$$

(92a)

$$a_{33} = \frac{R_L}{L_L} a_{11} - \bar{\omega}_g^2 a_{22} \quad (92b)$$

$$b_{33} = a_{11} + \frac{R_L}{L_L} b_{11} - \bar{\omega}_g^2 b_{22} \quad (92c)$$

$$c_{33} = \frac{R_L}{L_L} c_{11} + b_{11} - \bar{\omega}_g^2 \quad (92d)$$

$$d_{33} = \frac{R_L}{L_L} + c_{11} \quad (92e)$$

$$K_4 = 2 \bar{\omega}_g \quad (92f)$$

$$a_{44} = \frac{1}{2} \left( a_{11} + \frac{R_L}{L_L} a_{22} \right) \quad (92g)$$

$$b_{44} = \frac{1}{2} \left( b_{11} + \frac{R_L}{L_L} b_{22} + a_{22} \right) \quad (92h)$$

$$c_{44} = \frac{1}{2} \left( c_{11} + b_{22} + \frac{R_L}{L_L} \right) \quad (92i)$$




Fig. 22

$G_1(s)$ ,  $G_2(s)$ ,  $G_3(s)$  and  $G_4(s)$  are linear filters. They can be implemented on an analog computer. The coefficient of the filters can be tabulated by digital computer so that a new set of values can readily be obtained when the machine and/or load parameters are changed while this implies to change of potentiometer settings of the analog computer. However, this section will emphasize on theoretical analysis of the equivalent filters. Different kinds of stability analysis methods are used to interpret the relative stability, transient and other concerns. Numerical examples are given along with the discussion. Digital computer is used for the computations.

- (ii) First, the characteristics of the transfer functions of the models  $G_1(s)$ ,  $G_2(s)$ ,  $G_3(s)$  and  $G_4(s)$  are investigated. The denominator is a fourth order polynomial with all the coefficients positive. There will be four poles. Their locations depend on the generator and load parameters and the generator frequency which has been assumed constant. For the system to be stable, all these poles of the closed



loop system must lie on the left half of the complex plane so as to ensure convergence. The closed loop system is assumed to be: (with constant speed drive)




Fig. 23  
Closed-Loop System

Thus, the synchronous generator and the load can be considered as an open-loop plant.

A synchronous generator used as a sample throughout the following discussion is rated at 120 volt/111 amp line to neutral with a power factor of 0.75.

$$\bar{\omega}_g = 2500 \text{ radians/second}$$

$$L_{md} = 0.068 \text{ henries}$$

$$L_{mq} = 0.044 \text{ henries}$$

$$R_f = 1.0 \text{ ohms}$$

$$R_L = 0.8 \text{ ohms}$$

$$L_L = 0.0003 \text{ henries}$$

From the previous argument and derivation

$$\begin{aligned}
 G_3(s) &= \frac{E_d(s)}{E_f(s)} \\
 &= \frac{s^4 + 2.73 \times 10^3 s^3 - 6.2 \times 10^6 s^2 - 6 \times 10^8 s - 3.84 \times 10^{11}}{s^4 + 6 \times 10^3 s^3 + 6.5 \times 10^6 s^2 + 1.37 \times 10^{10} s + 3.08 \times 10^{11}}
 \end{aligned} \tag{93a}$$

$$\begin{aligned}
 G_4(s) &= \frac{E_g(s)}{E_f(s)} \\
 &= \frac{5 \times 10^3 (s^3 + 1.4 \times 10^3 s^2 - 1.97 \times 10^4 s - 7.07 \times 10^7)}{s^4 + 6 \times 10^3 s^3 + 6.5 \times 10^6 s^2 + 1.37 \times 10^{10} s + 3.08 \times 10^{11}}
 \end{aligned} \tag{93b}$$

The steady state gains are -

$$\lim_{s \rightarrow 0} |G_3(s)| = 1.25$$

$$\lim_{s \rightarrow 0} |G_4(s)| = 1.15$$

Factorize  $G_3(s)$  and  $G_4(s)$

$$G_3(s) = \frac{5 \times 10^3 (s - 215)(s + 238)(s + 1377)}{(s + 23)(s + 5300)(s + 360 \pm j 1560)}$$

$$G_4(s) = \frac{(s-1570)(s+4300)(s+57 \pm j 235)}{(s+23)(s+5300)(s+360 \pm j 1560)}$$

The denominator determines the locations of the open-loop poles while the numerator determines the open-loop zeros. The poles are the starting points of the root locus which terminate at the corresponding zeros as the gain approaches to infinity. Observe both  $G_3(s)$  and  $G_4(s)$  have the same denominator and the poles are all in the left half plane, therefore, the open loop plant is a stable one. Only  $G_4(s)$  is plotted on the complex plane.

S-plane

$$G_4(s) = \frac{(s+57 \pm j 235)(s-1570)(s+4300)}{(s+23)(s+5300)(s+360 \pm j 1560)}$$




Fig. 24 Root locus of  $G_4(s)$

$G_3(s)$  and  $G_4(s)$  have poles located at  $-23$ ,  $-5300$ , and  $-360$ . The latter is taken from the real part of the pair of complex root. The correspondent time constants are

$$T_1 = \frac{1}{23} = 0.0435 \text{ sec.} \quad (96a)$$

$$T_2 = \frac{1}{360} = 0.00277 \text{ sec.} \quad (96b)$$

$$T_3 = \frac{1}{5300} = 0.000189 \text{ sec.} \quad (96c)$$

The last two are comparatively insignificant. Thus, for a rough estimate, the synchronous generator with excitation voltage  $e_f$  as the only feed forward control effort, can be approximated as a first order system with a time constant of  $T_1$ . Generally,  $T_2$  can be included as subtransient time while  $T_1$  as transient time constant. From eqs. (94a) and (94b), steady state gain of terminal voltage  $e_t$  over excitation voltage  $e_f$  can be derived.

$$\begin{aligned} \lim_{s \rightarrow 0} \frac{E_t(s)}{E_f(s)} &= \lim_{s \rightarrow 0} \left\{ [G_3(s)]^2 + [G_4(s)]^2 \right\}^{\frac{1}{2}} \\ &= (1.25^2 + 1.15^2)^{\frac{1}{2}} \\ &= 1.7 \end{aligned} \quad (97)$$

Therefore, the approximated linear transfer function of  $e_t/e_f$  can be written as:

$$\begin{aligned} \frac{E_t(s)}{E_f(s)} &= \frac{Kt}{(1+T_1s)(1+T_2s)} \\ &= \frac{1.7}{(1+0.0435s)(1+0.00277s)} \end{aligned} \quad (98)$$

(iii) Frequency domain plot:

To plot  $G_3(s)$  and  $G_4(s)$  in the frequency domain, let

$$s = j\omega$$

$$D(s) = s^4 + d_p s^3 + c_p s^2 + b_p s + a_p \quad (99a)$$

$$\begin{aligned} D(j\omega) &= (a_p - c_p \omega^2 + \omega^4) + j\omega(b_p - d_p \omega^2) \\ &= |D(j\omega)| \angle \theta_D \end{aligned} \quad (99b)$$

where

$$|D(j\omega)| = \left[ (a_p - c_p \omega^2 + \omega^4)^2 + \omega^2 (b_p - d_p \omega^2)^2 \right]^{\frac{1}{2}} \quad (99c)$$

$$\theta_D = \tan^{-1} \left[ \frac{\omega(b_p - d_p \omega^2)}{a_p - c_p \omega^2 + \omega^4} \right] \quad (99d)$$

Similarly:

$$N_3(s) = K_3(s^4 + d_{33}s^3 + c_3 s^2 + b_{33}s + a_{33}) \quad (100a)$$

$$N_3(j\omega) = |N_3(j\omega)| \angle \theta_3 \quad (100b)$$

where

$$|N_3(j\omega)| = K_3 \left[ (a_{33} - c_{33} \omega^2 + \omega^4)^2 + \omega^2 (b_{33} - d_{33} \omega^2)^2 \right]^{\frac{1}{2}} \quad (100c)$$

$$\theta_3 = \tan^{-1} \left[ \frac{\omega(b_{33} - d_{33} \omega^2)}{a_{33} - c_{33} \omega^2 + \omega^4} \right] \quad (100d)$$

$$N_4(s) = K_4 (s^3 + c_{44}s^2 + b_{44}s + a_{44}) \quad (101a)$$

$$N_4(j\omega) = |N_4(j\omega)| \angle \theta_4 \quad (101b)$$

where

$$|N_4(j\omega)| = \left[ K_4 (a_{44} - c_{44}\omega^2)^2 + \omega^2 (b_{44} - \omega^2)^2 \right]^{\frac{1}{2}} \quad (101c)$$

$$\theta_4 = \tan^{-1} \left[ \frac{\omega (b_{44} - \omega^2)}{a_{44} - c_{44}\omega^2} \right] \quad (101d)$$




Fig. 25

Use the same data for the synchronous generator and impose the same assumptions as in the previous example. Plot the transfer functions with respect to frequency in Fig. IV. Consider  $G_3(s)$ , the zero cross-over of the amplitude curve corresponds to a phase lag of  $35^\circ$ . That is a phase margin of  $145^\circ$ .  $G_3(s)$  is far from unstable. One must know that not all the poles and zeros are in the left half of the complex plane. The non-minimum phase characteristics prevent the direct approximation of the phase angle derived from the asymptotic plot of the amplitude curve.




FIG. V



(iv) Transfer function derivation from laboratory data:

Conversely, if a transient response curve is in hand, a transfer function can be derived from asymptotic plot in a frequency domain curve. The break-away points of two asymptotes with 20 db/decade decay difference determines the time constants. The order of the transfer function depends on the need of accuracy in describing the characteristics. It must be noted that a time domain plot which is the usual case of laboratory data, should be transformed into frequency domain plot before applying the approximation technique. The abscissa should be the ratio of output versus input in decibel while the ordinate, frequency in radians per second. Suppose an actual curve is plotted in Fig. D. Three asymptotic lines are approximated. The zero db/decade line is at 4.6 db which determines the gain of the transfer function while the two break-away points at




FIG IV FREQUENCY PLOT OF  $G_3(s)$  AND  $G_4(s)$

$$\omega_1 = 23 \text{ rad/sec. AND } \omega_2 = 360 \text{ rad/sec}$$

The transfer function becomes -

$$\begin{aligned} G(s) &= \frac{K}{(1 + T_1 s)(1 + T_2 s)} \\ &= \frac{\frac{1}{20} \text{ antilog}_{10} (4.6)}{(1 + \frac{1}{23} s)(1 + \frac{1}{360} s)} \\ &= \frac{1.7}{(1 + 0.0435s)(1 + 0.00277s)} \end{aligned} \quad (98a)$$

(v) Two manipulated variables:

If both  $\Delta \omega$  and  $\Delta e_f$  are considered simultaneously,

$$\begin{bmatrix} \Delta i_d \\ \Delta i_f \end{bmatrix} = \begin{bmatrix} G_1(s) \\ G_2(s) \end{bmatrix} \begin{bmatrix} \Delta e_f \end{bmatrix} + \begin{bmatrix} A \end{bmatrix}^{-1} \begin{bmatrix} R_f \bar{i}_f (L_{mf} + L_L) + s L_{md} \bar{i}_f (L_{mf} + L_L) \\ R_f \{ L_{md} \bar{i}_f - \bar{i}_d (L_{md} + L_L) \} + s L_{md} \{ L_{md} \bar{i}_f - \bar{i}_d (L_{md} + L_L) \} \end{bmatrix} \begin{bmatrix} \Delta \omega \end{bmatrix}$$

$$= \begin{bmatrix} G_1(s) \\ G_2(s) \end{bmatrix} [\Delta e_f] + \begin{bmatrix} G_5(s) \\ G_6(s) \end{bmatrix} [\Delta \omega] \quad (102)$$

where

$$G_5(s) = \frac{s^3 d_5 + s^2 c_5 + s b_5 + a_5}{s^4 e_p + s^3 d_p + s^2 c_p + s b_p + a_p} \quad (102a)$$

$$G_6(s) = \frac{s^3 d_6 + s^2 c_6 + s b_6 + a_6}{s^4 e_p + s^3 d_p + s^2 c_p + s b_p + a_p} \quad (102b)$$

$$\begin{bmatrix} \Delta e_d \\ \Delta e_f \end{bmatrix} = \begin{bmatrix} G_3(s) \\ G_4(s) \end{bmatrix} [\Delta e_f] + \begin{bmatrix} G_7(s) \\ G_8(s) \end{bmatrix} [\Delta \omega] \quad (103)$$

where

$$G_7(s) = \frac{s^4 e_7 + s^3 d_7 + s^2 c_7 + s b_7 + a_7}{s^4 e_p + s^3 d_p + s^2 c_p + s b_p + a_p} \quad (103a)$$

$$G_8(s) = \frac{s^4 e_8 + s^3 d_8 + s^2 c_8 + s b_8 + a_8}{s^4 e_p + s^3 d_p + s^2 c_p + s b_p + a_p} \quad (103b)$$

Again, approximate the coefficients by assuming

$$L_{mq}, L_{md} \gg L_L$$

$$d_5 = L_{md}^2 L_{mq}^2 \bar{i}_q \quad (104a)$$

$$c_5 = \left[ L_{md} (L_{md} R_L + 2 L_{mq} R_f) \bar{i}_q + \bar{\omega}_g L_L L_{md}^2 (\bar{i}_f - \bar{i}_d) \right] \quad (104b)$$

$$b_5 = R_f \left[ L_{mq} (2 L_{md} R_L + L_{mq} R_f) \bar{i}_q + \bar{\omega}_g L_{md}^3 (\bar{i}_f - \bar{i}_d) \right] \quad (104c)$$

$$a_5 = R_f^2 \left[ R_L L_{mq} \bar{i}_q + \bar{\omega}_g L_{md}^2 (\bar{i}_f - \bar{i}_d) \right] \quad (104d)$$

$$d_6 = L_L L_{md}^2 (\bar{i}_f - \bar{i}_d) \quad (104e)$$

$$c_6 = L_{md}^3 (\bar{i}_f - \bar{i}_d) (R_L + R_f) - \bar{\omega}_g L_{md}^2 L_{mq} \bar{i}_q \quad (104f)$$

$$b_6 = R_f L_{md} \left[ L_{md} (2 R_L + R_f) (\bar{i}_f - \bar{i}_d) - 2 \bar{\omega}_g L_{mq} \bar{i}_q \right] \quad (104g)$$

$$a_6 = R_f^2 \left[ R_L L_{md} (\bar{i}_f - \bar{i}_d) - \bar{\omega}_g L_{mq}^2 \bar{i}_q \right] \quad (104h)$$

$$e_7 = L_L (d_5 - e_p \bar{i}_q) \quad (104i)$$

$$d_7 = R_L d_5 + L_L (c_5 - \bar{w}_g d_b - d_p \bar{i}_q) \quad (104j')$$

$$c_7 = R_L c_5 + L_L (b_5 - \bar{w}_g c_b - c_p \bar{i}_q) \quad (104k)$$

$$b_7 = R_L b_5 + L_L (a_5 - \bar{w}_g b_b - b_p \bar{i}_q) \quad (104l)$$

$$a_7 = R_L a_5 - L_L (\bar{w}_g a_b + a_p \bar{i}_q) \quad (104m)$$

$$e_8 = L_L (d_b + e_p \bar{i}_d) \quad (104n)$$

$$d_8 = R_L d_b + L_L (c_b + \bar{w}_g d_5 + d_p \bar{i}_d) \quad (104o)$$

$$c_8 = R_L c_b + L_L (b_b + \bar{w}_g c_5 + c_p \bar{i}_d) \quad (104p)$$

$$b_8 = R_L b_b + L_L (a_b + \bar{w}_g b_5 + a_p \bar{i}_d) \quad (104q)$$

$$a_8 = R_L a_b + L_L (\bar{w}_g a_5 + a_p \bar{i}_d) \quad (104r)$$

$$e_p = L_{md}^2 L_{mq} L_L \quad (104s)$$

$$d_p = L_{md} \left[ L_{md} L_{mq} (R_f + R_L) + L_L (L_{md} R_L + L_{mq} R_f) \right] \quad (104t)$$

$$c_p = L_{md} \left[ L_{mq} (R_f R_L + \bar{w}_g^2 L_{md} L_L) + (R_f + R_L) (L_{md} R_L + L_{mq} R_f) \right] \quad (104u)$$

$$b_p = R_f \left[ R_L (2 L_{md} R_L + R_f L_{md} + L_{mf} R_f) + \bar{\omega}_f^2 L_{md}^2 L_{mf} \right] \quad (104v)$$

$$a_p = R_f^2 (R_L^2 + \bar{\omega}_f^2 L_{md} L_{mf}) \quad (104w)$$

The increments of the variables have to be small for the formulation to be valid. The result is an interacting system.





Fig. 26 Linearization of two control variables

(vi) Closed loop control:



$G_s(s)$  = transfer function of synchronous generator

$G_c(s)$  = controller

$H(s)$  = measuring elements

$T(s)$  = closed-loop transfer function

where

$$T(s) = \frac{G_c(s) G_s(s)}{1 + H(s) G_c(s) G_s(s)}$$

Assume:

$$G_s(s) = \frac{s^4 + 2.73 \times 10^3 s^3 - 6.2 \times 10^6 s^2 - 6 \times 10^8 s - 3.84 \times 10^{10}}{s^4 + 6 \times 10^3 s^3 + 6.5 \times 10^6 s^2 + 1.37 \times 10^{10} s + 3.08 \times 10^{10}}$$

$$H(s) = 1.0$$

$$G_c(s) = K$$



It is desired to find the maximum permissible gain  $K$  for a stable operation. Hurwitz criterion states that a characteristic equation

$$a_n s^n + a_{n-1} s^{n-1} + \dots + a_2 s^2 + a_1 s + a_0 = 0$$

All the determinants

$a_1$	$a_0$	$0$	$0 \dots$
$a_3$	$a_2$	$a_1$	$0 \dots$
$a_5$	$a_4$	$a_3$	$a_2 \dots$
$a_7$	$a_6$	$\dots$	$\dots$

must be positive for a stable system. The characteristic equation of  $T(s)$  is

$$1 + H(s) G_C(s) G_S(s) = 0$$

i.e.,

$$(1+K)s^4 + (6-2.73K)10^7 s^3 + (6.5-6.2K)10^6 s^2 + (138-6K)10^8 s + (3.08-3.84K)10^8 = 0$$

Set the determinants equal to zero for critical condition.

$$(138-6K)10^8 = 0$$

$$K_1 = 23$$

$$\begin{vmatrix} (138-6K)10^8 & (3.08-3.84K)10'' \\ (6-2.73K)10^3 & (6.5-6.2K)10^4 \end{vmatrix} = 0$$

i.e.,  $K^2 - 32.6K + 33.3 = 0$

$$K = 31.6 \text{ or } 1.05$$

Since both values are valid, it is desirable to choose  $K_2 = 31.6$

$$\begin{vmatrix} (1.38-6K)10^8 & (3.08-3.84K)10'' & 0 \\ (6-2.73K)10^3 & (6.5-6.2K)10^6 & (1.38-6K)10^8 \\ 0 & 1+K & (6-2.73K)10^3 \end{vmatrix}$$

i.e.,

$$K^3 - 38.6K^2 + 135.5K - 48.6 = 0$$

$$K = 34.76, 3.38 \text{ or } 48.6$$

It is desirable to have  $K_3 = 34.76$

To compare with the  $K_3$  obtained from the three determinants, in order to satisfy the criterion, the smallest value should be chosen. That is  $K = K_1 = 23$ .

(vii) Sensitivity:

Since any component of the same kind may not be identical due to various reasons, it is beneficial to learn the variation of total performance with respect to the deviation of characteristics of a certain component. It can be the parameters of the plant, the gain of the amplifier or others. For instance, one would like to know the effect of  $K$  on  $T(s)$  in the last example. Define sensitivity as

$$\begin{aligned}
 S_K^T &= \frac{d(\ln T)}{d(\ln K)} \\
 &= \frac{d[\ln(KG_s)]}{d(\ln K)} \\
 &= \frac{1}{1 + KG_s}
 \end{aligned}$$

The smaller the value of  $S_K^T$ , the less effect of variation of  $K$  on  $T(s)$ . However, in this example, the sensitivity is almost linearly related to  $K$  because  $KG_s \gg 1$ .

(viii) Degrees of Freedom:


By investigating the closed-loop transfer function

$$T(s) = \frac{G_c(s) G_s(s)}{1 + H(s) G_c(s) G_s(s)}$$

assuming the plant  $G_s(s)$  is fixed, one can adjust the controller  $G_c(s)$  or feedback element  $H(s)$  respectively to obtain a desired  $T(s)$ . Thus, there is only one degree of freedom. If  $G_c(s)$  and  $H(s)$  are adjusted simultaneously, there will be two degrees of freedom. The latter is more flexible and many a time the implementation is much easier to be realized.

(ix) Model Approach:

Another method to enforce a specified transient response of a synchronous generator is by introducing a model which describes the specification precisely. The block diagram will be as follows:



$$\frac{O}{I} = \frac{G_s (1 + G_c G_m)}{1 + G_c G_s H}$$

Let  $H \cong 1$  and make

$$|G_c| \gg 1$$


$$\frac{O}{I} = G_m$$

where

$O(s)$  = output

$I(s)$  = input

$G_m(s)$  = transfer function of model




THREE PHASE  
Y-CONNECTED  
UNBALANCED LOADS


TWO AXIS COMPONENTS TO  
THREE PHASE COMPONENTS  
CONVERTER

DAMPER BAR (QUAD. AXIS)

MECHANICAL-ELECTRICAL  
CONVERSION

SYNCHRONOUS GENERATOR  
DYNAMIC SIMULATION  
(UNBALANCED LOAD)





# ANALOG COMPUTER SIMULATION OF SYNCHRONOUS GENERATOR WITH UNBALANCED LOAD

